



Entergy Operations, Inc.  
River Bend Station  
5485 U.S. Highway 61  
P. O. Box 220  
St. Francisville, LA 70775  
Tel 225 336 6225  
Fax 225 635 5068

**Rick J. King**  
Director  
Nuclear Safety Assurance

February 1, 2000

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

Subject: River Bend Station - Unit 1  
Docket No. 50-458  
License No. NPF-47  
Licensee Event Report 50-458/99-001-01

File Nos. G9.5, G9.25.1.3

RBG-45240  
RBF1-00-0007

Ladies and Gentlemen:

In accordance with 10CFR 50.73(a)(2)(i)(B), enclosed is the subject amended Licensee Event Report. This LER is being amended to revise a commitment made in the corrective action section of the original submittal. The following corrective action has been removed from the LER:

"A document will be created that identifies where to obtain alternate indications when the at-the-controls area installed recorder/indicator is unavailable."

This is the only change to the LER. Other commitments made in the original submittal and the main body of text of the LER remain unchanged. There are no new commitments made in this submittal.

IE22

Licensee Event Report 50-458/99-001-01  
February 1, 2000  
RBG-45240  
RBF1-00-0007  
Page 2 of 3

Reason for Change:

This corrective action is not directly related to the root cause of the condition. The action was an enhancement intended to provide the operator with alternative indicators to be used if the primary indicator for a surveillance is not available. This type of information is available for use during normal and emergency conditions in existing plant documents. However, designation of alternate indicators for use during surveillance activities would require extensive resources that are not justified based on the infrequent need or use for this purpose. Based on this, a decision was made to not pursue this action.

Please contact David Lorring at (225) 381-4157 if you have any questions.

Sincerely,



RJK/dlm  
Attachment  
Enclosure

Licensee Event Report 50-458/99-001-01  
February 1, 2000  
RBG-45240  
RBF1-00-0007  
Page 3 of 3

cc: U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 400  
Arlington, TX 76011

NRC Sr. Resident Inspector  
P. O. Box 1050  
St. Francisville, LA 70775

INPO Records Center  
E-Mail

Mr. Jim Calloway  
Public Utility Commission of Texas  
1701 N. Congress Ave.  
Austin, TX 78711-3326

Mr. Prosanta Chowdhury  
Program Manager - Surveillance Division  
Louisiana Department of Environmental Quality  
Office of Radiological Emergency Planning & Response  
P. O. Box 82215  
Baton Rouge, LA 70884-2215

Attachment 1

Commitment Identification Form

Subject: LER 99-001-01, Inadequate Surveillances—Drywell Air Temperature and Suppression Pool Average Water Temperature during a Plant Modification of Control Room Recorders Due to Communication Failures and Inadequate Procedure

RBF1-00-0007

RBG-45240

Date: February 1, 2000

COMMITMENT	ONE-TIME ACTION*	CONTINUING COMPLIANCE*
No New Commitments		

\*Check one only