

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

February 23, 2000

William T. Cottle, President and Chief Executive Officer STP Nuclear Operating Company P.O. Box 289 Wadsworth, Texas 77483

SUBJECT: NRC INSPECTION REPORT NO. 50-498/00-01; 50-499/00-01

We are issuing a corrected cover letter and Attachment page for the subject NRC Inspection Report to clarify the cover letter and to correct an NRC inspection procedure reference. Please replace the originally issued pages in the report with the ones enclosed. We regret any inconvenience this may have caused.

Sincerely,

/RA/

Gail M. Good, Chief Plant Support Branch Division of Reactor Safety

Docket Nos.: 50-498

50-499

License Nos.: NPF-76

NPF-80

Enclosures: As stated

cc:

T. H. Cloninger, Vice President Engineering & Technical Services STP Nuclear Operating Company P.O. Box 289 Wadsworth, Texas 77483 S. M. Head, Supervisor, Licensing Quality & Licensing Department STP Nuclear Operating Company P.O. Box 289 Wadsworth, Texas 77483

A. Ramirez/C. M. Canady City of Austin Electric Utility Department 721 Barton Springs Road Austin, Texas 78704

M. T. Hardt/W. C. Gunst City Public Service Board P.O. Box 1771 San Antonio, Texas 78296

D. G. Tees/R. L. Balcom Houston Lighting & Power Company P.O. Box 1700 Houston, Texas 77251

Jon C. Wood Matthews & Branscomb One Alamo Center 106 S. St. Mary's Street, Suite 700 San Antonio, Texas 78205-3692

A. H. Gutterman, Esq. Morgan, Lewis & Bockius 1800 M. Street, N.W. Washington, D.C. 20036-5869

G. E. Vaughn/C. A. Johnson Central Power & Light Company P.O. Box 289 Mail Code: N5012 Wadsworth, Texas 77483

INPO Records Center 700 Galleria Parkway Atlanta, Georgia 30339-5957

Bureau of Radiation Control State of Texas 1100 West 49th Street Austin, Texas 78756 Jim Calloway
Public Utility Commission
William B. Travis Building
P.O. Box 13326
1701 North Congress Avenue
Austin, Texas 78701-3326

John L. Howard, Director Environmental and Natural Resources Policy Office of the Governor P.O. Box 12428 Austin, Texas 78711-3189

Judge, Matagorda County Matagorda County Courthouse 1700 Seventh Street Bay City, Texas 77414 STP Nuclear Operating Company

E-Mail report to D. Lange (DJL)

E-Mail report to NRR Event Tracking System (IPAS)

E-Mail report to Document Control Desk (DOCDESK)

E-Mail notification of report issuance to the STP SRI and Site Secretary (NFO, LAR).

E-Mail notification of issuance of all documents to Nancy Holbrook (NBH).

bcc to DCD (IE06)

bcc distrib. by RIV: Regional Administrator

DRP Director

DRS Director

Branch Chief (DRP/A) Project Engineer (DRP/A) Branch Chief (DRP/TSS) STP Resident Inspector

RIV File

-4-

RITS Coordinator

R. Bachmann, OGC (MS: 15-B-18)

DOCUMENT NAME: R:_STP\ST2000-01LT-MPS.WPD

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

	·	1.7	
RIV:PSB\SRS	C:DRS\PSB	C:DRP\A	
MShannon:nh	GMGood	JTapia	
02/17/00	02/22/00	02/22/00	



UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

February 14, 2000

William T. Cottle, President and Chief Executive Officer STP Nuclear Operating Company P.O. Box 289 Wadsworth, Texas 77483

SUBJECT: NRC INSPECTION REPORT NO. 50-498/00-01; 50-499/00-01

Dear Mr. Cottle:

This refers to the inspection conducted on January 24-27, 2000, at the South Texas Project Electric Generating Station, Units 1 and 2 facilities. The purpose of the inspection was to review the radioactive effluent waste programs and the release of radioactive materials from the radiological controlled area. The enclosed report presents the results of this inspection.

Overall, the liquid and gaseous radioactive effluent waste programs and the release of radioactive materials from the radiologically controlled area were effectively implemented. However, based on the results of this inspection, the NRC has determined that two Severity Level IV violations of NRC requirements occurred. One of the violations pertained to the radioactive effluent waste programs, the other involved the release of radioactive material from the radiologically controlled area. These violations are being treated as noncited violations (NCVs), consistent with Section VII.B.1.a of the Enforcement Policy. These NCVs are described in the subject inspection report. If you contest the violation or severity level of these NCVs, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington DC 20555-0001, with copies to the Regional Administrator, U.S. Nuclear Regulatory Commission, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, Texas 76011, the Director, Office of Enforcement, United States Nuclear Regulatory Commission, Washington, DC 20555-0001; and the NRC Resident Inspector at the South Texas Project Electric Generating Station, Units 1 and 2 facilities.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure(s), and your response, if requested, will be placed in the NRC Public Document Room (PDR).

ATTACHMENT

SUPPLEMENTAL INFORMATION

PARTIAL LIST OF PERSONS CONTACTED

Licensee

- P. Arrington, Licensing Specialist
- L. Cochrane, Auditor, Quality
- B. Dowly, Manager, Generation Support
- R. Gangluff, Manager, Chemistry
- S. Head, Superintendent, Licensing
- M. McBurnett, Director, Quality and Licensing
- B. Mookhoek, Engineer, Licensing
- K. Reynolds, Effluent Tracking Chemist, Chemistry
- J. Simmons, Acting Manager, Health Physics
- M. Smith, Manager, Plant Support Quality

NRC

N. O'Keefe, Senior Resident Inspector

LIST OF INSPECTION PROCEDURES USED

IP 84750	Radioactive Waste Treatment, and Effluent and Environmental Monitoring
IP 83750	Occupational Radiation Exposure

LIST OF ITEMS OPENED AND CLOSED

Opened and Closed

50-499/0001-01	NCV	Failure to survey and control radioactive material released from the radiologically controlled area

50-498; 499/0001-02 NCV Failure to perform an Offsite Dose Calculation Manual audit