

February 29, 2000

Mr. James Knubel
Chief Nuclear Officer
Power Authority of the State of
New York
123 Main Street
White Plains, NY 10601

SUBJECT: COMPLETION OF LICENSING ACTION FOR GENERIC LETTER 98-04,
"POTENTIAL FOR DEGRADATION OF THE EMERGENCY CORE COOLING
SYSTEM AND THE CONTAINMENT SPRAY SYSTEM AFTER A LOSS-OF-
COOLANT ACCIDENT BECAUSE OF CONSTRUCTION AND PROTECTIVE
COATING DEFICIENCIES AND FOREIGN MATERIAL IN CONTAINMENT" -
INDIAN POINT NUCLEAR GENERATING UNIT NO. 3 (TAC NO. MA4058)

Dear Mr. Knubel:

On July 14, 1998, the U.S. Nuclear Regulatory Commission (NRC) issued Generic Letter (GL) 98-04, "Potential for Degradation of the Emergency Core Cooling System and the Containment Spray System After a Loss-of-Coolant Accident Because of Construction and Protective Coating Deficiencies and Foreign Material in Containment," to all holders of operating licenses or construction permits. The NRC issued GL 98-04 to determine the status of containment coating programs.

In GL 98-04, the NRC staff specifically requested that the licensees provide information outlined below for each of their facilities.

- (1) A summary description of the plant-specific program or programs implemented to ensure that Service Level 1 protective coatings used inside the containment are procured, applied, and maintained in compliance with applicable regulatory requirements and the plant-specific licensing basis for the facility. Include a discussion of how the plant-specific program meets the applicable criteria of 10 CFR Part 50, Appendix B, as well as information regarding any applicable standards, plant-specific procedures or other guidance used for (a) controlling the procurement of coatings and paints used at the facility; (b) the qualification testing of protective coatings; and (c) surface preparation, application, surveillance, and maintenance activities for protective coatings. Maintenance activities refer to rework of degraded coatings, removing degraded coatings to sound coatings, correctly preparing the surfaces, applying new coating, and verifying the quality of coatings.
- (2) Information demonstrating compliance with item (i) or item (ii).
 - (i) For plants with licensing-basis requirements for tracking the amount of unqualified coatings inside the containment and for assessing the impact of potential coating

debris on the operation of safety-related systems, structures, and components (SSCs) during a postulated design basis loss-of-coolant accident, the following information shall be provided to demonstrate compliance:

- (a) The date and findings of the last assessment of coatings and the planned date of the next assessment of coatings.
 - (b) The limit for the amount of unqualified protective coatings allowed in the containment and how this limit is determined. Discuss any conservatism in the method used to determine this limit.
 - (c) If a commercial-grade dedication program is being used at your facility for dedicating commercial-grade coatings for Service Level 1 applications inside the containment, discuss how the program adequately qualifies a coating for Service Level 1. Identify what standards or other guidance are currently being used to dedicate containment coatings at your facility.
- (ii) For plants without the above licensing-basis requirements, information shall be provided to demonstrate compliance with the requirements of 10 CFR 50.46b(5), "Long-term cooling" and the functional capability of the safety-related containment spray system (CSS) as set forth in your licensing basis. If a licensee can demonstrate this compliance without quantifying the amount of unqualified coatings, this is acceptable. The following information shall be provided:

If a commercial-grade dedication program is not being used at your facility for qualifying and dedicating commercial-grade coatings for Service Level 1 applications, provide the regulatory and safety basis for not controlling these coatings in accordance with such a program. Additionally, explain why the facility's licensing basis does not require such a program.

In response to GL 98-04, you provided a letter on November 10, 1998, for Indian Point Unit No. 3. This submittal provided the information requested by GL-98-04. Clarification was provided during a phone call that took place on October 7, 1999. Further clarification was provided in a subsequent teleconference. The staff has reviewed your response and has concluded that all requested information has been provided; therefore, we consider GL 98-04 to be closed for your facility.

J. Knubel

-3-

If you have any questions regarding this matter, please contact me at (301) 415-1494. This completes the staff's action on TAC No. MA4058.

Sincerely,

/RA/

George F. Wunder, Project Manager, Section 1
Project Directorate I
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-286

cc: See next page

If you have any questions regarding this matter, please contact me at (301) 415-1494. This completes the staff's action on TAC No. MA4058.

Sincerely,

/RA/

George F. Wunder, Project Manager, Section 1
Project Directorate I
Division of Licensing Project Management
Office of Nuclear Reactor Regulation

Docket No. 50-286

cc: See next page

DISTRIBUTION:

File Center	PUBLIC	PDI-1 r/f	GWunder	ESullivan
SLittle	OGC	ACRS	MOprendek, RI	
MGamberoni	RPulsifer	CLauron	JDavis	

Document Name: C:\gl-98-04closeout.wpd

OFC	PM/PDI-1	LA/PDI-1	BC/EMCB	(A)SC/PDI-1
NAME	GWunder/vw	SLittle	ESullivan	MGamberoni
DATE	1/11/00	1/11/00	1/27/00	2/23/00
COPY	YES/NO	YES/NO	YES/NO	YES/NO

OFFICIAL RECORD COPY

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. Gerald C. Goldstein
Assistant General Counsel
Power Authority of the State
of New York
1633 Broadway
New York, NY 10019

Mr. Eugene W. Zeltmann, President
and Chief Operating Officer
Power Authority of the State
of New York
30 South Pearl Street
Albany, NY 12207-3425

Mr. Robert J. Barrett
Site Executive Officer
Indian Point 3 Nuclear Power Plant
P.O. Box 215
Buchanan, NY 10511

Ms. Charlene D. Faison
Director Nuclear Licensing
Power Authority of the State
of New York
123 Main Street
White Plains, NY 10601

Mr. F. William Valentino, President
New York State Energy, Research,
and Development Authority
Corporate Plaza West
286 Washington Ave. Extension
Albany, NY 12203-6399

Charles Donaldson, Esquire
Assistant Attorney General
New York Department of Law
120 Broadway
New York, NY 10271

Resident Inspector
Indian Point 3 Nuclear Power Plant
U.S. Nuclear Regulatory Commission
P.O. Box 337
Buchanan, NY 10511

Mr. John McCann
Nuclear Safety and Licensing
Consolidated Edison Company
of New York, Inc.
Broadway and Bleakley Avenues
Buchanan, NY 10511

Mayor, Village of Buchanan
236 Tate Avenue
Buchanan, NY 10511

Mr. Richard L. Patch, Director
Quality Assurance
Power Authority of the State
of New York
123 Main Street
White Plains, NY 10601

Mr. Paul Eddy
New York State Dept. of
Public Service
3 Empire State Plaza, 10th Floor
Albany, NY 12223

Mr. Harry P. Salmon, Jr.
Vice President - Engineering
Power Authority of the State
of New York
123 Main Street
White Plains, NY 10601

Mr. Eric Beckjord
2909 29th St. NW
Washington, DC 20008-3416