

Entergy Operations, Inc. P. O. Box 756
Port Gibson MS 39150

Port Gibson, MS 39150 Tel 601 437 2129

Joseph E. Venable General Manager, Plant Operations Grand Gulf Nuclear Station

March 1, 2000

U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Attention:

Document Control Desk

Subject:

Grand Gulf Nuclear Station

Unit 1

Docket No. 50-416 License No. NPF-29

1999 Annual Operating Report

GNRO-2000/00013

Gentlemen:

Entergy Operations, Inc. is transmitting the Grand Gulf Nuclear Station (GGNS) Unit 1 Annual Operating Report for 1999. This report is in accordance with the reporting program described in Regulatory Guide 1.16, Revision 4, Part C.1.b as modified by the NRC letter to GGNS dated May 25, 1987 (MAEC-87/0131).

Provided as attachments are:

- 1. A narrative summary of operating experience during the year 1999,
- 2. Main Steam Line Safety Relief Valve challenges,
- 3. A tabulated annual report of personnel exposure greater than 100 mrem/yr, and
- 4. A summary of failed fuel indications/inspections.

A001

March 1, 2000 GNRO-2000/00013 Page 2 of 2

If you have any questions, please contact this office.

ol Venable

Yours truly,

JEV/AMT

CC:

attachments:

1. Summary Of Operating Experience - 1999

2. Main Steam Safety Relief Valve Challenges - 1999

3. Man-rem Exposure - 1999

4. Failed Fuel Indications/Inspections - 1999

Ms. J. L. Dixon-Herrity, GGNS Senior Resident (w/a)

Mr. D. E. Levanway (Wise Carter) Mr. L. J. Smith (Wise Carter) (w/a)

Mr. N. S. Reynolds (w/a) Mr. H. L. Thomas (w/o)

Mr. E. W. Merschoff (w/a) Regional Administrator

U.S. Nuclear Regulatory Commission

Region IV

611 Ryan Plaza Drive, Suite 400

Arlington, TX 76011

Mr. S. P. Sekerak, NRR/DLPM/PD IV-I (W/2)

U.S. Nuclear Regulatory Commission One White Flint North, Mail Stop 04-D3

11555 Rockville Pike Rockville, MD 20852-2378

March 1, 2000 GNRO-2000/00013

bcc:

Mr. R. J. King (RB) (w/a)

Mr. S. D. Lin (w/a)

Ms. A. M. Townsend (w/a)
File (LCTS/RPTS) (w/a)
File (Hard Copy) (w/a)
File (Central) (w/a) ()

INPO Records Center (w/a)

700 Galleria Parkway

Atlanta, Georgia 30339-5957

Mr. Marcus Ware (w/a) Manager of Production

South Mississippi Electric Power Association

P. O. Box 15849

Hattiesburg, MS 39401

Mr. Fred Yost (w/a)

Director Research Services

Utility Data Institute

1200 G Street, N.W. Suite 1100

Washington, D.C. 20005

Mr. D. P. Galle 19025 Ruth Drive Mokena, IL 60448

ccmail:

Mr. P. W. Alberstadt (w/a)

Mr. S. J. Bethay (w/o)

Mr. C. A. Bottemiller (w/a)

Mr. R. N. Buckley (w/a)

Mr. S. A. Burris (w/a)

Mr. R. W. Carroll (w/a)

Mr. L. F. Daughtery (w/a)

Mr. G. G. Davie (W3 - LIC) (w/a)

Mr. C. M. Dugger (W3 – VP) (w/a)

Mr. W. A. Eaton (w/a)

Mr. R. K. Edington (RBS – VP) (w/a)

Mr. C. W. Ellsaesser (w/a)

Mr. J. L. Ensley (ESI) (w/a)

Mr. E. C. Ewing (W3 - LIC) (w/a)

Mr. C. W. Lambert (w/a)

Mr. J. R. McGaha (ECH) (w/a)

Mr. T. O. McIntyre (w/a)

Mr. J. C. Roberts (w/a)

Mr. J. L. Robertson (w/a)

Mr. W. M. Shelly (w/a)

Ms. M. T. Soniat (LP) (w/a)

Mr. G. D. Swords (w/a)

Mr. J. D. Vandergrift (ANO – LIC) (w/a)

Mr. R. A. Wilson (w/a)

1999 SUMMARY OF OPERATING EXPERIENCE

The following is a summary of Grand Gulf Nuclear Station (GGNS) Unit 1 operating experience for the 1999 calendar year. During 1999, the reactor was critical for 7,124.2 hours with the generator on line for 6,946.0 hours.

On 1/9/99, reactor power reduced to approximately 65% to perform control rod sequence exchange. Duration time – 0 hours.

On 1/13/99, following discovery of melted epoxy compound (used to encapsulate low-voltage current transformers) on the base of Div I Diesel Generator feeder breaker, it was decided to shut down the plant to inspect and replace other CT's as required. The reactor power was first reduced and then at 0942 hour, the reactor was manually scrammed. Duration time – 401.1 hours.

On 2/21/99, while closely monitoring water leakage from "A" main condenser expansion joint seal water trough into the condenser, the reactor power was quickly reduced and then the reactor manually scrammed @2050 hour upon observation of full opening of the "A" seal water makeup valve and rapid increase in offgas flow. All 3 expansion joints were inspected during shutdown and both "A" and "C" were replaced. Duration time – 171.2 hours.

On 2/21/99, shutdown because of failure of "A" main condenser expansion joint continued until 03/02/99 @ 1341 hour. The "C" expansion joint was found to have air bubbles in the vulcanized rubber joint during inspection. Both "A" and "C" expansion joints were replaced during the outage. Rated core thermal power was restored on 03/05/99. Duration time – 37.7 hours.

On 10/22/99, scheduled power reduction for performing Reactor Feed Pump Turbine "A" over-speed test before refueling. Duration time – 0 hours.

On 10/23/99, reactor shut down for Refueling Outage #10 planned for 40 days. Duration time – 217.0 hours.

On 10/23/99, refueling Outage #10 continued through the month. Duration time – 720.0 hours.

On 10/23/99, planned Refueling Outage #10 continued. Duration time – 24.0 hours.

On 12/02/99, scheduled extension of RFO #10. Duration time – 203.9 hours.

On 12/11/99, power reduced to take generator off grid for repairing HP Turbine 1st-stage pressure sensing line. Duration time – 14.6 hours.

On 12/13/99, turbine tripped at reduced power to repair the pressure sensing line again. Duration time – 19.1 hours.

On 12/30/99, for prudence, reactor power was reduced to approximately 80% for Y2K rollover. Duration time – 0.0 hours.

1999 MAIN STEAM SAFETY RELIEF VALVE CHALLENGES

This section contains a summary of main steam line safety relief valve challenges which occurred during 1999 as reported in the GGNS Monthly Operating Report for that period.

The summaries were originally included in the following monthly reports:

February 1999 Report - GNRO-99/00047 - Dated: July 15, 1999

DOCKET NO.

<u>50-416</u>

DATE

6/08/99

COMPLETED BY C. W. GUNN TELEPHONE

(601) 437-2396

MAIN STEAM SAFETY RELIEF VALVE CHALLENGES

Date of Occurrence:

February 22, 1999

Plant Operating Condition:

Rx Thermal Power

83%

Rx Pressure (psia)

About 600 psia

Rx Mode

1

Rx Power (MWE)

1066

Rx Temperatures

547F

Number of main steam line SRVs:

20

Number of SRVs affected by event:

6

Narrative:

On February 22, 1999, six SRVs were manually opened to control pressure during plant scram with MSIV closed. The following SRVs were opened to evenly heat-up suppression pool:

B21F041K, F051K, F041G, F041E, F041C, F047H

GGNS UNIT 1 ANNUAL REPORT

MAN-REM EXPOSURE-1999

This section contains a tabulation of the number of station, utility and other personnel receiving exposures greater than 100 mrem/year and their associated man-rem exposure according to work and job function. Also included is a tabulation of the number of personnel by exposure range.

Entergy Operations, Inc. Grand Gulf Nuclear Station P.O. Box 756 Port Gibson, MS. 39150 LICENSE: NPF-29

Date: 23-FEB-2000 13:15

Regulatory Guide 1.16 Information End of Year Report 1999

Number of Personnel > 100 mrem Total man-rem * Work and Job Function Station Utility Contractor Station Utility Contractor ROUTINE OPERATIONS AND SURVEILLANCE MAINTENANCE AND CONSTRUCTION 0 0 0 0.293 0.015 0.065 OPERATIONS 40 Ô 0 10.957 0.079 0.930 HEALTH PHYSICS 17 0 14 5.162 SUPERVISORY 0.121 6.780 1 1 n 0.577 0.328 0.366 ENGINEERING 0 0 0 0.686 0.002 0.003 ROUTINE PLANT MAINTENANCE MAINTENANCE AND CONSTRUCTION 83 17 144 21.398 5.105 56.741 **OPERATIONS** 22 3 Ω 5.917 HEALTH PHYSICS 0.556 0.010 14 O 4.536 0.083 SUPERVISORY 1.882 1 0 0 0.994 0.184 ENGINEERING 0.680 2 0 19 1.293 0.009 5.390 INSERVICE INSPECTION MAINTENANCE AND CONSTRUCTION 0 1 20 0.000 0.272 10.869 **OPERATIONS** 0 0 0 0.011 0.002 0.012 HEALTH PHYSICS 0 0 0.117 0.000 0.133 SUPERVISORY 1 3 29 0.322 ENGINEERING 0.450 10.870 1 0 1 0.277 0.000 0.903 SPECIAL PLANT MAINTENANCE MAINTENANCE AND CONSTRUCTION 20 11 27 6.949 2.849 11.811 **OPERATIONS** 0 0 0.110 0.000 HEALTH PHYSICS 0.430 0 0 1 0.427 0.000 SUPERVISORY 0.294 0 0 1 0.012 0.055 ENGINEERING 0.410 0 0 18 0.160 0.062 5.834 WASTE PROCESSING MAINTENANCE AND CONSTRUCTION 0 0 0.555 0.002 **OPERATIONS** 0.187 2 0 2 0.841 0.000 HEALTH PHYSICS 0.536 4 0 0 1.350 0.084 SUPERVISORY 0.111 0 0 0 0.000 ENGINEERING 0.000 0.000 1 0 3 0.132 0.000 1.488 REFUELING MAINTENANCE AND CONSTRUCTION 2 0 37 0.927 0.014 **OPERATIONS** 10.319 3 ٥ 0 0.876 0.000 0.000 HEALTH PHYSICS 5 4 4 1.014 0.750 SUPERVISORY 0.993 2 0 0 0.652 0.391 ENGINEERING 0.007 1 0 0.537 0.151 0.000 Totals MAINTENANCE AND CONSTRUCTION 105 29 228 30.122 8.257 89.992 **OPERATIONS** 67 3 2 18.712 HEALTH PHYSICS 0.637 1.918 40 4 23 12.606 1.038 10.193 SUPERVISORY 5 4 30 2.557 1.408 ENGINEERING 12.333 5 0 41 3.085 0.224 13.618 Grand Totals 222 40 324 67.082 11.564 128.054

^{*} The total radiation exposure of the above personnel constitutes 100% of the site's exposure for the year.

The following is a description of all Special Plant Maintenance activities for 1999 and total dose for each category.

Description	Dose(Rem)
ERs, MCP, and DCP work activities.	3.533
Open/Disassemble/Inspect/Repack/Rework MSIVs. To include all support work.	10.806
Perform Modifications to the Refueling Bridge (CTMT), Auxiliary Platform (CTMT), and the Fuel Handling Bridge. Drills and Emergencies	0.605 0.010
Furmanite Repair of Plant Equipment.	1.869
HFTS Repairs	0.444
Aux. Steam Tunnel G33 Penetration Cooler Mods	0.294
Drywell Cooling Coils Replacement and Vent Mods	1.794
Repair Broken/Damaged Grating, Studs, and Hold-	0.047
Down Plates in the Drywell. B21F010A and B21F032A Valve Work.	0.334
MOV Work and Diagnostic Testing on E12F009.	4.656
Replace RVDT and Calibrate B33F060A/B.	0.233
Replace RTD G33N007 Temperature Element in the	0.054
RWCU Heat Exchanger Room. Open the east side manway of the intermediate Condenser	0.008
for Hotwell pump down. Replace G33C001B Pump Seal.	0.602
Replace G33C001B Pump Seal, Rework valve G36F031A, G36F032A, and G33F003A.	0.854
P45 Sump Work and Calibrations Undervessel.	0.528
Seimens/Power Equipment Maintenance (PEM)	0.225
Turbine Deck and Turbine Bldg. Work. Emergent Work Activities During RF10.	0.154
MOV/AOV Work and Diagnostic Testing in the Drywell	1.528
Fire Watch Rounds Due To Problems With Conduit Fire Seals.	0.825

1999 FAILED FUEL INDICATIONS/INSPECTIONS

Cycle 10 startup and steady-state data indicate there are no fuel failures in the Grand Gulf core.