

---

**TABLE OF CONTENTS**

<u>Section</u>	<u>Title</u>	<u>Page</u>
CHAPTER 17	QUALITY ASSURANCE .....	17-1
17.1	Quality Assurance During the Design and Construction Phases .....	17-1
17.2	Quality Assurance During the Operations Phase .....	17-1
17.3	Quality Assurance During Design, Procurement, Fabrication, Inspection and/or Testing of Nuclear Power Plant Items and Services .....	17-1
17.4	Design Reliability Assurance Program .....	17-2
17.4.1	Introduction .....	17-2
17.4.2	Scope .....	17-2
17.4.3	Design Considerations .....	17-2
17.4.4	Relationship to Other Administrative Programs .....	17-3
17.4.5	The AP600 Design Organization .....	17-3
17.4.6	Objective .....	17-4
17.4.7	D-RAP, Phase 1 .....	17-5
17.4.7.1	SSCs Identification and Prioritization .....	17-5
17.4.7.2	D-RAP, Phase II .....	17-8
17.4.7.3	D-RAP, Phase III .....	17-8
17.4.7.4	D-RAP Implementation .....	17-9
17.4.8	Glossary of Terms .....	17-10
17.5	Combined License Information Items .....	17-10
17.6	References .....	17-11

LIST OF TABLES

<u>Table No.</u>	<u>Title</u>	<u>Page</u>
17-1	Quality Assurance Program Requirements for RTNSS Systems, Structures, and Components . . . . .	17-13
17.4-1	Risk-Significant SSCs Within the Scope of D-RAP (Sheets 1 - 10) . . . . .	17-16
17.4-2	Example of Risk-Significant Ranking of SSCs for the Automatic Depressurization System . . . . .	17-26

**LIST OF FIGURES**

<b><u>Figure No.</u></b>	<b><u>Title</u></b>	<b><u>Page</u></b>
17.4-1	Design Reliability Assurance Program and O-RAP .....	17-27