

Dave Morey
Vice President
Farley Project

Southern Nuclear
Operating Company
P.O. Box 1295
Birmingham, Alabama 35201
Tel 205.992.5131

March 2, 2000

Docket No.: 50-364



Energy to Serve Your World™

NEL-00-0060

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555 - 0001

Joseph M. Farley Nuclear Plant - Unit 2
Interval 2/Period 3/Outage 2
Inservice Inspection Report

Ladies and Gentlemen:

Pursuant to the requirements of 10CFR50.55a(g) and 10CFR50.36, Southern Nuclear Operating Company hereby submits the Joseph M. Farley Nuclear Plant Unit 2 Interval 2/Period 3/Outage 2 Inservice Inspection Report. This report describes and summarizes the inservice inspection activities performed during the Unit 2 thirteenth refueling outage. These activities were completed December 13, 1999.

Included in this report are the results of the steam generator eddy current testing conducted during this outage as required by 10CFR50.55a(g) and Section 4.4.6.5.b of the Farley Nuclear Plant Unit 2 Technical Specifications. Specifically, the results and a summary may be found in Tab B. None of the information in this report is proprietary and may be reproduced as necessary under government regulations associated with public information rights.

Other pertinent report information is available at Farley Nuclear Plant for your review. This information includes as applicable, examination plans and schedules, examination results and reports, examination methods and procedures, evaluation results, and corrective actions and repairs.

If there are any questions, please advise.

Respectfully submitted,

A handwritten signature in cursive script that reads "Or Morey".

Dave Morey

SOM:maf isi_rpt2.doc
Enclosure

A047

Page 2
U. S. Nuclear Regulatory Commission

cc: Southern Nuclear Operating Company
Mr. L. M. Stinson, General Manager

U. S. Nuclear Regulatory Commission, Washington, D. C.
Mr. L. M. Padovan, Licensing Project Manager – Farley – w/o Enclosure

U. S. Nuclear Regulatory Commission, Region II
Mr. L. A. Reyes, Regional Administrator – w/1 Enclosure
Mr. T. P. Johnson, Senior Resident Inspector – Farley – w/o Enclosure