

John Richmond

From: Peter.Tamburro@exeloncorp.com
Sent: Friday, August 29, 2008 11:12 AM
To: John Richmond; Thomas.Roddey@exeloncorp.com
Cc: Charles.Albert@exeloncorp.com; Calvin.Taylor@exeloncorp.com
Subject: Oyster Creek 1R22 Scope
Attachments: 082008 1R22 Work Orders.xls

John

No changes to our draft outage schedule we sent you last week.

Attached is spreadsheet with what we believe is our 1R22 Refueling Outage License Renewal Scope.

Any questions please call (609)-971-4141

Received: from TWMS01.nrc.gov (148.184.200.145) by R1MS01.nrc.gov
(148.184.99.10) with Microsoft SMTP Server (TLS) id 8.0.751.0; Fri, 29 Aug
2008 11:12:43 -0400
Received: from mail2.nrc.gov (148.184.176.43) by TWMS01.nrc.gov
(148.184.200.145) with Microsoft SMTP Server id 8.0.751.0; Fri, 29 Aug 2008
11:12:43 -0400
X-Ironport-ID: mail2
X-SBRS: 6.3
X-MID: 20384001
X-IronPort-Anti-Spam-Filtered: true
X-IronPort-Anti-Spam-Result:
AhEBANyut0if1nwzo2dsb2JhbACBZVYpjj8WgRABAQEBAQEHBQgHEUSfFQmFf219
X-IronPort-AV: E=Sophos;i="4.32,293,1217822400";
d="xls'32?scan'32,208,217,32";a="20384001"
Received: from maileast1.peco.com (HELO exeloncorp.com) ([159.214.124.51]) by
mail2.nrc.gov with ESMTP; 29 Aug 2008 11:12:26 -0400
Received: from ([159.214.172.27]) by mobuniron2.exeloncorp.com with ESMTP id
5502179.109338607; Fri, 29 Aug 2008 11:11:57 -0400
Received: from mobmsxch06.energy.power.corp ([159.214.141.27]) by
MOBMSCON01.energy.power.corp with Microsoft SMTPSVC(6.0.3790.3959); Fri, 29
Aug 2008 11:12:11 -0400
X-MimeOLE: Produced By Microsoft Exchange V6.5
Content-Class: urn:content-classes:message
MIME-Version: 1.0
Subject: Oyster Creek 1R22 Scope
Date: Fri, 29 Aug 2008 11:12:12 -0400
Message-ID:
<D298806D8440D041B2E5D4AD8242F3BF5AA24C@mobmsxch06.energy.power.corp>
In-Reply-To: <2856BC46F6A308418F033D973BB0EE72841CDA633F@R1CLSTR01.nrc.gov>
X-MS-Has-Attach: yes
X-MS-TNEF-Correlator:
Thread-Topic: Confined Space Training Question
thread-index: AckCN4Pok/UreYoRQAIFU/cKq/2DugHsDboA
From: <Peter.Tamburro@exeloncorp.com>
To: <John.Richmond@nrc.gov>,
<Thomas.Roddey@exeloncorp.com>
CC: <Charles.Albert@exeloncorp.com>,
<Calvin.Taylor@exeloncorp.com>
Return-Path: Peter.Tamburro@exeloncorp.com
X-OriginalArrivalTime: 29 Aug 2008 15:12:11.0546 (UTC) FILETIME=[9C8FA7A0:01C909E9]
Content-Type: multipart/mixed;
boundary="----=_NextPart_001_01C909E9.9D0B0C46"

1R22 LRA WOs (101)

Action Request	System	Problem Desc Atn	Work Order	Program Owner	Program Manager
A2163473	241	1R22 REFUEL OUTAGE SCOPE FOR ISI	C2015095	Tamburro/ 4141	Roddey/ 4178
A2163526	215	ONE TIME INSPECTIONS IN THE REACTOR COOLANT SYSTEM	C2017055	Tamburro/ 4141	Roddey/ 4178
A2163526	223	ONE TIME INSPECTIONS IN THE REACTOR COOLANT SYSTEM	C2017057	Tamburro/ 4141	Roddey/ 4178
A2163526	223	ONE TIME INSPECTIONS IN THE REACTOR COOLANT SYSTEM	C2017059	Tamburro/ 4141	Roddey/ 4178
A2163526	211	ONE TIME INSPECTIONS IN THE REACTOR COOLANT SYSTEM	C2017060	Tamburro/ 4141	Roddey/ 4178
A2163527	215	PERFORM NDE INSPECTION - LRA	C2017129	Tamburro/ 4141	Roddey/ 4178
A2185547	531	LICENSE RENEWAL SELECTIVE LEACHING INSPECTIONS	C2017426	Tamburro/ 4141	Frank/ 4114
A2163659	168	PERFORM INSPECTIONS IN THE DISCHARGE TUNNEL	C2017433	Hand/ 4520	Markos/ 4421
A2163660	168	PERFORM INSPECTIONS IN THE INTAKE TUNNEL	C2017434	Hand/ 4520	Markos/ 4421
A2184115	215	LRA SELECTIVE LEACHING ONE TIME INSPECTIONS	C2017682	Williams/ 4927	Frank/ 4114
A2184116	561	LRA SELECTIVE LEACHING ONE TIME INSPECTION CIRC WATER V-3-13	C2017689	Williams/ 4927	Frank/ 4114
A0708184	532	ESW SYSTEM SYSTEM I VIDEO INSPECTION @ THE INTAKE	R0808959	Gayley/ 4406	Roddey/ 4178
A2045296	723	AUXILIARY TRANSFORMER (BANK 4) ELECTRICAL TESTS	R2026131	Pruthi/ 4436	Barnes/ 4719
A2057925	724	START-UP TRANSFORMER 'B' ELECTRICAL TESTS	R2033700	Pruthi/ 4436	Barnes/ 4719
A2091682	731	"DC" HIPOT TEST OF THE FEEDER CABLE TO "A" RECIRC PMP MOTOR	R2054006	Pruthi/ 4436	Barnes/ 4719
A2101442	424	CONTAINMENT ISOLATION VALVE-INSTRUMENT AIR SYSTEM	R2060031	Trettel/ 2264	McMillan/ 4111
A2101443	424	CONTAINMENT ISOLATION VALVE-INSTRUMENT AIR SYSTEM	R2060032	Trettel/ 2264	McMillan/ 4111
A2134909	535	PM TO INSPECT EXPANSION JOINTS IN SUBSET 9 OF A2014243.66	R2081511	Tamburro/ 4141	Roddey/ 4178
A2135142	531	PM TO INSPECT EXPANSION JOINTS IN SUBSET 14 OF A2014243.66	R2081663	Tamburro/ 4141	Roddey/ 4178
A2135149	532	PM TO INSPECT EXPANSION JOINTS IN SUBSET 15 OF A2014243.66	R2081668	Tamburro/ 4141	Roddey/ 4178
A2137811	421	PM TO INSPECT EXPANSION JOINTS IN SUBSET 7 OF A2014243.66	R2083515	Tamburro/ 4141	Roddey/ 4178
A2146960	535	VISUAL INSPECTION OF V-3-31 (1C N. COND OUTLET)	R2089742	Tamburro/ 4141	Roddey/ 4178
A2147323	333	VISUAL INSPECTION OF V-3-793 (S-3-018 DRN)	R2089997	Tamburro/ 4141	Roddey/ 4178

1R22 LRA WOs (101)

Action Request	System	Problem Desc Atn	Work Order	Program Owner	Program Manager
A2147349	333	VISUAL INSPECTION OF V-3-799 (S-3-024 DRN)	R2090021	Tamburro/ 4141	Roddey/ 4178
A2147386	531	VISUAL INSPECTION OF V-3-986 (1-2 TBCCW HX VENT)	R2090043	Tamburro/ 4141	Roddey/ 4178
A2147422	535	VISUAL INSPECTION OF V-3-112 (TBCCW HX VENT DRN HDR)	R2090057	Tamburro/ 4141	Roddey/ 4178
A2147426	535	VISUAL INSPECTION OF V-3-32 (1C S. COND OUTLET)	R2090060	Tamburro/ 4141	Roddey/ 4178
A2149411	212	INTERNAL PIPING INSPECTION UPSTREAM OF V-1-177	R2091382	Tamburro/ 4141	Roddey/ 4178
A2151788	271	SECONDARY CONTAINMENT LEAK RATE	R2092962	Abelev/ 2306	McMillan/ 4111
A2152686	814	1C SWITCHGEAR INSPECTION POINTS	R2093471	Trettel/ 2264	McMillan/ 4111
A2152731	888	TORUS MONORAIL - YEARLY INSPECTION AND	R2093513	Ricketts/ 4818	McMillan/ 4111
A2153338	811	SPRINKLER SYSTEM #2 AND #7 INSPECTION	R2093872	Trettel/ 2264	McMillan/ 4111
A2153659	535	REPLACE E1PANSION JOINT Y-3-23, 1C-S OUTLET BACKWASH	R2094036	Tamburro/ 4141	Roddey/ 4178
A2154251	411	CONTAINMENT ISOLATION VALVE-INSTRUMENT AIR	R2094311	Trettel/ 2264	McMillan/ 4111
A2154252	411	CONTAINMENT ISOLATION VALVE-INSTRUMENT AIR	R2094312	Trettel/ 2264	McMillan/ 4111
A2154259	411	CONTAINMENT ISOLATION VALVE-INSTRUMENT AIR	R2094317	Trettel/ 2264	McMillan/ 4111
A2154260	411	CONTAINMENT ISOLATION VALVE-INSTRUMENT AIR	R2094318	Trettel/ 2264	McMillan/ 4111
A2154389	243	V-26-16; CONTAINMENT ISOLATION VALVE-INSTRUMENT AIR	R2094400	Trettel/ 2264	McMillan/ 4111
A2154439	814	1D SWITCHGEAR INSPECTION POINTS	R2094450	Trettel/ 2264	McMillan/ 4111
A2154545	243	V-26-18; CONTAINMENT ISOLATION VALVE-INSTRUMENT AIR	R2094508	Trettel/ 2264	McMillan/ 4111
A2154565	621	SRM/IRM JUMPERING, AND MEGGER (IR) TESTS	R2094520	Jimenez/ 4833	Skelskey/ 4475
A2154570	621	OBTAIN IV CURVES ON IRM DETECTORS	R2094525	Jimenez/ 4833	Skelskey/ 4475
A2154712	187	VT INSPECTION OF EXTERIOR DW SHELL IN SAND BED REGION 9	R2094623	Tamburro/ Porras	Markos/ Roddey
A2155838	187	VT INSPECTION OF EXTERIOR DW SHELL IN SAND BED REGION 17	R2095467	Tamburro/ Porras	Markos/ Roddey
A2155839	187	VT INSPECTION OF EXTERIOR DW SHELL IN SAND BED REGION 7	R2095468	Tamburro/ Porras	Markos/ Roddey
A2155840	187	VT INSPECTION OF EXTERIOR DW SHELL IN SAND BED REGION 1	R2095469	Tamburro/ Porras	Markos/ Roddey

1R22 LRA WOs (101)

Action Request	System	Problem Desc Atn	Work Order	Program Owner	Program Manager
A2155842	187	VT INSPECTION OF EXTERIOR DW SHELL IN SAND BED REGION 11	R2095471	Tamburro/ Porras	Markos/ Roddey
A2156101	187	TORUS INSPECTION	R2095647	Tamburro/ Porras	Markos/ Roddey
A2156234	262	RECIRC PUMP MONORAIL HOIST - REFUEL OUTAGE	R2095750	Ricketts/ 4818	McMillan/ 4111
A2156377	187	DURING REFUEL OUTAGE CHECK FOR LEAKAGE FROM RX CAVITY	R2095857	Harttraft/ 2287	Roddey/ 4178
A2156501	814	FIRE BARRIER PENETRATION INSP (CONDENSER & HTR BAY ONLY)	R2095973	Trettel/ 2264	McMillan/ 4111
A2156555	888	DW AIRLOCK #1 MONORAIL 10 TON CHAIN HOIST -	R2096023	Ricketts/ 4818	McMillan/ 4111
A2156566	187	UT EXAMINATION OF DRYWELL SHELL IN SANDBED REGION	R2096031	Tamburro/ 4141	Roddey/ 4178
A2156631	187	UT OF UPPER DRYWELL	R2096037	Tamburro/ 4141	Roddey/ 4178
A2157530	151	INSPECTION OF TURBINE-GENERATOR PEDESTAL	R2096676	Hand/ 4520	Markos/ 4421
A2157531	153	INSPECT DRYWELL SHIELD WALLS, SPENT FUEL AND EQUIP POOL WALL	R2096677	Hand/ 4520	Markos/ 4421
A2157532	151	INSPECT STRUCTURES AND COMPONENTS IN TURBINE BLD - HEATERBAY	R2096678	Hand/ 4520	Markos/ 4421
A2157540	187	INSPECT DRYWELL SHELL INNER SURFACE	R2096685	Porras 4247	Markos/ 4421
A2158431	187	INSPECT CONTAINMENT INTERNAL STRUCTURES	R2097321	Hand/ 4520	Markos/ 4421
A2160415	221	PERFORM REACTOR DISASSEMBLY FOR REFUEL	R2098683	Harttraft	Roddey
A2163427	814	TRUNNION ROOM ACCESS DOOR INSPECTION	R2100729	Trettel/ 2264	McMillan/ 4111
A2166367	187	CAMERA INSPECTION OF RX CAVITY DRAIN LINE BEFORE & AFTER OUT	R2102695	Tamburro/ 4141	Roddey/ 4178
A2169855	187	VT INSPECTION OF EXTERIOR DW SHELL IN SAND BED REGION 5	R2105179	Tamburro/ Porras	Markos/ Roddey
A2170313	187	VT INSPECTION OF EXTERIOR DW SHELL IN SAND BED REGION 13	R2105477	Tamburro/ Porras	Markos/ Roddey
A2170315	187	VT INSPECTION OF EXTERIOR DW SHELL IN SAND BED REGION 15	R2105479	Tamburro/ Porras	Markos/ Roddey
A2170354	187	VT INSPECTION OF EXTERIOR DW SHELL IN SAND BED REGION 3	R2105515	Tamburro/ Porras	Markos/ Roddey
A2170355	187	VT INSPECTION OF EXTERIOR DW SHELL IN SAND BED REGION 19	R2105516	Tamburro/ Porras	Markos/ Roddey
A2170439	157	INSPECTION OF TURBINE BLD, COND BAY STRUCTURES AND COMPONENT	R2105563	Hand/ 4520	Markos/ 4421
A2182608	168	INTAKE CANAL UNDERWATER STRUCTURAL INSPECTIONS - NORTH SIDE	R2113811	Hand/ 4520	Markos/ 4421
A2182633	535	REPLACE EXPANSION JOINT Y-3-16, CIR WATER SYSTEM	R2113836	Tamburro/ 4141	Roddey/ 4178

1R22 LRA WOs (101)

Action Request	System	Problem Description	Work Order	Program Owner	Program Manager
A2182635	535	REPLACE EXPANSION JOINT Y-3-30	R2113838	Tamburro/ 4141	Roddey/ 4178
A2182636	535	REPLACE EXPANSION JOINT Y-3-27	R2113839	Tamburro/ 4141	Roddey/ 4178
A2182810	541	LICENSE RENEWAL/RBCCW PIPING INSPECTION IN DRYWELL	R2113993	Hand/ 4520	Markos/ 4421
A2183180	187	LICENSE RENEWAL/INSPECTION OF PIPING UNDER INSULATION IN DW	R2114261	Hand/ 4520	Markos/ 4421
A2183181	100	LICENSE RENEWAL/INSIDE INTAKE CANAL EXPANSION JOINTS	R2114262	Hand/ 4520	Markos/ 4421
A2183227	187	LICENSE RENEWAL/MAIN STEAM LINE INSPECTION IN DRYWELL	R2114299	Hand/ 4520	Markos/ 4421
A2183228	187	LICENSE RENEWAL/FEEDWATER LINE INSPECTION IN DRYWELL	R2114300	Hand/ 4520	Markos/ 4421
A2184441	814	TRUNNION ROOM FIRE DOOR INSPECTION	R2115105	Trettel/ 2264	McMillan/ 4111
A2185286		INSPECT DRYWELL AT EL 23' 6" LR	R2115674	Harttraff/ 2287	Roddey/ 4178
A2187833	187	INSPECT DW TRENCHES - LRA COMMITMENT	R2117387	Tamburro/ 4141	Roddey/ 4178
A2190456	424	PERFORM INTERNAL INSPECTIONS OF T-11-1 (CST)	R2119514	Sparks/ 4109	McMillan/ 4111
A2190721	531	LICENSE RENEWAL/SEAL WELL - STRUCTURAL MONITORING	R2119740	Hand/ 4520	Markos/ 4421
A2191777	531	LICENSE RENEWAL/SERVICE WATER/EMERGENCY SERVICE WATER	R2120584	Hand/ 4520	Markos/ 4421
A2192721	535	PIPING AND FITTINGS UPSTREAM OR DOWNSTREAM OF V-3-13	R2121220	Tamburro/ 4141	Roddey/ 4178
A2192730	535	INSPECT COATED CS PIP IN SW SYS. UPSTRM OR DSTRM F V-3-12	R2121228	Tamburro/ 4141	Roddey/ 4178
A2192732	535	INSPECT COATED CS PIP IN SW SYS. UPSTRM OR DSTRM F V-3-58	R2121230	Tamburro/ 4141	Roddey/ 4178
A2192993	333	FLOW GLASS FG-3-380	R2121407	Tamburro/ 4141	Roddey/ 4178
A2193109	333	OPEN/INSPECT INTERNAL OF FLOW INDICATOR BODIES - FI-333-5	R2121461	Tamburro/ 4141	Roddey/ 4178
A2193111	333	OPEN/INSPECT INTERNAL OF FLOW INDICATOR BODIES - FI-333-9	R2121463	Tamburro/ 4141	Roddey/ 4178
A2193113	333	OPEN/INSPECT INTERNAL OF FLOW INDICATOR BODIES - FI-333-11	R2121465	Tamburro/ 4141	Roddey/ 4178
A2193127	421	OPEN/INSPECT INTERNAL OF GLASS BODIES - LI-3, 52, 56	R2121480	Tamburro/ 4141	Roddey/ 4178
A2193248	535	OPEN/INSPECT INTERNAL PORTIONS OF VALVE BODY V-3-125	R2121587	Tamburro/ 4141	Roddey/ 4178
A2193250	535	OPEN/INSPECT INTERNAL PORTIONS OF VALVE BODY V-3-58	R2121590	Tamburro/ 4141	Roddey/ 4178

1R22 LRA WOs (101)

Action Request	System	Problem Desc Atn	Work Order	Program Owner	Program Manager
A2193252	535	OPEN/INSPECT INTERNAL PORTIONS OF VALVE BODY V-3-110	R2121592	Tamburro/ 4141	Roddey/ 4178
A2193786	535	PM TO INSPECT V-3-13 INTERNAL (LRA)	R2121963	Tamburro/ 4141	Roddey/ 4178
A2194292	187	INSPECT TORUS VENT LINE/VENT HEADER FOR CORROSION	R2122300	Tamburro/ 4141	Roddey/ 4178
A2194644	333	OPEN AND INSPECT ONE COPPER ALLOY STRAINER (LRA)	R2122551	Tamburro/ 4141	Roddey/ 4178
A2194658	535	INSPECT INTERNAL PORTIONS OF 4 CIRC WTR THERMOWELLS (LRA)	R2122565	Tamburro/ 4141	Roddey/ 4178
A2194670	535	PERFORM INTERNAL INSPECTION OF V-3-1041 (LRA)	R2122575	Tamburro/ 4141	Roddey/ 4178
A2194697	775	PERFORM CABLE INSPECTIONS DW & COND BAY (LRA)	R2122597	Pruthi/ 4436	Barnes/ 4719
A2198049	621	LPRM CABLE DIAGNOSTICS	R2124860	Jimenez/ 4833	Skelskey/ 4475
A2204217		PERIODIC VISUAL INSPECTION OF VALVES V-3-74 OR V-3-75	R2129041	Tamburro/ 4141	Roddey/ 4178
A2110003	532	Repace ESW System 2 Undergrouind Pipe	C2017279	Tamburro/ 4141	Roddey/ 4178
A2107517	532	Repace ESW System 2 Undergrouind Pipe		Tamburro/ 4141	Roddey/ 4178
A2107518	532	Repace ESW System 1 Undergrouind Pipe		Tamburro/ 4141	Roddey/ 4178