

Joseph H. Plona
Site Vice President

6400 N. Dixie Highway, Newport, MI 48166
Tel: 734.586.5910 Fax: 734.586.4172

DTE Energy



10 CFR 50.55a

2009

July 23, 2008 (This letter is re-issued without the enclosure to correct the date.)
NRC-09-0038

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington D C 20555-0001

Reference: Fermi 2
NRC Docket No. 50-341
NRC License No. NPF-43

Subject: Inservice Inspection Summary Report

Enclosed is the Summary Report of the 2009 Inservice Inspection (ISI) activities performed at Detroit Edison Company's Fermi 2 Nuclear Power Plant. This report represents a summary of the ISI activities for the Second Ten-Year Inspection Interval beginning February 17, 2000 through the Thirteenth Refueling Outage, which was completed on May 1, 2009.

This report is being submitted in accordance with ASME Section XI, 1989 Edition, paragraph IWA-6230, for IWB, IWC, IWD, and IWF inspections, and the 1992 Edition, including the 1992 Addenda, for IWE inspections.

Should you have any questions or require additional information, please contact Mr. Rodney W. Johnson, Manager - Nuclear Licensing, at (734) 586-5076.

Sincerely,

Enclosure

cc: NRC Project Manager
NRC Resident Office
Reactor Projects Chief, Branch 4, Region III
Regional Administrator, Region III
M. Wilson - ANII
Supervisor, Electric Operators,
Michigan Public Service Commission
R. J. Aben Jr. - Chief Inspector
Michigan Department of Labor & Economic Growth
Bureau of Construction Codes and Fire Safety - Boiler Division

A047
NRC