

NRC INSPECTION MANUAL

DIRS

Change Notice 11-005

DELETED:

<u>Number</u>	<u>Date</u>	<u>Number</u>	<u>Date</u>
1. _____	_____	IMC 0351	04/05/11
2. _____	_____	IP 40100	04/05/11
3. IP 71111.15	11/16/09	IP 71111.15	04/05/11
4. TI 2515/180	10/07/09	_____	_____

TRAINING: None

REMARKS: IMC 0351 (Implementation of The Reactor Oversight Process at Reactor Facilities in an Extended Shutdown Condition for Reasons Other Than Significant Performance Problems) is issued to provide guidance for ROP implementation during extended outages not related to performance.

IP 40100 (Independent Safety Culture Assessment Followup) is issued to provide guidance for following up on an NRC request for a licensee to perform an independent safety culture assessment.

IP 71111.15 (Operability Determinations and Functionality Assessments) has been revised to clarify and enhance the sample selection guidance related to functionality assessments associated with Technical Specification (TS) structures, systems, and components (SSCs) operability determinations and provides the additional latitude to select risk significant SSCs which may not be identified in the TS for sampling.

TI 2515/180 (Inspection of Procedures and Processes for Managing Fatigue) has been deleted because the inspection activities have been completed.

DISTRIBUTION: Standard

END