

Thomas D. Gatlin
Vice President, Nuclear Operations
803.345.4342



April 25, 2011

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, DC 20555

Dear Sir / Madam:

Subject: VIRGIL C. SUMMER NUCLEAR STATION (VCSNS) UNIT 1
DOCKET NO. 50/395
OPERATING LICENSE NO. NPF-12
SPECIAL REPORT (SPR) 2011-001

South Carolina Electric & Gas Company (SCE&G) is submitting this Special Report pursuant to the requirements of Technical Specifications 6.9.2 and Fire Protection Procedure (FPP)-025, "Fire Containment," Section 4.2 and Enclosure 6.6. This report addresses Control Building Fire/Pressure Door (DRCB/102) being inoperable for greater than seven days prior to completing repair of the door.

On March 21, 2011, DRCB/102 was noted as being inoperable when the door did not latch properly during use. The door was entered into the station's corrective action program under CR-11-01278 and CR-11-01367. Repair of the door was not completed until March 30, 2011, which is outside the seven-day limitation of the VCSNS Fire Protection Program.

A roving fire watch was established and auxiliary steam to the Auxiliary Building was tagged out to remove the need for the door to function as a steam propagation barrier on March 21, 2011. These measures remained in effect until the repairs were completed and the door was made operable on March 30, 2011.

Should you have any questions, please call Bruce Thompson at (803) 931-5042 at your convenience.

Very truly yours,

Thomas D. Gatlin

TS/TDG/gr

c: K. B. Marsh
S. A. Byrne
J. B. Archie
N. S. Carns
J. H. Hamilton
R. J. White
W. M. Cherry
V. M. McCree

R. E. Martin
NRC Resident Inspector
INPO Records Center
K. M. Sutton
NSRC
RTS (CR-11-01278 and CR-11-01367)
File (818.08)
PRSF (RC-11-0061)

JE22
A006
NRC