## Catts, Michelle

From: Dries, Michael

Sent: Friday, September 10, 2010 5:48 PM

To: Catts, Michelle

Subject: FW: RCP Motors With Truncated Flow Chamber Modification

Michelle,

As a follow up to Rich Burroni's e-mail and my previous e-mail to you, Westinghouse confirmed below our present records and cleared up the mystery about two of the motors. Therefore a total of seven of the eight operating pumps have had the flow chamber modification and the listing is below. Only the motor on RCP-24 and our two spare motors have not been modified.

Mike

From: Dries, Michael Sent: Friday, September 10, 2010 4:31 PM To: Burroni, Richard J Cc: Raffaele, Joseph J; Chan, Tat; Hixson, Matthew T Subject: FW: RCP Motors With Truncated Flow Chamber Modification

Rich,

From my records:

LM-92P152	8/1999	RCP-34
2S-74P500	4/2001	RCP-32
15-76P888	11/2002	RCP-22
3S-76P888	1/2006	RCP-33
1S-D001	12/2006	RCP-23
2S-76P888	. 11/2007	RCP-31
35-74P500	3/2010	RCP-21

## Mike

From: Hixson, Matthew T [mailto:hixsonmt@westinghouse.com] Sent: Friday, September 10, 2010 10:29 AM To: Dries, Michael Cc: Brady, David R.; Harms, Steve R Subject: FW: RCP Motors With Truncated Flow Chamber Modification

The NRC was looking for this.

Could you lend some clarity on unit 2 v unit 3

From: Brady, David R. Sent: Friday, September 10, 2010 9:47 AM To: Harms, Steve R Cc: Hixson, Matthew T; Stickel, Mark M.; Moxie, Jai Information in this record was deleted in accordance with the Freedom of Information Act, exemptions

FOIA



Subject: RCP Motors With Truncated Flow Chamber Modification

Steve,

Per your request, the following RCP motors at Indian Point have had the truncated flow chamber modification:

LM-92P152	8/1999
2S-74P500	4/2001
1S-76P888	11/2002
3S-76P888	1/2006
1S-D001	12/2006
2S-76P888	11/2007
3S-74P500	3/2010

Please note Indian Point swaps motors between units, thus I do not know present location of motors with respect to the unit it is installed in. The original shop order for unit #2 is 74P500 and unit #3 is76P888 If you have further questions please let me know.

regards,

dave

David R. Brady Principal Engineer Rotating Equipment Services

Westinghouse Electric Company Waltz Mill Facility Madison, PA 15663, USA Phone: +1 (724) 722-5639 Fax: +1 (724) 722-5424

Cell (b)(6) Email: bradydr@westinghouse.com Home Page: www.westinghousenuclear.com

ex 6 CHEMINION