

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 12/31/2011)**

TAC NO.	TAC TITLE	STATUS	AGE (Mon)	TAC OPENED	LEAD ORG
ME4841	RIS 'Adequacy of Station Electric Distribution System Voltages'	O	15.0	10/08/2010	DE
ME5167	RIS 'Staff Position on the Clarification of Submitting of Alter. Under 10 CFR 50.55'	O	13.0	12/13/2010	DCI
ME5784	RIS 'Selecting Edition and Addenda of Section XI of ASME Code for Part 52 Inspection Programs'	O	10.0	03/07/2011	NRO
ME6022	RIS 'Guidance on Meeting NRC Expectations for Generic Letter 96-05'	O	9.0	04/13/2011	DCI
ME6255	RIS 'Metal Fatigue Analysis Performed By Computer Software'	O	8.0	05/17/2011	DLR
ME6641	RIS 'Clarification of Methods For Applicant And Vendor Compliance With Part 21'	O	6.0	07/05/2011	NMSS
ME6862	RIS 'Endorsement of NEI Guidance Addendum for Managing Personnel Fatigue at Power Reactor Sites'	O	5.0	08/15/2011	DIRS
ME6890	RIS 'NRC Staff Position on Applying SRs 3.0.2 & 3.0.3 to Administrative Controls Program'	O	5.0	08/22/2011	DIRS
ME7109	RIS 'Insights into Reactor LR Application Consistency with the GALL Report'	O	4.0	09/13/2011	DLR
ME7133	RIS 'Reintegration of Security into the Reactor Oversight Process Action Matrix'	O	4.0	09/19/2011	DIRS
ME7208	RIS 'Use of 10 CFR 72.212 Evaluations to Accept Conditions Outside of the FSAR Analysis'	O	4.0	09/29/2011	NMSS

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 12/31/2011)**

TAC NO.	TAC TITLE	STATUS	AGE (Mon)	TAC OPENED	LEAD ORG
ME4076	IN 'Non-Conservatism with Spent Fuel Pool Criticality Analyses'	O	19.0	06/16/2010	DPR
ME6847	IN 'Hydrology Study Affects Design Basis External Flooding Evaluation'	O	5.0	08/12/2011	DE
ME6848	IN 'Seismic Issues Involving Safety-Related Tanks'	O	5.0	08/12/2011	DIRS
ME7139	IN 'Electrolytic Capacitor Degradation Issues'	O	4.0	09/19/2011	DIRS
ME7178	IN 'Plant Systems that have Leaked with the Potential for Groundwater Contamination'	O	4.0	09/26/2011	DPR
ME7565	IN 'Fuel Assembly Design Evaluation for a Seismic Event'	O	2.0	11/15/2011	NRO
ME7680	IN 'Preconditioning of Pressure Switches Surveillance Testing'	O	1.0	12/09/2011	EICB
ME7681	IN 'Ineffective Use of Vendor Technical Recommendations'	O	1.0	12/09/2011	IOEB
ME7682	IN 'Hazardous Chemical Fumes Impact Plant Operations'	O	1.0	12/09/2011	IOEB
ME7683	IN 'Ventilation System Design Control Issues Challenge Safety System Function'	O	1.0	12/09/2011	IOEB
ME5720	GL 'Implications of Updated Probabilistic Seismic Hazard Estimates in Central and Eastern US of Existing Plants'	O	11.0	02/22/2011	DPR