

-R2
From: Walker, Shakur
To: Kolcum, Gregory
Cc: Franke, Mark; Suggs, LaDonna; Clagg, Rodney
Subject: NA AIT Requests - Walker 9/9/11
Date: Friday, September 09, 2011 1:22:14 PM

Please provide the following requests to the licensee:

1. Regarding 2H EDG, please provide manufacturing specs for the jacket water cooling gasket
2. Regarding 1J/2J EDG Missing Orifice Plates:
 - a. How long has the condition existed for both diesels?
 - b. Why was the pump replaced previously?
 - c. Why was the pump being replaced/worked on 9/4/11 which led to the discovery?
 - d. Please explain what is meant by the missing plate was found still attached to the removed discharge flange (i.e., for which pump – current or from 2004)
 - e. Please be prepared to discuss CR 441537/441540

I'm reviewing the other OD now and if I have additional questions, I'll provide them.

Thanks
Shakur

Shakur A. Walker | Sr. Reactor Inspector
Engineering Branch 1 | Electrical / Digital I&C
U S Nuclear Regulatory Commission
p_404.997.4639 | f_404.997.4907
shakur.walker@nrc.gov

B/34