

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 74

FILE: INCIDENT REPORT

FROM: Iowa Electric Light & Pwr Cedar Rapids, Iowa Mr. G.G. Hunt		DATE OF DOC 12-23-74	DATE REC'D 1-3-75	LTR X	TWX	RPT	OTHER
TO: J. Keppler		ORIG none signed	CC	OTHER	SENT AEC PDR	XXX	
					SENT LOCAL PDR	XXX	
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-331		

DESCRIPTION:
Ltr reporting an abnormal Occurrence at the Duane Arnold Nuclear Power Plant...concerning Abnormal Occurrence No. 50-331/74-33...
MOV 2300 inoperable (HPCI CST Isolation Valve)
.....

ENCLOSURES:
ACKNOWLEDGED
DO NOT REMOVE

PLANT NAME: Duane Arnold

FOR ACTION/INFORMATION 1-4-75 JB

- | | | | |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (S)
W/ Copies | SCHWENCER (S)
W/ Copies | ZIEMANN (S)
W/ Copies | REGAN (E)
W/ Copies |
| CLARK (S)
W/ Copies | STOLZ (S)
W/ Copies | DICKER (E)
W/ Copies | LEAR (S)
W/4 Copies |
| PARR (S)
W/ Copies | VASSALLO (S)
W/ Copies | KNIGHTON (E)
W/ Copies | SPEIS (S)
W/ Copies |
| KNIEL (S)
W/ Copies | PURPLE (S)
W/ Copies | YOUNGBLOOD (E)
W/ Copies | |

INTERNAL DISTRIBUTION

- | | | | | |
|--|--|--|--|---|
| <u>REG FILE</u>
AEC-PDR
COGC, ROOM P-506-A
MUNIZING/STAFF
CASE
GIAMBUSSO
BOYD
MOORE (S) (BWR)
DEYOUNG (S) (PWR)
SKOVHOLT (S)
GOLLER (S)
P. COLLINS
DENISE
REG OPR
FILE & REGION
T.R. WILSON | TECH REVIEW
SCHROEDER
MACCARRY
KNIGHT
PAWLICKI
SHAO
STELLO
HOUSTON
NOVAK
ROSS
IPPOLITO
TEDESCO
LONG
LAINAS
BENAROYA
STEELE
VOLIMER | DENTON
GRIMES
GAMMILL
KASTNER
BALLARD
SPANGLER

ENVIRO
MULLER
DICKER
KNIGHTON
YOUNGBLOOD
REGAN
PROJECT LDR
HARLESS | LIC. ASST.
DIGGS (S)
GEARIN (S)
GOULBOURNE (S)
KREUTZER (E)
LEE (S)
MAIGRET (S)
REED (E)
SERVICE (S)
SHEPPARD (S)
SLATER (E)
SMITH (S)
TEETS (S)
WILLIAMS (E)
WILSON (S)
INGRAM (S) | A/T IND
BRAITMAN
SALTZMAN
B. HURT

PLANS
MCDONALD
CHAPMAN
DUBE w/input
E. COUPE
D. THOMPSON (2)
KLECKER
F. WILLIAMS |
|--|--|--|--|---|

EXTERNAL DISTRIBUTION

- | | | |
|--------------------------------|--------------------------------|---|
| 1-LOCAL PDR Cedar Rapids, Iowa | (1) (2) (10) -NATIONAL LABS | 1-PDR SAN/LA/NY |
| 1-TIC (ABERNATHY) | 1-M. PENNINGTON, RM E-201 G.T. | 1-BROOKHAVEN NAT LAB |
| 1-NSIC (BUCHANAN) | 1-CONSULTANTS | 1-G. ULRIKSON, ORNL |
| 1-ASLB | NEWMARK/BLUME/AGBABIAN | 1-AGMED (RUTH GUSSMAN)
RM B-127 G.T. |
| 1-NEWTON ANDERSON | | 1-J. RUNKLES, RM E-201
G.T. |
| 5-ACRS SENT TO LIC ASST. | | |

Case

Regulatory Docket File

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS, IOWA
DUANE ARNOLD ENERGY CENTER
PALO, IOWA
DECEMBER 23, 1974
DAEC - 74 - 426

Mr. James Keppler, Director
Regulatory Operations Regional Office
U. S. Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: Abnormal Occurrence No. AO 50-331/74-53
FILE: A-118a
A-110

Dear Mr. Keppler:

In accordance with DAEC Technical Specifications, Section 6.11.2A.1 this letter is intended as notification of an abnormal occurrence at the Duane Arnold Energy Center on December 22, 1974. This letter, telecopied to your office, is intended to satisfy the requirements for notification by telegram within 24 hours of an abnormal occurrence.


Identification of Occurrence

MOV 2300 inoperable (HPCI CST Isolation Valve), reportable in accordance with Appendix A, Operating License DPR-49, Specification 1.0.4.d..


Description of Occurrence

While conducting routine panel checks, the Reactor Operator observed that indicating lights on MOV 2300 were not functional. Further checks revealed that due to a failure of the 27P coil control power to the motor operator was not available. MOV 2300 was in the normal open position.

Investigation is continuing.



A formal written report will be submitted to the Office of Directorate of Regulatory Operations within 10 days of the subject abnormal occurrence.



G. G. Hunt
Chief Engineer
Duane Arnold Energy Center

RH:GGH:pd

CC: E. G. Case
C. W. Sandford
J. A. Wallace
E. L. Hammond
B. R. York
D. L. Wilson
R. R. Rinderman
L. D. Root
H. W. Rehrauer - Chairman, Safety Committee
G. A. Cook