

# IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

Cedar Rapids, Iowa  
DUANE ARNOLD ENERGY CENTER  
PALO, IOWA  
JULY 7, 1975  
DAEC-75-269

50-331

Mr. James G. Keppler, Director  
Office of Inspection and Enforcement-Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

SUBJECT: Abnormal Occurrence

FILE: A-110, A-118

Dear Mr. Keppler:

In accordance with DAEC Technical Specifications, Specification 6.11.2.A.1, this letter is a notification of an abnormal occurrence at the Duane Arnold Energy Center on July 7, 1975. This letter, telecopied to your office, is intended to satisfy the requirement for notification by telegram within 24 hours of an abnormal occurrence.

### Identification of Occurrence


Out-of-specification pressure differential indicating switch, reportable in accordance with Appendix A to Operating License DPR-49, Specifications 1.0.4.b and Table 3.2.B.

### Description of Occurrence

During the performance of Surveillance Test No. 42B025, HPCI Steam Line High-Dp Instrument Functional Test/Calibration, it was determined that the trip setting of Pressure Differential Indicating Switch 2244 was 84 inches water. The limiting set point for operation is 100 ± 7 inches water. (See Abnormal Occurrence Report No. AO 50-331/74-47 submitted November 4, 1974).

A formal written report will be submitted to the Office of Inspection and Enforcement within 10 days of the subject abnormal occurrence.

Very truly yours,



G. G. Hunt  
Chief Engineer  
Duane Arnold Energy Center

DEW/GCH/mg

cc: B. C. Rusche L. D. Root R. H. Hinderman E. L. Hammond  
C. W. Sandford H. R. York G. A. Cook  
J. A. Wallace D. L. Wilson H. W. Rehner - Chairman, Safety Committee

Received  
3:46  
KH 7/7/75