

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Medical Faculty Associates Heart Care Imaging, Inc. 2150 Pennsylvania Avenue, NW, Suite 4-232 Washington, DC 20037 REPORT NUMBER(S) 2012-001	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
3. DOCKET NUMBER(S) 030-37218	4. LICENSE NUMBER(S) 08-31160-01	5. DATE(S) OF INSPECTION <i>January 23, 2012</i>

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

10 CFR 35.67(g) requires, in part, that a licensee in possession of sealed sources shall conduct a semi-annual physical inventory of all such sources in its possession. Contrary to the above, as of January 23, 2012, the licensee's semi-annual physical inventory did not list all such sources in its possession. Specifically, a Cerium-139 source and a Cobalt-57 button source were not listed on the licensee's inventory. The licensee committed to adding the two sealed sources to their inventory by January 27, 2012 and will inventory them every six months.

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Erwin Osborn	<i>[Signature]</i>	1-23-2012
NRC INSPECTOR	Janice Nguyen	<i>[Signature]</i>	1-23-2012
BRANCH CHIEF	JOSEPH NICK <i>[Signature]</i>	<i>[Signature]</i>	2/13/12

*NRC FORM 591M PART 1 (10-2011) (RI Rev. 01/12/2012)

G:\WordDocs\Current\Insp Record\R08-31160-01.2012-001.591M-Part1.doc

SUNSI Review Completed By: / RA / Janice Nguyen Public Non-Sensitive