

**U.S. NUCLEAR REGULATORY COMMISSION**

2/22/2012

**Date:****TELEPHONE CONVERSATION RECORD**

**Mail Control** 576549 **License No(s).** 01-00126-16 **Docket No(s).** 03012630  
**or Report No(s).**

**Name of Licensee:** Department of the Army

**Name of Participant(s):** Stephen Howard, Radiation Safety Officer  
Dave Walsh, staff of Stephen Howard  
Dennis Lawyer, R1, DNMS

**Telephone No.** 256-876-5593

**Subject:** RAI, 10 CFR 36.23(a) Check

(NOTE: This will be used as the  
Documents Title in ADAMS)

I discussed that the interlock checks for the door exit submitted in the February 16, 2012 letter did not check the door operation in the most stringent condition. That would be with the radiation monitor interlock engaged required in 10 CFR 36.23(c) and the door locked. Mr. Walsh said that it was an oversight in the letter they sent and that it was in their procedure. He said that would send an update to the interlock checks to us.

**Action Required:** New interlock procedure would be submitted.

**Document Availability:**

**Publicly Available**

**Non-Publicly Available**

**Non-Sensitive**  
 **Sensitive – Privacy Act/ PII**  
 **Immediate Release**

**Non-Sensitive Copyright**  
 **Sensitive – Internal**

Normal Release Date: 03/01/2012

**Sensitive- Proprietary**  
 **Sensitive – Security-Related**  
**Delayed Release Date:**

SUNSI Review Completed By: Dennis Lawyer

/ RA /

Document Accession #: ML120540237