

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-520	320020	1056150	217
42	75	34	4275-34-521	317220	1059600	279
42	75	34	4275-34-522	317216	1060338	319
42	75	34	4275-34-523	316420	1059600	255
42	75	34	4275-34-524	316420	1058800	239
42	75	34	4275-34-525	316420	1058000	216
42	75	34	4275-34-526	316820	1057800	215
42	75	34	4275-34-527	316420	1057200	199
42	75	34	4275-34-528	315620	1058800	259
42	75	34	4275-34-529	315620	1058400	250
42	75	34	4275-34-530	318370	1058800	295
42	75	34	4275-34-531	315620	1056800	215
42	75	34	4275-34-532	315620	1057600	238
42	75	34	4275-34-533	315620	1060000	255
42	75	34	4275-34-534	315620	1059200	250
42	75	34	4275-34-535	317820	1060350	339
42	75	34	4275-34-536	317820	1060150	335
42	75	34	4275-34-537	317820	1059950	312
42	75	34	4275-34-538	318020	1060050	338
42	75	34	4275-34-539	317920	1060050	335
42	75	34	4275-34-540	317920	1059850	250
42	75	34	4275-34-541	317720	1059950	315
42	75	34	4275-34-542	317520	1059750	298
42	75	34	4275-34-543	317520	1059550	294
42	75	34	4275-34-544	317620	1059450	297
42	75	34	4275-34-545	316420	1060400	299
42	75	34	4275-34-546	317220	1058800	275
42	75	34	4275-34-547	317820	1057650	202
42	75	34	4275-34-548	317970	1060100	337
42	75	34	4275-34-549	317720	1060350	336
42	75	34	4275-34-550	317920	1059950	315
42	75	34	4275-34-551	318020	1059850	315
42	75	34	4275-34-552	317520	1059650	296
42	75	34	4275-34-553	317420	1059550	298
42	75	34	4275-34-554	317420	1059700	293
42	75	34	4275-34-555	317420	1059400	299
42	75	34	4275-34-556	317320	1059600	272
42	75	34	4275-34-557	317320	1059450	293
42	75	34	4275-34-558	317370	1057900	400
42	75	34	4275-34-559C	317470	1057900	400
42	75	34	4275-34-560C	317576	1057895	400
42	75	34	4275-34-561	316920	1058050	218
42	75	34	4275-34-562	316420	1057800	236
42	75	34	4275-34-563	317020	1057800	218
42	75	34	4275-34-564	316880	1057700	218
42	75	34	4275-34-565	317220	1058600	255
42	75	34	4275-34-566	317220	1059000	276
42	75	34	4275-34-567	315620	1058800	256
42	75	34	4275-34-568	318920	1056150	239
42	75	34	4275-34-569	317920	1056050	219
42	75	34	4275-34-570	317470	1059550	294

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-571	317520	1059600	294
42	75	34	4275-34-572	317270	1059600	294
42	75	34	4275-34-573	317620	1059750	314
42	75	34	4275-34-574	317770	1059850	316
42	75	34	4275-34-575	317970	1059950	338
42	75	34	4275-34-576	317970	1060050	335
42	75	34	4275-34-577	317920	1060150	336
42	75	34	4275-34-578	318071	1060200	334
42	75	34	4275-34-579	318020	1060150	337
42	75	34	4275-34-580	317770	1060050	337
42	75	34	4275-34-581	317620	1059650	295
42	75	34	4275-34-582	317620	1059550	298
42	75	34	4275-34-583	317720	1059650	294
42	75	34	4275-34-584	317320	1058450	255
42	75	34	4275-34-585	316824	1057741	233
42	75	34	4275-34-586	317970	1060150	350
42	75	34	4275-34-587	317770	1060100	334
42	75	34	4275-34-588	317770	1060000	340
42	75	34	4275-34-589	317720	1060050	334
42	75	34	4275-34-590	317670	1059750	311
42	75	34	4275-34-591	317670	1059650	315
42	75	34	4275-34-592	317470	1059600	294
42	75	34	4275-34-593	317420	1059500	294
42	75	34	4275-34-594	317870	1060150	335
42	75	34	4275-34-595	317870	1060400	337
42	75	34	4275-34-596	317964	1060394	353
42	75	34	4275-34-597	318057	1060394	353
42	75	34	4275-34-598	318170	1060400	334
42	75	34	4275-34-599	317870	1060300	335
42	75	34	4275-34-600	317971	1060293	334
42	75	34	4275-34-601	318070	1060296	334
42	75	34	4275-34-602	318177	1060304	334
42	75	34	4275-34-603	317857	1060488	357
42	75	34	4275-34-604	317720	1059800	314
42	75	34	4275-34-605	317820	1059900	314
42	75	34	4275-34-606	317920	1060000	334
42	75	34	4275-34-607	318120	1060150	333
42	75	34	4275-34-608	317720	1060450	335
42	75	34	4275-34-609	317770	1060150	333
42	75	34	4275-34-610	317720	1060100	336
42	75	34	4275-34-611	317820	1060100	334
42	75	34	4275-34-612	317870	1060050	334
42	75	34	4275-34-613	317620	1059600	295
42	75	34	4275-34-614	317520	1059450	292
42	75	34	4275-34-615	317670	1059800	313
42	75	34	4275-34-616	317870	1060200	330
42	75	34	4275-34-617	317320	1059350	294
42	75	34	4275-34-618	317220	1059450	274
42	75	34	4275-34-619	317220	1058300	234
42	75	34	4275-34-626	317220	1060000	293
42	75	34	4275-34-627C	317870	1058600	253

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-628C	317970	1058600	273
42	75	34	4275-34-629C	318070	1058600	274
42	75	34	4275-34-631	317222	1057895	400
42	75	34	4275-34-632	317210	1057794	400
42	75	34	4275-34-633	317642	1057969	400
42	75	34	4275-34-634	317568	1057653	400
42	75	34	4275-34-635	317546	1057596	400
42	75	34	4275-34-636	317543	1057553	400
42	75	34	4275-34-637	317566	1057842	400
42	75	34	4275-34-638	317774	1057884	400
42	75	34	4275-34-639	317774	1057884	400
42	75	34	4275-34-640	317120	1059600	273
42	75	34	4275-34-641	316820	1059200	275
42	75	34	4275-34-642	317220	1059050	272
42	75	34	4275-34-643	317220	1058650	254
42	75	34	4275-34-644	317820	1060500	354
42	75	34	4275-34-645	317870	1060550	353
42	75	34	4275-34-646	318170	1060500	333
42	75	34	4275-34-647	318120	1060550	353
42	75	34	4275-34-648	317771	1060197	332
42	75	34	4275-34-649	317664	1059845	314
42	75	34	4275-34-650	317667	1059691	312
42	75	34	4275-34-651	317717	1059999	335
42	75	34	4275-34-652	317915	1059750	315
42	75	34	4275-34-653	318025	1060553	354
42	75	34	4275-34-654	317716	1060145	300
42	75	34	4275-34-655	318199	1060406	333
42	75	34	4275-34-656	318168	1060452	335
42	75	34	4275-34-657	318271	1060353	332
42	75	34	4275-34-658	318239	1060307	334
42	75	34	4275-34-659	318021	1060101	333
42	75	34	4275-34-660	318065	1060053	334
42	75	34	4275-34-661	317966	1059853	315
42	75	34	4275-34-662	317974	1059900	314
42	75	34	4275-34-663	317819	1059794	315
42	75	34	4275-34-664	317776	1059741	314
42	75	34	4275-34-665	317761	1060437	337
42	75	34	4275-34-666	317218	1058548	255
42	75	34	4275-34-667	317020	1057844	214
42	75	34	4275-34-668	317174	1057841	214
42	75	34	4275-34-669	317170	1057896	400
42	75	34	4275-34-670	317165	1057948	214
42	75	34	4275-34-671	317570	1057997	213
42	75	34	4275-34-672	317510	1057790	214
42	75	34	4275-34-673	316427	1057850	234
42	75	34	4275-34-674	318076	1060554	355
42	75	34	4275-34-675	317972	1060548	355
42	75	34	4275-34-676	317918	1060548	355
42	75	34	4275-34-677	317761	1060344	333
42	75	34	4275-34-678	317814	1060390	335
42	75	34	4275-34-679	317905	1060395	352

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-680	318018	1060000	335
42	75	34	4275-34-681	317318	1058303	228
42	75	34	4275-34-682	317976	1060594	354
42	75	34	4275-34-683	317765	1059644	294
42	75	34	4275-34-684	317717	1059589	292
42	75	34	4275-34-685	317112	1059693	293
42	75	34	4275-34-686	317122	1059501	274
42	75	34	4275-34-687	316816	1059596	274
42	75	34	4275-34-688	317171	1057795	213
42	75	34	4275-34-689	317123	1057793	400
42	75	34	4275-34-690	317120	1057841	211
42	75	34	4275-34-691	317116	1057894	213
42	75	34	4275-34-692	315600	1058600	259
42	75	34	4275-34-693	317212	1060143	315
42	75	34	4275-34-694	317220	1059747	293
42	75	34	4275-34-695	317566	1059494	294
42	75	34	4275-34-696	317023	1058700	249
42	75	34	4275-34-697	316920	1057743	211
42	75	34	4275-34-698	316637	1057692	229
42	75	34	4275-34-699C	317644	1058545	400
42	75	34	4275-34-700	317130	1059393	274
42	75	34	4275-34-701	317027	1059490	274
42	75	34	4275-34-702	317012	1059597	274
42	75	34	4275-34-703	317474	1059496	298
42	75	34	4275-34-704	317379	1059404	294
42	75	34	4275-34-705	316481	1057796	235
42	75	34	4275-34-706	316376	1057803	231
42	75	34	4275-34-707	317034	1059385	274
42	75	34	4275-34-708	317135	1059294	280
42	75	34	4275-34-709	317215	1060048	314
42	75	34	4275-34-710	316797	1060368	310
42	75	34	4275-34-711	316809	1059979	292
42	75	34	4275-34-712	317112	1059644	275
42	75	34	4275-34-713	317224	1059670	293
42	75	34	4275-34-714	317370	1059457	287
42	75	34	4275-34-715	317417	1060167	315
42	75	34	4275-34-716	316917	1058700	259
42	75	34	4275-34-717	317015	1058801	354
42	75	34	4275-34-718	317029	1058604	252
42	75	34	4275-34-719C	317528	1058762	400
42	75	34	4275-34-720	317694	1057897	400
42	75	34	4275-34-721	316986	1059383	266
42	75	34	4275-34-722	317040	1059287	272
42	75	34	4275-34-723	317418	1059600	292
42	75	34	4275-34-724	316912	1058802	253
42	75	34	4275-34-725	316815	1058709	255
42	75	34	4275-34-726	316914	1058607	255
42	75	34	4275-34-727	317125	1059557	271
42	75	34	4275-34-728	317216	1059842	295
42	75	34	4275-34-729	317311	1059789	250
42	75	34	4275-34-730	317325	1059690	293

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-731	317069	1059600	279
42	75	34	4275-34-732	317169	1059602	275
42	75	34	4275-34-733	317762	1060506	400
42	75	34	4275-34-734	317760	1060392	331
42	75	34	4275-34-735	317713	1060286	334
42	75	34	4275-34-736	317706	1060172	338
42	75	34	4275-34-737	318179	1060205	335
42	75	34	4275-34-738	318176	1060254	335
42	75	34	4275-34-739	318277	1060305	334
42	75	34	4275-34-740	318260	1060408	339
42	75	34	4275-34-741	318215	1060454	339
42	75	34	4275-34-742	318181	1060563	338
42	75	34	4275-34-743	318027	1060600	355
42	75	34	4275-34-744	317923	1060587	355
42	75	34	4275-34-745	317977	1060642	355
42	75	34	4275-34-746	318069	1060110	332
42	75	34	4275-34-747	318064	1060005	332
42	75	34	4275-34-748	318063	1059956	333
42	75	34	4275-34-749	318016	1059898	319
42	75	34	4275-34-750	317967	1059799	400
42	75	34	4275-34-751	317921	1059797	400
42	75	34	4275-34-752	317862	1059747	300
42	75	34	4275-34-753	317816	1059696	315
42	75	34	4275-34-754	317815	1059645	314
42	75	34	4275-34-755	317760	1059585	294
42	75	34	4275-34-756	317666	1059593	292
42	75	34	4275-34-757	317569	1059544	400
42	75	34	4275-34-758	316992	1059283	274
42	75	34	4275-34-759	317046	1059188	274
42	75	34	4275-34-760	316929	1059193	258
42	75	34	4275-34-761	317610	1059690	293
42	75	34	4275-34-762	317465	1059648	294
42	75	34	4275-34-763	317662	1059896	312
42	75	34	4275-34-764	318070	1060155	338
42	75	34	4275-34-765	318113	1060056	338
42	75	34	4275-34-766	317519	1059497	295
42	75	34	4275-34-767	317171	1059503	400
42	75	34	4275-34-768	317031	1059436	274
42	75	34	4275-34-769	317088	1059290	275
42	75	34	4275-34-770	317079	1059549	279
42	75	34	4275-34-771	317166	1059680	274
42	75	34	4275-34-772	317276	1059681	275
42	75	34	4275-34-773	317071	1059500	279
42	75	34	4275-34-774	317131	1059348	279
42	75	34	4275-34-775	317182	1059396	278
42	75	34	4275-34-776	317046	1059236	279
42	75	34	4275-34-777	316982	1059189	278
42	75	34	4275-34-778	317315	1059900	298
42	75	34	4275-34-779	317176	1059546	278
42	75	34	4275-34-780	317414	1060103	344
42	75	34	4275-34-781	317323	1060101	345

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-782	317422	1060300	316
42	75	34	4275-34-783	317319	1060157	312
42	75	34	4275-34-784	317657	1059948	400
42	75	34	4275-34-785	317763	1060289	336
42	75	34	4275-34-786	317716	1060244	335
42	75	34	4275-34-787	317719	1059901	314
42	75	34	4275-34-788	317865	1059699	314
42	75	34	4275-34-789	317467	1059448	285
42	75	34	4275-34-790	316964	1058802	279
42	75	34	4275-34-791	316974	1058700	259
42	75	34	4275-34-792	316812	1058609	258
42	75	34	4275-34-793	316823	1060625	313
42	75	34	4275-34-794	317270	1059751	250
42	75	34	4275-34-795	317162	1059740	279
42	75	34	4275-34-796	317970	1059746	314
42	75	34	4275-34-797	318020	1059789	310
42	75	34	4275-34-798	317756	1059535	298
42	75	34	4275-34-799	318070	1060647	350
42	75	34	4275-34-800	317869	1060580	351
42	75	34	4275-34-801	317449	1060642	337
42	75	34	4275-34-802	317646	1060652	335
42	75	34	4275-34-803	317244	1060639	337
42	75	34	4275-34-804	317711	1060389	300
42	75	34	4275-34-805	317369	1060162	400
42	75	34	4275-34-806	317425	1060344	314
42	75	34	4275-34-807	317818	1060573	400
42	75	34	4275-34-808	317350	1060639	400
42	75	34	4275-34-809	317323	1060297	317
42	75	34	4275-34-810	317322	1060000	295
42	75	34	4275-34-811	317268	1059900	289
42	75	34	4275-34-812	317216	1059504	279
42	75	34	4275-34-813	317083	1059340	278
42	75	34	4275-34-814	317076	1059433	279
42	75	34	4275-34-815	316980	1059093	259
42	75	34	4275-34-816	316873	1059099	400
42	75	34	4275-34-817	318220	1060500	400
42	75	34	4275-34-818	317764	1060241	332
42	75	34	4275-34-819	317816	1060288	332
42	75	34	4275-34-820	317672	1060197	332
42	75	34	4275-34-821	317447	1060496	333
42	75	34	4275-34-822	317110	1059735	279
42	75	34	4275-34-823	317548	1060646	300
42	75	34	4275-34-824	317045	1060638	335
42	75	34	4275-34-825	316425	1060609	300
42	75	34	4275-34-826	317372	1060103	315
42	75	34	4275-34-827	317414	1060007	400
42	75	34	4275-34-828	317267	1059805	400
42	75	34	4275-34-829	317113	1058798	256
42	75	34	4275-34-830	317026	1058655	255
42	75	34	4275-34-831	317573	1059450	400
42	75	34	4275-34-832	317771	1059442	292

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-833	317667	1059545	298
42	75	34	4275-34-834	318057	1059632	300
42	75	34	4275-34-835	317349	1060498	300
42	75	34	4275-34-836	317545	1060499	338
42	75	34	4275-34-837	317366	1060004	315
42	75	34	4275-34-838	317216	1059899	299
42	75	34	4275-34-839	317103	1059576	279
42	75	34	4275-34-840	316422	1058397	238
42	75	34	4275-34-841	317130	1059415	250
42	75	34	4275-34-842	317035	1059342	278
42	75	34	4275-34-843	317818	1060621	400
42	75	34	4275-34-844	317870	1060631	400
42	75	34	4275-34-845	317767	1060573	358
42	75	34	4275-34-846	317376	1060301	319
42	75	34	4275-34-847	317466	1060168	319
42	75	34	4275-34-848	317565	1060103	338
42	75	34	4275-34-849	317363	1059900	293
42	75	34	4275-34-850	317465	1059843	297
42	75	34	4275-34-851	316434	1059929	296
42	75	34	4275-34-852	316826	1058310	234
42	75	34	4275-34-853	317393	1060498	338
42	75	34	4275-34-854	317291	1060500	338
42	75	34	4275-34-855	316927	1059094	400
42	75	34	4275-34-856	317745	1060550	400
42	75	34	4275-34-857	317566	1060297	337
42	75	34	4275-34-858	317497	1060643	338
42	75	34	4275-34-859	317661	1060431	332
42	75	34	4275-34-860	317870	1059446	292
42	75	34	4275-34-861	317874	1059537	298
42	75	34	4275-34-862	318372	1057853	400
42	75	34	4275-34-863	318474	1057851	400
42	75	34	4275-34-864	318025	1057649	216
42	75	34	4275-34-865	317870	1057996	215
42	75	34	4275-34-866	316931	1059145	256
42	75	34	4275-34-867	316982	1059143	255
42	75	34	4275-34-868	317034	1059141	258
42	75	34	4275-34-869	317371	1060210	258
42	75	34	4275-34-870	317420	1060216	318
42	75	34	4275-34-871	317609	1060427	400
42	75	34	4275-34-872	317393	1060641	340
42	75	34	4275-34-873	317272	1060014	300
42	75	34	4275-34-874	316894	1058948	254
42	75	34	4275-34-875	319026	1056808	236
42	75	34	4275-34-876C	317080	1059388	400
42	75	34	4275-34-877C	317219	1059710	400
42	75	34	4275-34-878	316789	1058969	400
42	75	34	4275-34-879	316839	1058959	255
42	75	34	4275-34-880	316695	1058985	258
42	75	34	4275-34-881C	317770	1059700	317
42	75	34	4275-34-882C	317920	1060100	337
42	75	34	4275-34-883	317870	1060450	358

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-884C	318070	1060450	355
42	75	34	4275-34-885	317869	1058448	256
42	75	34	4275-34-886	317968	1058383	400
42	75	34	4275-34-887	317823	1058399	400
42	75	34	4275-34-888	317872	1058493	400
42	75	34	4275-34-891C	317775	1059106	295
42	75	34	4275-34-892C	317768	1058202	243
42	75	34	4275-34-893	317842	1058421	400
42	75	34	4275-34-894C	317898	1058275	400
42	75	34	4275-34-4073	318216	1058300	397
42	75	34	4275-34-4074	318069	1058710	395
42	75	34	4275-34-4075	318070	1058354	397
42	75	34	4275-34-4076	318071	1058203	398
42	75	34	4275-34-4077	318171	1058203	398
42	75	34	4275-34-4078	318171	1058153	397
42	75	34	4275-34-4079	317921	1058203	396
42	75	34	4275-34-4080	317770	1058156	398
42	75	34	4275-34-4081	317873	1058306	397
42	75	34	4275-34-4082	317901	1058402	394
42	75	34	4275-34-4083	317670	1059006	398
42	75	34	4275-34-4084	317770	1059108	397
42	75	34	4275-34-4085	317950	1059373	397
42	75	34	4275-34-4086	317126	1059438	364
42	75	34	4275-34-4087	317719	1059698	396
42	75	34	4275-34-4088	317315	1059958	397
42	75	34	4275-34-4089	317874	1059855	397
42	75	34	4275-34-4090	317874	1059963	398
42	75	34	4275-34-4091	317867	1060110	398
42	75	34	4275-34-4092	317971	1060203	396
42	75	34	4275-34-4093	318137	1060235	399
42	75	34	4275-34-4094	317935	1060491	396
42	75	34	4275-34-4095	317870	1060628	398
42	75	34	4275-34-4128	318627	1060160	799
42	75	34	4275-34-4129	318906	1060121	806
42	75	34	4275-34-4130	318932	1060317	791
42	75	34	4275-34-4131	318966	1060607	803
42	75	34	4275-34-4132	318851	1059823	804
42	75	34	4275-34-4133	318819	1059631	802
42	75	34	4275-34-4134	319121	1059551	792
42	75	34	4275-34-4135	319071	1059380	794
42	75	34	4275-34-4136	319254	1059331	800
42	75	34	4275-34-4137	319218	1059146	792
42	75	34	4275-34-4143	318150	1057985	402
42	75	34	4275-34-4144	318235	1057967	402
42	75	34	4275-34-4145	319813	1056819	301
42	75	34	4275-34-4146	319427	1056804	303
42	75	34	4275-34-4147	317665	1058086	402
42	75	34	4275-34-4148	317508	1057981	402
42	75	34	4275-34-4158	317979	1058361	402
42	75	34	4275-34-4159	317919	1058498	405
42	75	34	4275-34-4160	317999	1058817	403

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-4161	317876	1059140	402
42	75	34	4275-34-4162	317806	1059590	402
42	75	34	4275-34-4163	317948	1060311	401
42	75	34	4275-34-4200	320020	1057258	303
42	75	34	4275-34-4201	319920	1057180	300
42	75	34	4275-34-4202	319920	1056960	302
42	75	34	4275-34-4203	319720	1056960	302
42	75	34	4275-34-4204	319620	1056760	300
42	75	34	4275-34-4206	319520	1056360	296
42	75	34	4275-34-4207	319520	1056260	305
42	75	34	4275-34-4208	319420	1056160	300
42	75	34	4275-34-4209	319320	1056210	302
42	75	34	4275-34-4210	319720	1056160	292
42	75	34	4275-34-4212	318920	1056560	303
42	75	34	4275-34-4213	318320	1057057	391
42	75	34	4275-34-4214	318520	1057157	402
42	75	34	4275-34-4215	318416	1057360	402
42	75	34	4275-34-4216	318415	1057657	400
42	75	34	4275-34-4217	318372	1057962	402
42	75	34	4275-34-4218	318316	1058048	398
42	75	34	4275-34-4219	317859	1057852	398
42	75	34	4275-34-4220	317775	1057902	397
42	75	34	4275-34-4221	317809	1057754	400
42	75	34	4275-34-4222	317323	1057358	400
42	75	34	4275-34-4223	317370	1057708	398
42	75	34	4275-34-4224	317450	1057799	398
42	75	34	4275-34-4225	317370	1057808	399
42	75	34	4275-34-4226	317413	1058108	399
42	75	34	4275-34-4227	317671	1058209	398
42	75	34	4275-34-4228	317820	1058209	399
42	75	34	4275-34-4229	317721	1058407	398
42	75	34	4275-34-4230	318372	1058358	402
42	75	34	4275-34-4231	318370	1058458	401
42	75	34	4275-34-4232	318320	1058559	400
42	75	34	4275-34-4233	318271	1058608	400
42	75	34	4275-34-4234	317973	1058529	400
42	75	34	4275-34-4235	317470	1058609	399
42	75	34	4275-34-4236	317375	1058816	400
42	75	34	4275-34-4237	317672	1058777	400
42	75	34	4275-34-4238	318120	1058958	398
42	75	34	4275-34-4239	318220	1058958	401
42	75	34	4275-34-4240	318117	1059154	400
42	75	34	4275-34-4241	318170	1059254	402
42	75	34	4275-34-4242	318170	1059509	402
42	75	34	4275-34-4243	318070	1059459	401
42	75	34	4275-34-4244	317869	1059373	402
42	75	34	4275-34-4245	317520	1059412	400
42	75	34	4275-34-4246	317695	1059452	402
42	75	34	4275-34-4247	317820	1059507	402
42	75	34	4275-34-4248	317952	1059555	402
42	75	34	4275-34-4249	317970	1059701	402

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-4250	318112	1059797	401
42	75	34	4275-34-4251	318128	1059989	402
42	75	34	4275-34-4252	318040	1060274	400
42	75	34	4275-34-4253	318330	1060312	400
42	75	34	4275-34-4254	318321	1060508	402
42	75	34	4275-34-4255	318230	1060571	400
42	75	34	4275-34-4256	318181	1060621	400
42	75	34	4275-34-4266	317767	1060629	400
42	75	34	4275-34-4267	317598	1060598	402
42	75	34	4275-34-4268	317497	1060598	402
42	75	34	4275-34-4269	317373	1060581	402
42	75	34	4275-34-4270	317660	1060493	400
42	75	34	4275-34-4271	317435	1060436	401
42	75	34	4275-34-4272	317608	1060358	402
42	75	34	4275-34-4273	317491	1060307	402
42	75	34	4275-34-4274	317466	1060223	401
42	75	34	4275-34-4275	317272	1060218	402
42	75	34	4275-34-4276	317413	1060063	402
42	75	34	4275-34-4277	317414	1059958	403
42	75	34	4275-34-4278	317313	1059852	402
42	75	34	4275-34-4279	316982	1059244	399
42	75	34	4275-34-4280	316819	1059107	400
42	75	34	4275-34-4281	316789	1058874	401
42	75	34	4275-34-4282	317113	1058708	399
42	75	34	4275-34-4283	316700	1058619	401
42	75	34	4275-34-4287	320036	1057350	299
42	75	34	4275-34-4288	320015	1057163	302
42	75	34	4275-34-4289	319975	1057061	300
42	75	34	4275-34-4292	317467	1057748	302
42	75	34	4275-34-4293	317770	1058305	301
42	75	34	4275-34-4294	317970	1058279	302
42	75	34	4275-34-4295	318170	1058350	301
42	75	34	4275-34-4296	317404	1058612	400
42	75	34	4275-34-4297	318168	1058903	301
42	75	34	4275-34-4298	318171	1059058	301
42	75	34	4275-34-4299	317872	1059055	301
42	75	34	4275-34-4300	318050	1059104	301
42	75	34	4275-34-4301	316930	1059244	299
42	75	34	4275-34-4302	317721	1059402	402
42	75	34	4275-34-4303	318170	1059406	402
42	75	34	4275-34-4304	318001	1059502	402
42	75	34	4275-34-4305	317669	1059804	400
42	75	34	4275-34-4306	318141	1059922	400
42	75	34	4275-34-4307	317915	1060256	397
42	75	34	4275-34-4308	318115	1060403	400
42	75	34	4275-34-4318	317660	1060580	401
42	75	34	4275-34-4319	317510	1060435	400
42	75	34	4275-34-4320	317349	1060435	401
42	75	34	4275-34-4321	317516	1060224	395
42	75	34	4275-34-4322	317465	1059958	400
42	75	34	4275-34-4323	317766	1060579	399

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-4350	318470	1058408	301
42	75	34	4275-34-4351	318320	1060621	398
42	75	34	4275-34-4356	317045	1060507	401
42	75	34	4275-34-4357	316814	1060507	401
42	75	34	4275-34-4358C	317985	1059701	399
42	75	34	4275-34-4359C	317987	1058529	399
42	75	34	4275-34-4361	318220	1059154	402
42	75	34	4275-34-4365	317250	1060430	399
42	75	34	4275-34-4366	317110	1060250	402
42	75	34	4275-34-4367	316945	1060509	402
42	75	34	4275-34-4368	316920	1060634	401
42	75	34	4275-34-4369	316770	1060635	401
42	75	34	4275-34-4370	318320	1059155	803
42	75	34	4275-34-4371	318095	1059040	802
42	75	34	4275-34-4372	318270	1059060	402
42	75	34	4275-34-4373	318320	1058960	402
42	75	34	4275-34-4374	318420	1058561	301
42	75	34	4275-34-4375	318112	1059860	301
42	75	34	4275-34-4376	318085	1059730	402
42	75	34	4275-34-4377	318275	1060215	802
42	75	34	4275-34-4380	315600	1060540	300
42	75	34	4275-34-4381	315800	1060540	805
42	75	34	4275-34-4383	317110	1060350	400
42	75	34	4275-34-4384	317010	1060250	400
42	75	34	4275-34-4385	317110	1060150	401
42	75	34	4275-34-4386	317110	1059950	401
42	75	34	4275-34-4387	317010	1059950	400
42	75	34	4275-34-4388	316925	1059500	804
42	75	34	4275-34-4389	318240	1059925	803
42	75	34	4275-34-4390	318418	1058262	299
42	75	34	4275-34-4391	318015	1057956	302
42	75	34	4275-34-4392	317378	1059256	400
42	75	34	4275-34-4396	317150	1060450	404
42	75	34	4275-34-4397	317500	1060065	403
42	75	34	4275-34-4398	318185	1059730	402
42	75	34	4275-34-4399	318320	1059255	401
42	75	34	4275-34-4400	318420	1059155	401
42	75	34	4275-34-4401	318420	1058960	402
42	75	34	4275-34-4403	317400	1059799	402
42	75	34	4275-34-4404	318250	1059641	402
42	75	34	4275-34-4405	318370	1059060	401
42	75	34	4275-34-4406	318500	1058610	401
42	75	34	4275-34-4407	318415	1058050	801
42	75	34	4275-34-4408	317918	1057755	303
42	75	34	4275-34-4409	317710	1057755	302
42	75	34	4275-34-4410	318415	1057525	803
42	75	34	4275-34-4411	318515	1060000	800
42	75	34	4275-34-4412	318640	1059750	802
42	75	34	4275-34-4413	318810	1059440	808
42	75	34	4275-34-4414	318515	1059400	808
42	75	34	4275-34-4415	318620	1059255	806

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-4416	318520	1059155	402
42	75	34	4275-34-4417	318470	1059060	402
42	75	34	4275-34-4418	318520	1058960	402
42	75	34	4275-34-4419	318420	1058750	365
42	75	34	4275-34-KM1	315656	1059616	958
42	75	34	4275-34-KM2	318362	1059614	970
42	75	34	4275-34-KM3	316030	1059399	400
42	75	34	4275-34-KM4	316616	1059376	400
42	75	34	4275-34-KM5	317226	1059320	400
42	75	34	4275-34-KM6	317808	1059350	400
42	75	34	4275-34-KM7	318110	1059631	400
42	75	34	4275-34-KM8	318732	1059583	400
42	75	34	4275-34-KM9	318408	1059897	400
42	75	34	4275-34-KM10	318397	1059305	400
42	75	34	4275-34-KM11	315751	1060701	400
42	75	34	4275-34-KM12	318003	1059631	400
42	75	34	4275-34-KM13	317895	1059630	400
42	75	34	4275-34-KM14	318209	1059309	400
42	75	34	4275-34-KM15	317997	1059308	400
42	75	34	4275-34-KM16	318141	1059915	400
42	75	34	4275-34-KM17	317853	1059917	400
42	75	34	4275-34-KM18	317723	1060509	400
42	75	34	4275-34-KM19	317588	1058713	400
42	75	34	4275-34-KM20	318030	1058708	400
42	75	34	4275-34-KM21	318000	1059363	400
42	75	34	4275-34-KM22	317949	1059315	400
42	75	34	4275-34-KM23	317995	1059260	400
42	75	34	4275-34-KM24	318133	1060515	400
42	75	34	4275-34-KM25	317624	1059919	400
42	75	34	4275-34-KM26	317950	1059266	400
42	75	34	4275-34-KM27	318035	1060514	400
42	75	34	4275-34-KM28	318027	1058762	400
42	75	34	4275-34-KM29	317979	1058711	400
42	75	34	4275-34-KM30	318040	1058657	400
42	75	34	4275-34-KM31	317893	1059262	400
42	75	34	4275-34-KM32	317951	1059163	400
42	75	34	4275-34-KM33	318086	1060514	400
42	75	34	4275-34-KM34	317811	1058984	400
42	75	34	4275-34-KM35	318016	1058992	400
42	75	34	4275-34-KM36	317915	1058984	400
42	75	34	4275-34-KM37	318123	1058385	400
42	75	34	4275-34-KM38	318020	1058387	400
42	75	34	4275-34-KM39	317920	1058385	400
42	75	34	4275-34-KM40	318207	1058107	400
42	75	34	4275-34-KM41	318020	1058097	400
42	75	34	4275-34-KM42	317816	1058083	400
42	75	34	4275-34-KM43	318127	1060203	400
42	75	34	4275-34-KM44	318037	1060199	400
42	75	34	4275-34-KM45	317924	1060196	400
42	75	34	4275-34-KM46	318077	1060604	400
42	75	34	4275-34-KM47	317981	1060514	400

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	34	4275-34-KM48	317715	1058982	400
42	75	34	4275-34-MW-3	317949	1060552	318
42	75	34	4275-34-MW-4	318699	1056282	219
42	75	34	4275-34-MW-8	317925	1057973	219
42	75	34	4275-34-MW-9	317102	1059208	277
42	75	34	4275-34-OMW-3	317939	1060553	249
42	75	34	4275-34-OMW-4	318689	1056283	120
42	75	34	4275-34-UMW-3	317960	1060551	379
42	75	34	4275-34-UMW-4	318709	1056283	298
42	75	35	4275-35-1	322665	1058014	785
42	75	35	4275-35-2	325296	1057941	800
42	75	35	4275-35-3	321349	1058036	400
42	75	35	4275-35-4	320141	1057618	400
42	75	35	4275-35-5	321336	1057619	400
42	75	35	4275-35-6	321324	1060450	400
42	75	35	4275-35-7	320929	1060248	400
42	75	35	4275-35-8	321724	1059451	400
42	75	35	4275-35-9	321327	1058848	400
42	75	35	4275-35-10	320529	1059248	400
42	75	35	4275-35-11	321725	1058052	400
42	75	35	4275-35-12	320925	1057651	400
42	75	35	4275-35-13	320184	1057233	400
42	75	35	4275-35-14	321725	1058852	400
42	75	35	4275-35-15	322124	1058054	400
42	75	35	4275-35-16	322124	1058454	400
42	75	35	4275-35-17	322123	1058845	400
42	75	35	4275-35-18	322525	1058458	400
42	75	35	4275-35-19	322524	1057653	400
42	75	35	4275-35-20	322125	1057653	400
42	75	35	4275-35-21	320927	1057270	400
42	75	35	4275-35-22	320527	1057249	400
42	75	35	4275-35-23	320526	1057652	400
42	75	35	4275-35-24	320527	1060449	400
42	75	35	4275-35-25	320930	1059049	400
42	75	35	4275-35-26	320929	1059849	400
42	75	35	4275-35-27	320910	1060451	400
42	75	35	4275-35-28	320528	1060049	400
42	75	35	4275-35-29	320530	1059648	400
42	75	35	4275-35-30	320526	1058051	400
42	75	35	4275-35-31	320524	1057851	400
42	75	35	4275-35-32	320724	1057851	400
42	75	35	4275-35-33	320927	1057851	400
42	75	35	4275-35-34	321125	1057852	400
42	75	35	4275-35-35	321326	1057852	400
42	75	35	4275-35-36	321526	1057852	400
42	75	35	4275-35-37	321725	1057852	400
42	75	35	4275-35-38	321926	1057853	400
42	75	35	4275-35-39	322125	1057853	400
42	75	35	4275-35-40	322325	1057854	400
42	75	35	4275-35-41	320326	1057651	400
42	75	35	4275-35-42	320719	1057650	400

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-43	321127	1057652	400
42	75	35	4275-35-44	321725	1057652	400
42	75	35	4275-35-45	320128	1057451	400
42	75	35	4275-35-46	320326	1057451	400
42	75	35	4275-35-47	320524	1057452	400
42	75	35	4275-35-48	320721	1057450	400
42	75	35	4275-35-49	320926	1057452	400
42	75	35	4275-35-50	321125	1057451	400
42	75	35	4275-35-51	322325	1058054	400
42	75	35	4275-35-52	322324	1058254	400
42	75	35	4275-35-53	322324	1058453	400
42	75	35	4275-35-54	322324	1058654	400
42	75	35	4275-35-55	322323	1058853	400
42	75	35	4275-35-56	322524	1058853	400
42	75	35	4275-35-57	322522	1059253	400
42	75	35	4275-35-58	322922	1060052	400
42	75	35	4275-35-59	323721	1060053	400
42	75	35	4275-35-60	323319	1060056	400
42	75	35	4275-35-61	322722	1059653	400
42	75	35	4275-35-62	322922	1059253	400
42	75	35	4275-35-63	322924	1058854	400
42	75	35	4275-35-64	320929	1057071	400
42	75	35	4275-35-65	321326	1057286	400
42	75	35	4275-35-66	323319	1060453	400
42	75	35	4275-35-67	323720	1060453	400
42	75	35	4275-35-68	323321	1059654	400
42	75	35	4275-35-69	322933	1058453	400
42	75	35	4275-35-70	320929	1056853	400
42	75	35	4275-35-71	321125	1057053	400
42	75	35	4275-35-72	320729	1057050	400
42	75	35	4275-35-73	320927	1057154	400
42	75	35	4275-35-74	321125	1057253	400
42	75	35	4275-35-75	323518	1059255	400
42	75	35	4275-35-76	323718	1059063	400
42	75	35	4275-35-77	323520	1058958	400
42	75	35	4275-35-78	320126	1057343	400
42	75	35	4275-35-79	323421	1058858	400
42	75	35	4275-35-80	320524	1057552	400
42	75	35	4275-35-81	320427	1057652	400
42	75	35	4275-35-82	323325	1058755	400
42	75	35	4275-35-83	323221	1058657	400
42	75	35	4275-35-84	323322	1058556	400
42	75	35	4275-35-85	323125	1058556	400
42	75	35	4275-35-86	320628	1057851	400
42	75	35	4275-35-87	320827	1057851	400
42	75	35	4275-35-88	323222	1058454	400
42	75	35	4275-35-89	323222	1058599	400
42	75	35	4275-35-90	323813	1058457	400
42	75	35	4275-35-91	325327	1060516	400
42	75	35	4275-35-92	325310	1058439	400
42	75	35	4275-35-93	323323	1058856	400

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-94	323320	1059254	400
42	75	35	4275-35-95	323925	1059455	400
42	75	35	4275-35-96	324518	1059658	400
42	75	35	4275-35-97	324520	1060054	400
42	75	35	4275-35-98	322924	1058252	400
42	75	35	4275-35-99	323520	1058857	400
42	75	35	4275-35-100	323322	1058451	400
42	75	35	4275-35-101	323124	1058656	400
42	75	35	4275-35-102	322724	1058253	400
42	75	35	4275-35-103	323720	1059256	400
42	75	35	4275-35-104	323323	1058656	293
42	75	35	4275-35-105	323122	1058454	400
42	75	35	4275-35-106	323124	1058253	400
42	75	35	4275-35-107	322824	1058153	275
42	75	35	4275-35-108	322525	1058254	400
42	75	35	4275-35-109	323322	1059056	400
42	75	35	4275-35-110	323524	1059059	400
42	75	35	4275-35-111	322426	1058053	400
42	75	35	4275-35-112	322225	1057954	400
42	75	35	4275-35-113	322324	1057953	400
42	75	35	4275-35-114	322125	1057954	232
42	75	35	4275-35-115	322225	1057851	215
42	75	35	4275-35-116	322027	1057851	400
42	75	35	4275-35-117	321925	1057950	400
42	75	35	4275-35-118	321826	1057851	400
42	75	35	4275-35-119	321928	1057751	232
42	75	35	4275-35-120	321725	1057952	400
42	75	35	4275-35-121	321725	1057752	234
42	75	35	4275-35-122	322127	1057752	218
42	75	35	4275-35-123	322327	1057758	400
42	75	35	4275-35-124	321626	1057651	237
42	75	35	4275-35-125	321824	1057652	400
42	75	35	4275-35-126	321726	1057452	400
42	75	35	4275-35-127	322924	1058353	244
42	75	35	4275-35-128	323026	1058351	400
42	75	35	4275-35-129	322922	1058151	275
42	75	35	4275-35-130	322820	1058254	287
42	75	35	4275-35-131	322723	1058151	275
42	75	35	4275-35-132	321624	1057755	400
42	75	35	4275-35-133	321826	1057754	400
42	75	35	4275-35-134	321726	1057551	400
42	75	35	4275-35-135	321924	1057653	400
42	75	35	4275-35-136	322027	1057954	400
42	75	35	4275-35-137	322423	1057951	400
42	75	35	4275-35-138	322626	1058254	400
42	75	35	4275-35-139	322624	1058154	400
42	75	35	4275-35-140	321625	1057851	400
42	75	35	4275-35-141	322525	1058153	400
42	75	35	4275-35-142	323125	1058355	400
42	75	35	4275-35-143	323026	1058453	400
42	75	35	4275-35-144	323024	1058253	400

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-145	322824	1058353	400
42	75	35	4275-35-146	322724	1058102	400
42	75	35	4275-35-147	322823	1058102	400
42	75	35	4275-35-148	322924	1058101	400
42	75	35	4275-35-149	322724	1058203	400
42	75	35	4275-35-150	322923	1058301	400
42	75	35	4275-35-151	322924	1058201	400
42	75	35	4275-35-152	322823	1058202	400
42	75	35	4275-35-153	323225	1058505	400
42	75	35	4275-35-154	323321	1058507	400
42	75	35	4275-35-155	323322	1058606	400
42	75	35	4275-35-156	322327	1057803	400
42	75	35	4275-35-157	322275	1057853	400
42	75	35	4275-35-158	322176	1057852	400
42	75	35	4275-35-159	322027	1057751	400
42	75	35	4275-35-160	322075	1057852	400
42	75	35	4275-35-161	322524	1058051	400
42	75	35	4275-35-162	322524	1057951	400
42	75	35	4275-35-163	322873	1058200	400
42	75	35	4275-35-164	323420	1058955	400
42	75	35	4275-35-165	323221	1058756	400
42	75	35	4275-35-166	323421	1058757	400
42	75	35	4275-35-167	323420	1058657	400
42	75	35	4275-35-168	323419	1058556	400
42	75	35	4275-35-169	323420	1058458	400
42	75	35	4275-35-170	323324	1058357	400
42	75	35	4275-35-171	323226	1058355	400
42	75	35	4275-35-172	323022	1058150	400
42	75	35	4275-35-173	322922	1058052	400
42	75	35	4275-35-174	322825	1058052	400
42	75	35	4275-35-175	322423	1058152	400
42	75	35	4275-35-176	322424	1057852	400
42	75	35	4275-35-177	322219	1057750	400
42	75	35	4275-35-178	322226	1058054	400
42	75	35	4275-35-179	321811	1057553	400
42	75	35	4275-35-180	321627	1057551	400
42	75	35	4275-35-181	321526	1057652	400
42	75	35	4275-35-182	320330	1057346	400
42	75	35	4275-35-183	320425	1057450	400
42	75	35	4275-35-184	320725	1057551	400
42	75	35	4275-35-185	320926	1057551	400
42	75	35	4275-35-186	321023	1057651	400
42	75	35	4275-35-187	321030	1057855	400
42	75	35	4275-35-188	321325	1057752	400
42	75	35	4275-35-189	322623	1058052	400
42	75	35	4275-35-190C	322899	1058176	289
42	75	35	4275-35-191C	322897	1058126	275
42	75	35	4275-35-192C	322901	1058227	264
42	75	35	4275-35-193C	322902	1058277	289
42	75	35	4275-35-194C	322905	1058326	314
42	75	35	4275-35-195C	322904	1058377	316

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-196C	322896	1058076	275
42	75	35	4275-35-197C	322894	1058026	274
42	75	35	4275-35-198	320729	1056850	400
42	75	35	4275-35-199	320929	1056954	400
42	75	35	4275-35-200	320828	1057051	400
42	75	35	4275-35-201	320625	1057751	400
42	75	35	4275-35-202	320726	1057751	400
42	75	35	4275-35-203	320825	1057750	400
42	75	35	4275-35-204	320724	1057952	400
42	75	35	4275-35-205	321224	1057751	400
42	75	35	4275-35-206	321423	1057751	400
42	75	35	4275-35-207	321327	1057051	400
42	75	35	4275-35-208	321526	1057249	400
42	75	35	4275-35-209	321725	1057354	400
42	75	35	4275-35-210	321526	1057450	400
42	75	35	4275-35-211	321821	1057455	400
42	75	35	4275-35-212	321922	1057551	400
42	75	35	4275-35-213	322022	1057553	400
42	75	35	4275-35-214	322026	1057655	400
42	75	35	4275-35-215	322225	1057651	400
42	75	35	4275-35-216	322329	1057651	400
42	75	35	4275-35-217	322425	1057755	400
42	75	35	4275-35-218	322526	1057851	400
42	75	35	4275-35-219	322625	1057951	400
42	75	35	4275-35-220	321826	1057945	400
42	75	35	4275-35-221	322023	1058054	400
42	75	35	4275-35-222	322225	1058154	400
42	75	35	4275-35-223	322324	1058155	400
42	75	35	4275-35-224	322724	1057950	400
42	75	35	4275-35-225	322824	1057950	400
42	75	35	4275-35-226	322924	1057949	400
42	75	35	4275-35-227	323019	1058054	400
42	75	35	4275-35-228	322724	1058354	400
42	75	35	4275-35-229	322726	1058454	400
42	75	35	4275-35-230	322922	1058657	400
42	75	35	4275-35-231	323027	1058556	400
42	75	35	4275-35-232	323023	1058656	400
42	75	35	4275-35-233	323124	1058755	400
42	75	35	4275-35-234	323224	1058856	400
42	75	35	4275-35-235	323323	1058956	400
42	75	35	4275-35-236	323422	1059058	400
42	75	35	4275-35-237	323516	1059158	400
42	75	35	4275-35-238	323620	1059255	400
42	75	35	4275-35-239	323622	1059158	400
42	75	35	4275-35-240	323622	1059059	400
42	75	35	4275-35-241	323621	1058958	400
42	75	35	4275-35-242	323620	1058660	400
42	75	35	4275-35-243	323522	1059455	400
42	75	35	4275-35-244	323521	1059653	400
42	75	35	4275-35-245	323721	1059855	400
42	75	35	4275-35-246	323920	1060253	400

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-247	321627	1057451	400
42	75	35	4275-35-248	323223	1058955	400
42	75	35	4275-35-249	323123	1058855	400
42	75	35	4275-35-250	322927	1058554	800
42	75	35	4275-35-251	322824	1058453	400
42	75	35	4275-35-252	322725	1058553	400
42	75	35	4275-35-253	322627	1058454	400
42	75	35	4275-35-254	322625	1058354	400
42	75	35	4275-35-255	323119	1058058	400
42	75	35	4275-35-256	323024	1057950	400
42	75	35	4275-35-257	322920	1057852	760
42	75	35	4275-35-258	322825	1057850	400
42	75	35	4275-35-259	322724	1057850	400
42	75	35	4275-35-260	322623	1057850	400
42	75	35	4275-35-261	322527	1057750	400
42	75	35	4275-35-262	322432	1057652	400
42	75	35	4275-35-263	322330	1057551	400
42	75	35	4275-35-264	322232	1057551	760
42	75	35	4275-35-265	321922	1057451	400
42	75	35	4275-35-266	321825	1057356	400
42	75	35	4275-35-267	321726	1057253	400
42	75	35	4275-35-268	321625	1057350	400
42	75	35	4275-35-269	321426	1057447	400
42	75	35	4275-35-270	321526	1057548	400
42	75	35	4275-35-271	321524	1057753	400
42	75	35	4275-35-272	321623	1057953	400
42	75	35	4275-35-273	321827	1058047	400
42	75	35	4275-35-274	321925	1058052	400
42	75	35	4275-35-275	322025	1058153	400
42	75	35	4275-35-276	320324	1056852	400
42	75	35	4275-35-277	320527	1056454	400
42	75	35	4275-35-278	323422	1059157	760
42	75	35	4275-35-279	322124	1058152	400
42	75	35	4275-35-280	321520	1057952	400
42	75	35	4275-35-281	321526	1057349	400
42	75	35	4275-35-282	322724	1058050	400
42	75	35	4275-35-283	323219	1058059	400
42	75	35	4275-35-284	323125	1057949	400
42	75	35	4275-35-285	323023	1057850	400
42	75	35	4275-35-286	323122	1057850	400
42	75	35	4275-35-287	323124	1058154	400
42	75	35	4275-35-288	322624	1057751	400
42	75	35	4275-35-289	322724	1057749	400
42	75	35	4275-35-290	322822	1057752	400
42	75	35	4275-35-291	322924	1057748	400
42	75	35	4275-35-292	323022	1057748	400
42	75	35	4275-35-293	322430	1057554	400
42	75	35	4275-35-294	322332	1057451	400
42	75	35	4275-35-295	322230	1057450	400
42	75	35	4275-35-296	322122	1057553	400
42	75	35	4275-35-297	321919	1057354	400

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-298	321813	1057255	400
42	75	35	4275-35-299	321724	1057154	400
42	75	35	4275-35-300	321622	1057253	400
42	75	35	4275-35-301	321924	1058154	400
42	75	35	4275-35-302	323320	1059158	400
42	75	35	4275-35-303	323420	1059257	400
42	75	35	4275-35-304	323224	1057949	400
42	75	35	4275-35-305	322928	1057650	400
42	75	35	4275-35-306	322829	1057650	400
42	75	35	4275-35-307	322729	1057650	400
42	75	35	4275-35-308	322628	1057651	400
42	75	35	4275-35-309	322430	1057455	400
42	75	35	4275-35-310	322334	1057352	400
42	75	35	4275-35-311	322234	1057352	400
42	75	35	4275-35-312	322119	1057462	400
42	75	35	4275-35-313	322020	1057358	400
42	75	35	4275-35-314	322018	1057257	400
42	75	35	4275-35-315	321919	1057256	400
42	75	35	4275-35-316	321832	1057154	400
42	75	35	4275-35-317	321725	1057054	400
42	75	35	4275-35-318	321626	1057151	400
42	75	35	4275-35-319	322020	1057453	400
42	75	35	4275-35-320	322120	1057364	400
42	75	35	4275-35-321	321932	1057155	400
42	75	35	4275-35-322	321836	1057053	400
42	75	35	4275-35-323	321326	1056653	400
42	75	35	4275-35-324	320926	1056451	400
42	75	35	4275-35-325	321626	1056953	400
42	75	35	4275-35-326	321725	1056951	400
42	75	35	4275-35-327	321827	1056954	400
42	75	35	4275-35-328	321926	1057052	400
42	75	35	4275-35-329	321624	1057052	400
42	75	35	4275-35-330	322028	1057152	400
42	75	35	4275-35-331	322121	1057250	400
42	75	35	4275-35-332	323222	1057853	400
42	75	35	4275-35-333	322927	1057546	400
42	75	35	4275-35-334	322823	1057551	400
42	75	35	4275-35-335	322724	1057550	400
42	75	35	4275-35-336	322623	1057552	400
42	75	35	4275-35-337	322521	1057527	400
42	75	35	4275-35-338	321524	1056951	400
42	75	35	4275-35-339	322025	1057052	400
42	75	35	4275-35-340	321926	1056954	400
42	75	35	4275-35-341	321526	1057055	400
42	75	35	4275-35-342	321525	1056852	400
42	75	35	4275-35-343	321626	1056852	400
42	75	35	4275-35-344	321725	1056853	400
42	75	35	4275-35-345	321827	1056852	400
42	75	35	4275-35-346	321925	1056853	400
42	75	35	4275-35-347	322025	1056954	400
42	75	35	4275-35-348	322924	1057453	400

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-349	322825	1057451	400
42	75	35	4275-35-350	322724	1057453	400
42	75	35	4275-35-351	322624	1057454	400
42	75	35	4275-35-352	322524	1057454	400
42	75	35	4275-35-353	321424	1056852	400
42	75	35	4275-35-354	321425	1056753	400
42	75	35	4275-35-355	321526	1056752	400
42	75	35	4275-35-356	321625	1056753	400
42	75	35	4275-35-357	321725	1056753	400
42	75	35	4275-35-358	321826	1056754	400
42	75	35	4275-35-359	322623	1057351	400
42	75	35	4275-35-360	322724	1057354	400
42	75	35	4275-35-361	322824	1057352	400
42	75	35	4275-35-362	322523	1057349	400
42	75	35	4275-35-363	321528	1056653	400
42	75	35	4275-35-364	321627	1056654	400
42	75	35	4275-35-365	321731	1056653	400
42	75	35	4275-35-366	321428	1056653	400
42	75	35	4275-35-367	325321	1055452	700
42	75	35	4275-35-368	325343	1059499	760
42	75	35	4275-35-369	323521	1058759	400
42	75	35	4275-35-370	323520	1058659	400
42	75	35	4275-35-371	323522	1058558	400
42	75	35	4275-35-372	321423	1057851	400
42	75	35	4275-35-373	321529	1056553	400
42	75	35	4275-35-374	321622	1056554	400
42	75	35	4275-35-375	320726	1056952	400
42	75	35	4275-35-376	320628	1057049	400
42	75	35	4275-35-377	320627	1056947	400
42	75	35	4275-35-378	320425	1057256	400
42	75	35	4275-35-379	320326	1057246	400
42	75	35	4275-35-380	320537	1056039	400
42	75	35	4275-35-381	324246	1056708	698
42	75	35	4275-35-382	325325	1056657	700
42	75	35	4275-35-383	324624	1057104	400
42	75	35	4275-35-384	324642	1056702	700
42	75	35	4275-35-385	323174	1058656	274
42	75	35	4275-35-386	323124	1058606	276
42	75	35	4275-35-387	323222	1058606	276
42	75	35	4275-35-388	323123	1058504	271
42	75	35	4275-35-389	322977	1058450	277
42	75	35	4275-35-390	323123	1058405	258
42	75	35	4275-35-391	323076	1058352	256
42	75	35	4275-35-392	323074	1058252	250
42	75	35	4275-35-393	323023	1058203	250
42	75	35	4275-35-394	322972	1058151	250
42	75	35	4275-35-395	323018	1058101	258
42	75	35	4275-35-396	322724	1058000	237
42	75	35	4275-35-397	322624	1058002	233
42	75	35	4275-35-398	322374	1058053	216
42	75	35	4275-35-399	322269	1058051	216

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-400	322175	1058054	214
42	75	35	4275-35-401	322175	1057953	216
42	75	35	4275-35-402	322374	1057951	217
42	75	35	4275-35-403	322474	1057951	214
42	75	35	4275-35-404	322525	1057901	237
42	75	35	4275-35-405	322572	1057853	218
42	75	35	4275-35-406	322474	1057851	204
42	75	35	4275-35-407	322376	1057853	217
42	75	35	4275-35-408	321827	1057802	216
42	75	35	4275-35-409	321877	1057752	213
42	75	35	4275-35-410	322075	1057752	235
42	75	35	4275-35-411	322171	1057752	215
42	75	35	4275-35-412	322272	1057754	217
42	75	35	4275-35-413	322475	1057755	217
42	75	35	4275-35-414	322721	1057802	237
42	75	35	4275-35-415	322772	1057749	232
42	75	35	4275-35-416	322874	1057751	238
42	75	35	4275-35-417	322879	1057653	235
42	75	35	4275-35-418	322571	1057653	217
42	75	35	4275-35-419	322469	1057653	218
42	75	35	4275-35-420	322525	1057702	218
42	75	35	4275-35-421	322428	1057705	213
42	75	35	4275-35-422	322380	1057652	213
42	75	35	4275-35-423	322275	1057642	212
42	75	35	4275-35-424	322175	1057651	211
42	75	35	4275-35-425	322075	1057654	238
42	75	35	4275-35-426	321825	1057702	214
42	75	35	4275-35-427	321924	1057601	216
42	75	35	4275-35-428	321769	1057552	216
42	75	35	4275-35-429	321863	1057552	217
42	75	35	4275-35-430	322674	1057551	216
42	75	35	4275-35-431	322774	1057550	233
42	75	35	4275-35-432	322874	1057549	237
42	75	35	4275-35-433	321873	1057453	215
42	75	35	4275-35-434	321917	1057405	215
42	75	35	4275-35-435	321832	1057105	216
42	75	35	4275-35-436	321724	1057104	216
42	75	35	4275-35-437	321781	1057053	217
42	75	35	4275-35-438	321881	1057052	217
42	75	35	4275-35-439	321830	1057002	218
42	75	35	4275-35-440	321879	1056953	216
42	75	35	4275-35-441	321778	1057153	211
42	75	35	4275-35-442	321777	1057252	218
42	75	35	4275-35-443	321724	1057405	217
42	75	35	4275-35-444	321721	1057602	218
42	75	35	4275-35-445	321978	1057951	233
42	75	35	4275-35-446	322072	1058048	216
42	75	35	4275-35-447	323174	1058557	276
42	75	35	4275-35-448	323173	1058454	273
42	75	35	4275-35-449	322674	1058000	236
42	75	35	4275-35-450	322571	1058005	237

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-451	322527	1057801	235
42	75	35	4275-35-452	322424	1057803	213
42	75	35	4275-35-453	322729	1057604	217
42	75	35	4275-35-454	322474	1057546	217
42	75	35	4275-35-455	322525	1057606	247
42	75	35	4275-35-456	322323	1057898	217
42	75	35	4275-35-457	322240	1057905	217
42	75	35	4275-35-458	321925	1057901	215
42	75	35	4275-35-459	321925	1058005	218
42	75	35	4275-35-460	322217	1058018	215
42	75	35	4275-35-461	322420	1058004	217
42	75	35	4275-35-462	322421	1057899	213
42	75	35	4275-35-463	322378	1057754	210
42	75	35	4275-35-464	322327	1057705	218
42	75	35	4275-35-465	322225	1057703	218
42	75	35	4275-35-466	322030	1057705	200
42	75	35	4275-35-467	322123	1058004	213
42	75	35	4275-35-468	322127	1057903	212
42	75	35	4275-35-469	322327	1058003	200
42	75	35	4275-35-470	321769	1057601	217
42	75	35	4275-35-471	321818	1057603	216
42	75	35	4275-35-472	321873	1057602	216
42	75	35	4275-35-473	321771	1057502	216
42	75	35	4275-35-474	321867	1057500	217
42	75	35	4275-35-475	321819	1057500	215
42	75	35	4275-35-476	321773	1057751	210
42	75	35	4275-35-477	322623	1057600	215
42	75	35	4275-35-478	322573	1057603	210
42	75	35	4275-35-479	322622	1057702	216
42	75	35	4275-35-480	322573	1057701	217
42	75	35	4275-35-481	322476	1057702	216
42	75	35	4275-35-482	322575	1057801	198
42	75	35	4275-35-483	322475	1057802	203
42	75	35	4275-35-484	322376	1057803	217
42	75	35	4275-35-485	322375	1057901	217
42	75	35	4275-35-486	322624	1058102	250
42	75	35	4275-35-487	322672	1058105	250
42	75	35	4275-35-488	322677	1057599	216
42	75	35	4275-35-489	322776	1057600	210
42	75	35	4275-35-490	322826	1057601	216
42	75	35	4275-35-491	322774	1057652	217
42	75	35	4275-35-492	322679	1057652	217
42	75	35	4275-35-493	322677	1057699	217
42	75	35	4275-35-494	322728	1057699	209
42	75	35	4275-35-495	322777	1057699	216
42	75	35	4275-35-496	322828	1057700	217
42	75	35	4275-35-497	322877	1057698	214
42	75	35	4275-35-498	322673	1057751	214
42	75	35	4275-35-499	322573	1057751	217
42	75	35	4275-35-500	322619	1057800	217
42	75	35	4275-35-501	322674	1057801	213

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-502	322674	1057951	218
42	75	35	4275-35-503	322522	1058005	216
42	75	35	4275-35-504	322471	1058005	214
42	75	35	4275-35-505	322474	1058052	215
42	75	35	4275-35-506	321779	1057003	210
42	75	35	4275-35-507	321881	1057003	216
42	75	35	4275-35-508	321929	1057104	215
42	75	35	4275-35-509	321880	1057104	217
42	75	35	4275-35-510	321778	1057104	216
42	75	35	4275-35-511	321885	1057153	216
42	75	35	4275-35-512	321926	1057204	216
42	75	35	4275-35-513	321878	1057204	217
42	75	35	4275-35-514	321825	1057211	216
42	75	35	4275-35-515	321779	1057203	216
42	75	35	4275-35-516	321873	1057254	216
42	75	35	4275-35-517	321919	1057305	217
42	75	35	4275-35-518	321871	1057406	200
42	75	35	4275-35-519	321819	1057412	217
42	75	35	4275-35-520	321773	1057457	210
42	75	35	4275-35-521	322074	1058007	212
42	75	35	4275-35-522	321927	1057702	215
42	75	35	4275-35-523	321876	1057703	217
42	75	35	4275-35-524	322175	1057703	214
42	75	35	4275-35-525	322187	1057806	212
42	75	35	4275-35-526	322177	1057901	215
42	75	35	4275-35-527	322073	1057707	216
42	75	35	4275-35-528C	322892	1057976	253
42	75	35	4275-35-529C	321720	1057010	216
42	75	35	4275-35-530C	322573	1057553	202
42	75	35	4275-35-531C	323074	1058454	274
42	75	35	4275-35-532C	321726	1057303	237
42	75	35	4275-35-533C	321979	1057704	206
42	75	35	4275-35-534C	322577	1058051	233
42	75	35	4275-35-535C	321828	1057304	217
42	75	35	4275-35-536C	321777	1057303	217
42	75	35	4275-35-537C	323027	1058504	295
42	75	35	4275-35-538C	322574	1058153	237
42	75	35	4275-35-539C	322575	1058104	231
42	75	35	4275-35-540C	321979	1057755	212
42	75	35	4275-35-541C	323273	1058505	276
42	75	35	4275-35-542C	321875	1057305	214
42	75	35	4275-35-543C	323023	1057901	214
42	75	35	4275-35-544C	323272	1058555	275
42	75	35	4275-35-545C	323272	1058607	270
42	75	35	4275-35-546C	322986	1058560	292
42	75	35	4275-35-547C	321977	1057803	216
42	75	35	4275-35-548C	322574	1058206	233
42	75	35	4275-35-549C	322971	1057901	232
42	75	35	4275-35-550C	321978	1057902	212
42	75	35	4275-35-551C	323273	1058656	276
42	75	35	4275-35-552C	323271	1058452	271

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-553C	322575	1058253	233
42	75	35	4275-35-554C	321981	1057654	214
42	75	35	4275-35-555C	323073	1057903	255
42	75	35	4275-35-556C	321975	1058004	212
42	75	35	4275-35-557C	322774	1057801	229
42	75	35	4275-35-558	322826	1057800	225
42	75	35	4275-35-559C	321974	1058052	205
42	75	35	4275-35-560C	322925	1057797	248
42	75	35	4275-35-561	320121	1057059	400
42	75	35	4275-35-562	320320	1057046	258
42	75	35	4275-35-563	320321	1056649	238
42	75	35	4275-35-564	320718	1056649	238
42	75	35	4275-35-565	320920	1056059	400
42	75	35	4275-35-566	320072	1055659	400
42	75	35	4275-35-567	320519	1055658	400
42	75	35	4275-35-568C	321981	1057603	237
42	75	35	4275-35-569C	322576	1058317	400
42	75	35	4275-35-570C	322907	1058427	297
42	75	35	4275-35-571C	322575	1058353	237
42	75	35	4275-35-572C	322925	1058607	299
42	75	35	4275-35-573C	322909	1058477	216
42	75	35	4275-35-574C	322903	1058526	400
42	75	35	4275-35-575C	322573	1058403	214
42	75	35	4275-35-576C	322872	1058660	215
42	75	35	4275-35-577C	321973	1058101	400
42	75	35	4275-35-578C	321671	1057802	254
42	75	35	4275-35-579C	321877	1057808	400
42	75	35	4275-35-580C	322125	1057808	207
42	75	35	4275-35-581C	322275	1057808	208
42	75	35	4275-35-582C	322275	1057953	204
42	75	35	4275-35-583C	321840	1057527	216
42	75	35	4275-35-584C	321968	1057306	212
42	75	35	4275-35-585C	321908	1057129	215
42	75	35	4275-35-586C	321731	1056903	215
42	75	35	4275-35-587C	321725	1056803	214
42	75	35	4275-35-588C	322573	1057902	234
42	75	35	4275-35-589C	322726	1057902	229
42	75	35	4275-35-590C	322873	1057900	253
42	75	35	4275-35-591C	322724	1057501	214
42	75	35	4275-35-592C	322773	1058354	253
42	75	35	4275-35-593C	323074	1058202	251
42	75	35	4275-35-594C	323123	1058704	276
42	75	35	4275-35-595	323072	1058656	269
42	75	35	4275-35-596	323373	1058454	274
42	75	35	4275-35-597	323324	1058403	275
42	75	35	4275-35-598	323371	1058556	278
42	75	35	4275-35-599	323123	1058302	297
42	75	35	4275-35-600	322874	1058454	273
42	75	35	4275-35-601	323123	1058107	274
42	75	35	4275-35-602	323169	1058059	252
42	75	35	4275-35-603	323177	1057947	252

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-604	323124	1057897	251
42	75	35	4275-35-605	323072	1057850	231
42	75	35	4275-35-606	322927	1057698	215
42	75	35	4275-35-607	322824	1057501	214
42	75	35	4275-35-608	322723	1057401	195
42	75	35	4275-35-609	322622	1057405	193
42	75	35	4275-35-610	322478	1057455	198
42	75	35	4275-35-611	322525	1058203	400
42	75	35	4275-35-612	322473	1058155	236
42	75	35	4275-35-613	322229	1058099	204
42	75	35	4275-35-614	322024	1058102	212
42	75	35	4275-35-615	321873	1058049	214
42	75	35	4275-35-616	321875	1057947	213
42	75	35	4275-35-617	321825	1057898	217
42	75	35	4275-35-618	321725	1057905	213
42	75	35	4275-35-619	321625	1057901	206
42	75	35	4275-35-620	321524	1057901	212
42	75	35	4275-35-621	321474	1057850	215
42	75	35	4275-35-622	321524	1057702	214
42	75	35	4275-35-623	321576	1057651	211
42	75	35	4275-35-624	321627	1057601	213
42	75	35	4275-35-625	321677	1057500	212
42	75	35	4275-35-626	321675	1057351	214
42	75	35	4275-35-627	321676	1057254	214
42	75	35	4275-35-628	321674	1057149	213
42	75	35	4275-35-629	321623	1057100	212
42	75	35	4275-35-630	321576	1057053	215
42	75	35	4275-35-631	321576	1056952	214
42	75	35	4275-35-632	321474	1056852	212
42	75	35	4275-35-633	321475	1056753	214
42	75	35	4275-35-634	321527	1056701	215
42	75	35	4275-35-635	321776	1056755	215
42	75	35	4275-35-636	321876	1056850	212
42	75	35	4275-35-637	321874	1056904	215
42	75	35	4275-35-638	321976	1057051	213
42	75	35	4275-35-639	321979	1057151	212
42	75	35	4275-35-640	321675	1057303	216
42	75	35	4275-35-641	321675	1057199	216
42	75	35	4275-35-642	321674	1057098	214
42	75	35	4275-35-643	321575	1057005	215
42	75	35	4275-35-644	321525	1056912	400
42	75	35	4275-35-645	321870	1056800	212
42	75	35	4275-35-646	321923	1057002	210
42	75	35	4275-35-647	321976	1057102	213
42	75	35	4275-35-648	322383	1057454	194
42	75	35	4275-35-649	322379	1057547	198
42	75	35	4275-35-650	322480	1057506	197
42	75	35	4275-35-651	322530	1057399	193
42	75	35	4275-35-652	321826	1057994	400
42	75	35	4275-35-653	321873	1058000	209
42	75	35	4275-35-654	321676	1057653	217

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-655	321873	1058099	206
42	75	35	4275-35-656	321924	1058097	180
42	75	35	4275-35-657	322273	1058101	211
42	75	35	4275-35-658	323075	1058151	257
42	75	35	4275-35-659	321774	1057901	217
42	75	35	4275-35-660	321775	1057948	236
42	75	35	4275-35-661	323172	1058000	257
42	75	35	4275-35-662	323221	1058002	257
42	75	35	4275-35-663	321675	1057400	189
42	75	35	4275-35-664	322673	1057400	192
42	75	35	4275-35-665	322775	1057452	215
42	75	35	4275-35-666	322878	1057603	218
42	75	35	4275-35-667	322975	1057749	217
42	75	35	4275-35-668	323026	1057803	217
42	75	35	4275-35-669	322174	1058102	214
42	75	35	4275-35-670	322073	1058101	216
42	75	35	4275-35-671C	322427	1058105	233
42	75	35	4275-35-672C	323074	1058202	262
42	75	35	4275-35-673C	323038	1058606	282
42	75	35	4275-35-674C	321472	1057751	215
42	75	35	4275-35-675	321475	1057802	218
42	75	35	4275-35-676	321575	1057903	218
42	75	35	4275-35-677	321575	1057954	236
42	75	35	4275-35-678	321673	1057952	236
42	75	35	4275-35-679	321673	1057901	217
42	75	35	4275-35-680	321972	1057552	217
42	75	35	4275-35-681	321921	1057504	217
42	75	35	4275-35-682	321972	1057404	207
42	75	35	4275-35-683	321968	1057356	218
42	75	35	4275-35-684	322018	1057308	217
42	75	35	4275-35-685	321976	1057207	218
42	75	35	4275-35-686	322175	1057458	400
42	75	35	4275-35-687	322329	1057501	209
42	75	35	4275-35-688	322378	1057500	400
42	75	35	4275-35-689	322431	1057504	400
42	75	35	4275-35-690	322976	1057698	217
42	75	35	4275-35-691	323069	1057779	217
42	75	35	4275-35-692	323174	1057898	237
42	75	35	4275-35-693	323173	1058111	256
42	75	35	4275-35-694	323123	1058205	306
42	75	35	4275-35-695	323173	1058304	277
42	75	35	4275-35-696	323373	1058507	277
42	75	35	4275-35-697	323425	1058504	277
42	75	35	4275-35-698	323173	1058158	257
42	75	35	4275-35-699	323275	1058356	275
42	75	35	4275-35-700	323275	1058406	277
42	75	35	4275-35-701	323420	1058607	277
42	75	35	4275-35-702	323373	1058608	277
42	75	35	4275-35-703	323373	1058655	277
42	75	35	4275-35-704	323324	1058705	277
42	75	35	4275-35-705	323272	1058706	277

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-706	323221	1058707	277
42	75	35	4275-35-707	323170	1058700	271
42	75	35	4275-35-708	322979	1058609	282
42	75	35	4275-35-709	322824	1058402	257
42	75	35	4275-35-710	322725	1058403	274
42	75	35	4275-35-711	322675	1058303	256
42	75	35	4275-35-712	322626	1058304	255
42	75	35	4275-35-713	322477	1058205	255
42	75	35	4275-35-714	322376	1058105	214
42	75	35	4275-35-715	322325	1058105	214
42	75	35	4275-35-716	322273	1058157	215
42	75	35	4275-35-717	322173	1058155	235
42	75	35	4275-35-718	322123	1058105	217
42	75	35	4275-35-719	322075	1058154	234
42	75	35	4275-35-720	321975	1058154	237
42	75	35	4275-35-721	321475	1057901	217
42	75	35	4275-35-722	321423	1057802	216
42	75	35	4275-35-723	321474	1057701	217
42	75	35	4275-35-724	321579	1057597	215
42	75	35	4275-35-725	321628	1057502	216
42	75	35	4275-35-726	321627	1057400	213
42	75	35	4275-35-727	321572	1057450	211
42	75	35	4275-35-728	321677	1057452	217
42	75	35	4275-35-729	321575	1056653	215
42	75	35	4275-35-730	321678	1056655	214
42	75	35	4275-35-731	321776	1056706	214
42	75	35	4275-35-732	321828	1056702	216
42	75	35	4275-35-733	321877	1056754	215
42	75	35	4275-35-734	321927	1056901	217
42	75	35	4275-35-735	322020	1057200	213
42	75	35	4275-35-736	322070	1057300	176
42	75	35	4275-35-737	322066	1057360	217
42	75	35	4275-35-738	322119	1057413	218
42	75	35	4275-35-739	322067	1057412	215
42	75	35	4275-35-740	322020	1057407	217
42	75	35	4275-35-741	322069	1057461	213
42	75	35	4275-35-742	321970	1057453	218
42	75	35	4275-35-743	322120	1057510	209
42	75	35	4275-35-744	322070	1057506	216
42	75	35	4275-35-745	322019	1057505	216
42	75	35	4275-35-746	321970	1057501	218
42	75	35	4275-35-747	322070	1057556	215
42	75	35	4275-35-748	322072	1057604	215
42	75	35	4275-35-749	322122	1057603	212
42	75	35	4275-35-750	322170	1057605	217
42	75	35	4275-35-751	322120	1057700	214
42	75	35	4275-35-752	322275	1057706	209
42	75	35	4275-35-753	322377	1057704	210
42	75	35	4275-35-754	322328	1057604	212
42	75	35	4275-35-755	322379	1057599	215
42	75	35	4275-35-756	322432	1057605	214

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-757	322481	1057603	215
42	75	35	4275-35-758	322026	1057102	211
42	75	35	4275-35-759	322167	1057420	212
42	75	35	4275-35-760	322280	1057451	214
42	75	35	4275-35-761	322331	1057400	213
42	75	35	4275-35-762	322477	1057406	190
42	75	35	4275-35-763	322520	1057500	214
42	75	35	4275-35-764	322576	1057452	198
42	75	35	4275-35-765	322572	1057401	197
42	75	35	4275-35-766	322674	1057453	211
42	75	35	4275-35-767	322770	1057400	216
42	75	35	4275-35-768	322823	1057400	216
42	75	35	4275-35-769	323172	1058209	276
42	75	35	4275-35-770	323172	1058258	270
42	75	35	4275-35-771	323220	1058306	243
42	75	35	4275-35-772	323471	1058607	275
42	75	35	4275-35-773	323472	1058660	270
42	75	35	4275-35-774	323474	1058708	270
42	75	35	4275-35-775	323423	1058700	275
42	75	35	4275-35-776	323374	1058704	226
42	75	35	4275-35-777	323273	1058754	272
42	75	35	4275-35-778	323171	1058754	271
42	75	35	4275-35-779	323073	1058705	274
42	75	35	4275-35-780	323170	1058606	273
42	75	35	4275-35-781	323077	1058606	274
42	75	35	4275-35-782	322976	1058499	276
42	75	35	4275-35-783	322775	1058452	273
42	75	35	4275-35-784	322778	1058401	274
42	75	35	4275-35-785	322677	1058402	275
42	75	35	4275-35-786	322725	1058301	255
42	75	35	4275-35-787	322677	1058254	255
42	75	35	4275-35-788	322625	1058202	235
42	75	35	4275-35-789	323175	1058357	274
42	75	35	4275-35-790	323224	1058403	273
42	75	35	4275-35-791	321875	1058156	236
42	75	35	4275-35-792	321823	1058100	236
42	75	35	4275-35-793	321776	1057987	235
42	75	35	4275-35-794	321475	1057953	215
42	75	35	4275-35-795	321427	1057903	215
42	75	35	4275-35-796	321371	1057849	215
42	75	35	4275-35-797	321373	1057803	216
42	75	35	4275-35-798	321525	1057601	215
42	75	35	4275-35-799	321578	1057548	213
42	75	35	4275-35-800	321678	1057550	215
42	75	35	4275-35-801	321676	1057602	216
42	75	35	4275-35-802	321620	1057000	215
42	75	35	4275-35-803	321578	1056904	216
42	75	35	4275-35-804	321525	1056803	215
42	75	35	4275-35-805	321576	1056702	215
42	75	35	4275-35-806	321624	1056701	400
42	75	35	4275-35-807	321676	1056698	214

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-808	321727	1056702	216
42	75	35	4275-35-809	321829	1056802	213
42	75	35	4275-35-810	322024	1057604	214
42	75	35	4275-35-811	322069	1057254	216
42	75	35	4275-35-812	322071	1057202	212
42	75	35	4275-35-813	322877	1058495	297
42	75	35	4275-35-814	322874	1058353	275
42	75	35	4275-35-815	322776	1058303	255
42	75	35	4275-35-816	322824	1058297	275
42	75	35	4275-35-817	322374	1058154	232
42	75	35	4275-35-818	322220	1057600	218
42	75	35	4275-35-819	322269	1057610	208
42	75	35	4275-35-820	322277	1057548	216
42	75	35	4275-35-821	322177	1057554	214
42	75	35	4275-35-822	322278	1057500	211
42	75	35	4275-35-823	322229	1057498	216
42	75	35	4275-35-824	322179	1057502	217
42	75	35	4275-35-825	322279	1057398	212
42	75	35	4275-35-826	322378	1057401	214
42	75	35	4275-35-827	322573	1057351	196
42	75	35	4275-35-828	322776	1057355	197
42	75	35	4275-35-829	322875	1057350	215
42	75	35	4275-35-830	322820	1057300	191
42	75	35	4275-35-831	322870	1057400	215
42	75	35	4275-35-832	321475	1056801	210
42	75	35	4275-35-833	321472	1056903	214
42	75	35	4275-35-834	321675	1057053	211
42	75	35	4275-35-835	323272	1058319	275
42	75	35	4275-35-836	323223	1058258	272
42	75	35	4275-35-837	323224	1058208	274
42	75	35	4275-35-838	323222	1058158	276
42	75	35	4275-35-839	321820	1058150	235
42	75	35	4275-35-840	321427	1057953	215
42	75	35	4275-35-841	321377	1057907	215
42	75	35	4275-35-842	321371	1057754	216
42	75	35	4275-35-843	321322	1057803	215
42	75	35	4275-35-844	322860	1058451	271
42	75	35	4275-35-845	322728	1058503	273
42	75	35	4275-35-846	322774	1058503	275
42	75	35	4275-35-847	322780	1057305	195
42	75	35	4275-35-848	322826	1057251	197
42	75	35	4275-35-849	322875	1057298	215
42	75	35	4275-35-850	322925	1057346	216
42	75	35	4275-35-851	322926	1057497	215
42	75	35	4275-35-852	322873	1057500	217
42	75	35	4275-35-853	322977	1057541	214
42	75	35	4275-35-854	322927	1057596	234
42	75	35	4275-35-855C	322215	1057426	400
42	75	35	4275-35-856	320523	1056651	235
42	75	35	4275-35-857	322820	1056650	235
42	75	35	4275-35-858	321026	1057051	235

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-859	320220	1057048	232
42	75	35	4275-35-860	320423	1057047	232
42	75	35	4275-35-861	320324	1057145	228
42	75	35	4275-35-862	320125	1056856	234
42	75	35	4275-35-863	324122	1056655	295
42	75	35	4275-35-864	324113	1060453	312
42	75	35	4275-35-865	324923	1060453	315
42	75	35	4275-35-866	322281	1057351	213
42	75	35	4275-35-867	322182	1057353	212
42	75	35	4275-35-868	322327	1057250	235
42	75	35	4275-35-869	322319	1057048	229
42	75	35	4275-35-870	322523	1057251	233
42	75	35	4275-35-871	320121	1056952	238
42	75	35	4275-35-872	320126	1056757	200
42	75	35	4275-35-873	320415	1056651	233
42	75	35	4275-35-874	320626	1056653	232
42	75	35	4275-35-875	320720	1056753	231
42	75	35	4275-35-876	320830	1056854	233
42	75	35	4275-35-877	320828	1056948	234
42	75	35	4275-35-878	321528	1056602	214
42	75	35	4275-35-879	321623	1056602	213
42	75	35	4275-35-880	321673	1056601	212
42	75	35	4275-35-881	322924	1057294	214
42	75	35	4275-35-882	322729	1057308	195
42	75	35	4275-35-883	322784	1057257	195
42	75	35	4275-35-884	322734	1057260	189
42	75	35	4275-35-885	322876	1057247	194
42	75	35	4275-35-886	322929	1057396	215
42	75	35	4275-35-887	322976	1057493	214
42	75	35	4275-35-888	322975	1057442	215
42	75	35	4275-35-889	323184	1057486	235
42	75	35	4275-35-890	323180	1057701	275
42	75	35	4275-35-891	323375	1057898	274
42	75	35	4275-35-892	323176	1058802	274
42	75	35	4275-35-893	323224	1058805	275
42	75	35	4275-35-894	323273	1058854	275
42	75	35	4275-35-895	323323	1058805	274
42	75	35	4275-35-896	323274	1058806	275
42	75	35	4275-35-897	321378	1057954	209
42	75	35	4275-35-898	321329	1057911	215
42	75	35	4275-35-899	321370	1057705	210
42	75	35	4275-35-900	321331	1057705	215
42	75	35	4275-35-901	320831	1056758	400
42	75	35	4275-35-902	320621	1056753	235
42	75	35	4275-35-903	320519	1056752	235
42	75	35	4275-35-904	320420	1056746	236
42	75	35	4275-35-905	320408	1056551	234
42	75	35	4275-35-906	320523	1056550	233
42	75	35	4275-35-907	320631	1056552	235
42	75	35	4275-35-908	322877	1057197	195
42	75	35	4275-35-909	322828	1057201	195

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-910	322779	1057203	194
42	75	35	4275-35-911	322924	1057245	196
42	75	35	4275-35-912	320622	1056846	233
42	75	35	4275-35-913	320426	1056853	232
42	75	35	4275-35-914	320322	1056944	235
42	75	35	4275-35-915	320322	1056748	230
42	75	35	4275-35-916	320224	1056853	235
42	75	35	4275-35-917	321473	1058004	215
42	75	35	4275-35-918	321428	1058006	215
42	75	35	4275-35-919	321378	1058007	215
42	75	35	4275-35-920	321329	1057955	215
42	75	35	4275-35-921	321674	1058003	235
42	75	35	4275-35-922	321723	1058003	235
42	75	35	4275-35-923	321774	1058049	235
42	75	35	4275-35-924	323222	1058904	273
42	75	35	4275-35-925	323174	1058857	274
42	75	35	4275-35-926	323325	1058904	276
42	75	35	4275-35-927	323273	1058902	274
42	75	35	4275-35-928	323375	1058854	277
42	75	35	4275-35-929	322970	1057600	236
42	75	35	4275-35-930	322978	1057638	237
42	75	35	4275-35-931	321420	1056800	217
42	75	35	4275-35-932	321421	1056905	212
42	75	35	4275-35-933	321469	1056954	216
42	75	35	4275-35-934	320874	1056949	237
42	75	35	4275-35-935	320776	1056949	237
42	75	35	4275-35-936	320729	1056903	236
42	75	35	4275-35-937	320870	1056850	236
42	75	35	4275-35-938	320679	1056848	235
42	75	35	4275-35-939	320522	1056848	400
42	75	35	4275-35-940	320477	1056847	400
42	75	35	4275-35-941	320426	1056900	239
42	75	35	4275-35-942	320321	1056894	400
42	75	35	4275-35-943	320322	1056797	400
42	75	35	4275-35-944	320120	1056900	239
42	75	35	4275-35-945	320123	1056808	240
42	75	35	4275-35-946	320223	1056804	239
42	75	35	4275-35-947	320221	1056898	400
42	75	35	4275-35-948	320721	1056702	238
42	75	35	4275-35-949	320672	1056653	238
42	75	35	4275-35-950	320574	1056655	238
42	75	35	4275-35-951	320469	1056653	400
42	75	35	4275-35-952	320367	1056646	237
42	75	35	4275-35-953	320354	1056550	239
42	75	35	4275-35-954	320402	1056501	238
42	75	35	4275-35-955	320523	1056501	236
42	75	35	4275-35-956	320631	1056501	238
42	75	35	4275-35-957	320684	1056553	239
42	75	35	4275-35-958	322728	1057209	198
42	75	35	4275-35-959	322719	1057156	197
42	75	35	4275-35-960	322768	1057154	197

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-961	322820	1057150	197
42	75	35	4275-35-962	322869	1057150	195
42	75	35	4275-35-963	322917	1057156	214
42	75	35	4275-35-964	322916	1057203	215
42	75	35	4275-35-965	323022	1057443	217
42	75	35	4275-35-966	323026	1057394	214
42	75	35	4275-35-967	323020	1057600	237
42	75	35	4275-35-968	323020	1057650	400
42	75	35	4275-35-969	320970	1057000	237
42	75	35	4275-35-970	320920	1057000	236
42	75	35	4275-35-971	320870	1057000	236
42	75	35	4275-35-972	320780	1057000	234
42	75	35	4275-35-973	320830	1056901	235
42	75	35	4275-35-974	320826	1056805	241
42	75	35	4275-35-975	320775	1056756	241
42	75	35	4275-35-976	320679	1056897	236
42	75	35	4275-35-977	320621	1056795	237
42	75	35	4275-35-978	320516	1056799	236
42	75	35	4275-35-979	320469	1056749	230
42	75	35	4275-35-980	320420	1056801	242
42	75	35	4275-35-981	320372	1056797	230
42	75	35	4275-35-982	320375	1056852	238
42	75	35	4275-35-983	320275	1056853	252
42	75	35	4275-35-984	320173	1056805	238
42	75	35	4275-35-985	320073	1056809	236
42	75	35	4275-35-986	320075	1056859	237
42	75	35	4275-35-987	320470	1056707	233
42	75	35	4275-35-988	320666	1056705	236
42	75	35	4275-35-989	322968	1057153	217
42	75	35	4275-35-990	322918	1057109	218
42	75	35	4275-35-991	322965	1057104	216
42	75	35	4275-35-992	322861	1057109	198
42	75	35	4275-35-993	322814	1057107	241
42	75	35	4275-35-994	322764	1057105	188
42	75	35	4275-35-995	322712	1057106	196
42	75	35	4275-35-996	322663	1057102	189
42	75	35	4275-35-997	322671	1057151	187
42	75	35	4275-35-998	322977	1057397	217
42	75	35	4275-35-999	320175	1056754	236
42	75	35	4275-35-1000	320460	1056497	236
42	75	35	4275-35-1001	320576	1056501	236
42	75	35	4275-35-1002	320672	1056602	235
42	75	35	4275-35-1003	320770	1056705	234
42	75	35	4275-35-1004	320572	1056846	235
42	75	35	4275-35-1005	321025	1057149	236
42	75	35	4275-35-1006	322968	1057205	216
42	75	35	4275-35-1007	323027	1057701	236
42	75	35	4275-35-1008	323074	1057749	257
42	75	35	4275-35-1009	322613	1057099	194
42	75	35	4275-35-1010	322654	1057058	188
42	75	35	4275-35-1011	322706	1057056	190

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1012	322758	1057057	192
42	75	35	4275-35-1013	322808	1057060	191
42	75	35	4275-35-1014	320411	1056601	237
42	75	35	4275-35-1015	322607	1057051	200
42	75	35	4275-35-1016	322621	1057150	150
42	75	35	4275-35-1017	322677	1057201	400
42	75	35	4275-35-1018	322690	1057249	189
42	75	35	4275-35-1019	322974	1057253	400
42	75	35	4275-35-1020	320360	1056597	237
42	75	35	4275-35-1021	320352	1056501	229
42	75	35	4275-35-1022	320394	1056451	236
42	75	35	4275-35-1023	320446	1056444	225
42	75	35	4275-35-1024	320577	1056449	232
42	75	35	4275-35-1025	320626	1056449	228
42	75	35	4275-35-1026	320223	1056751	217
42	75	35	4275-35-1027	320230	1056703	218
42	75	35	4275-35-1028	320179	1056703	233
42	75	35	4275-35-1029	320120	1056650	221
42	75	35	4275-35-1030	320077	1056760	223
42	75	35	4275-35-1031	320270	1056799	237
42	75	35	4275-35-1032	321078	1056891	237
42	75	35	4275-35-1033	321108	1056898	232
42	75	35	4275-35-1034	321153	1056895	234
42	75	35	4275-35-1035	321228	1056897	234
42	75	35	4275-35-1036	321257	1056898	233
42	75	35	4275-35-1037	321286	1056894	225
42	75	35	4275-35-1038	321269	1056948	228
42	75	35	4275-35-1039	321261	1057002	236
42	75	35	4275-35-1040	320777	1057051	233
42	75	35	4275-35-1041	320881	1056902	234
42	75	35	4275-35-1042	320878	1056808	235
42	75	35	4275-35-1043	320826	1056704	236
42	75	35	4275-35-1044	322709	1057009	150
42	75	35	4275-35-1045	322760	1057009	193
42	75	35	4275-35-1046	322815	1057013	193
42	75	35	4275-35-1047	322857	1057061	196
42	75	35	4275-35-1048	323024	1057491	214
42	75	35	4275-35-1049	323079	1057572	235
42	75	35	4275-35-1050	323079	1057618	231
42	75	35	4275-35-1051	323077	1057699	234
42	75	35	4275-35-1052	323120	1057802	274
42	75	35	4275-35-1053	323223	1057902	272
42	75	35	4275-35-1054	323226	1058104	270
42	75	35	4275-35-1055	323277	1058262	272
42	75	35	4275-35-1056	323375	1058406	150
42	75	35	4275-35-1057	323476	1058551	200
42	75	35	4275-35-1058	323371	1058757	150
42	75	35	4275-35-1059	323370	1058800	277
42	75	35	4275-35-1060	323370	1058900	278
42	75	35	4275-35-1061	323375	1058955	277
42	75	35	4275-35-1062	323428	1058907	278

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1063	323172	1058905	271
42	75	35	4275-35-1064	322971	1058656	374
42	75	35	4275-35-1065	322829	1058197	274
42	75	35	4275-35-1066	322679	1058501	275
42	75	35	4275-35-1067	322475	1058255	275
42	75	35	4275-35-1068	322425	1058257	277
42	75	35	4275-35-1069	322428	1058211	252
42	75	35	4275-35-1070	322325	1058206	237
42	75	35	4275-35-1071	322275	1058205	227
42	75	35	4275-35-1072	322224	1058206	236
42	75	35	4275-35-1073	321623	1058002	234
42	75	35	4275-35-1074	321525	1058004	217
42	75	35	4275-35-1075	321325	1058006	216
42	75	35	4275-35-1076	321422	1057703	215
42	75	35	4275-35-1077	321474	1057650	214
42	75	35	4275-35-1078	321526	1057005	207
42	75	35	4275-35-1079	321470	1057000	212
42	75	35	4275-35-1080	321426	1057002	215
42	75	35	4275-35-1081	321419	1056953	212
42	75	35	4275-35-1082	321362	1056944	215
42	75	35	4275-35-1083	323377	1059005	293
42	75	35	4275-35-1084	323313	1059010	292
42	75	35	4275-35-1085	323272	1059006	293
42	75	35	4275-35-1086	323271	1058955	273
42	75	35	4275-35-1087	321476	1056701	218
42	75	35	4275-35-1088	321578	1057101	216
42	75	35	4275-35-1089	321884	1056702	215
42	75	35	4275-35-1090	321971	1057000	214
42	75	35	4275-35-1091	322073	1057153	214
42	75	35	4275-35-1092	322653	1057010	192
42	75	35	4275-35-1093	322653	1056959	194
42	75	35	4275-35-1094	322710	1056953	192
42	75	35	4275-35-1095	322765	1056953	191
42	75	35	4275-35-1096	322870	1057021	216
42	75	35	4275-35-1097	322921	1057014	213
42	75	35	4275-35-1098	322912	1057068	216
42	75	35	4275-35-1099	321372	1056904	219
42	75	35	4275-35-1100	321374	1056847	214
42	75	35	4275-35-1101	321927	1056804	213
42	75	35	4275-35-1102	322384	1057354	215
42	75	35	4275-35-1103	322685	1057308	192
42	75	35	4275-35-1104	322638	1057308	194
42	75	35	4275-35-1105	322631	1057261	191
42	75	35	4275-35-1106	322623	1057208	191
42	75	35	4275-35-1107	323268	1058154	250
42	75	35	4275-35-1108	323273	1058101	251
42	75	35	4275-35-1109	323281	1058056	256
42	75	35	4275-35-1110	320678	1056500	236
42	75	35	4275-35-1111	320671	1056443	235
42	75	35	4275-35-1112	320675	1056396	233
42	75	35	4275-35-1113	320622	1056396	230

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1114	320571	1056397	231
42	75	35	4275-35-1115	320523	1056397	237
42	75	35	4275-35-1116	320347	1056453	233
42	75	35	4275-35-1117	320305	1056548	234
42	75	35	4275-35-1118	320314	1056605	235
42	75	35	4275-35-1119	320277	1056705	235
42	75	35	4275-35-1120	320273	1056747	236
42	75	35	4275-35-1121	320375	1056746	228
42	75	35	4275-35-1122	320417	1056700	233
42	75	35	4275-35-1123	320473	1056800	232
42	75	35	4275-35-1124	320675	1056754	232
42	75	35	4275-35-1125	320724	1056803	232
42	75	35	4275-35-1126	320773	1056803	236
42	75	35	4275-35-1127	320779	1056853	233
42	75	35	4275-35-1128	320777	1056900	232
42	75	35	4275-35-1129	320834	1057103	247
42	75	35	4275-35-1130	320782	1057104	250
42	75	35	4275-35-1131	320733	1057100	251
42	75	35	4275-35-1132	320170	1056850	254
42	75	35	4275-35-1133	322373	1057248	215
42	75	35	4275-35-1134	322367	1057198	195
42	75	35	4275-35-1135	322370	1057148	195
42	75	35	4275-35-1136	322417	1057148	195
42	75	35	4275-35-1137	322713	1056907	197
42	75	35	4275-35-1138	322662	1056913	194
42	75	35	4275-35-1139	322610	1056916	193
42	75	35	4275-35-1140	322609	1056961	193
42	75	35	4275-35-1141	322606	1057006	192
42	75	35	4275-35-1142	322570	1057149	191
42	75	35	4275-35-1143	322568	1057198	192
42	75	35	4275-35-1144	322570	1057256	192
42	75	35	4275-35-1145	322569	1057308	190
42	75	35	4275-35-1146	323318	1058153	254
42	75	35	4275-35-1147	323325	1058102	250
42	75	35	4275-35-1148	323332	1058052	259
42	75	35	4275-35-1149	320301	1056501	235
42	75	35	4275-35-1150	320300	1056451	234
42	75	35	4275-35-1151	320291	1056402	230
42	75	35	4275-35-1152	320344	1056408	231
42	75	35	4275-35-1153	320391	1056406	232
42	75	35	4275-35-1154	320569	1056352	215
42	75	35	4275-35-1155	320616	1056350	212
42	75	35	4275-35-1156	320670	1056351	213
42	75	35	4275-35-1157	320719	1056349	211
42	75	35	4275-35-1158	322466	1057151	195
42	75	35	4275-35-1159	320723	1056439	211
42	75	35	4275-35-1160	320727	1056496	236
42	75	35	4275-35-1161	321324	1056904	214
42	75	35	4275-35-1162	321321	1056952	220
42	75	35	4275-35-1163	321318	1056999	214
42	75	35	4275-35-1164	321368	1057000	219

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1165	321369	1057048	216
42	75	35	4275-35-1166	321423	1057051	218
42	75	35	4275-35-1167	321474	1057052	219
42	75	35	4275-35-1168	321574	1057103	217
42	75	35	4275-35-1169	320620	1056600	231
42	75	35	4275-35-1170	322520	1058300	237
42	75	35	4275-35-1171	323272	1059054	276
42	75	35	4275-35-1172	323371	1059055	294
42	75	35	4275-35-1173	323420	1059000	293
42	75	35	4275-35-1174	323421	1058803	293
42	75	35	4275-35-1175	322717	1056857	189
42	75	35	4275-35-1176	322667	1056862	215
42	75	35	4275-35-1177	322617	1056865	216
42	75	35	4275-35-1178	322560	1056960	193
42	75	35	4275-35-1179	321574	1056554	193
42	75	35	4275-35-1180	322558	1057050	192
42	75	35	4275-35-1181	322565	1057099	194
42	75	35	4275-35-1182	322520	1057099	214
42	75	35	4275-35-1183	322518	1057305	215
42	75	35	4275-35-1184	322521	1057149	212
42	75	35	4275-35-1185	322514	1057188	210
42	75	35	4275-35-1186	323520	1059300	275
42	75	35	4275-35-1187	323468	1059305	274
42	75	35	4275-35-1188	323419	1059301	278
42	75	35	4275-35-1189	320678	1057050	238
42	75	35	4275-35-1190	322478	1057196	189
42	75	35	4275-35-1191	320684	1057150	237
42	75	35	4275-35-1192	320734	1057150	237
42	75	35	4275-35-1193	320783	1057155	236
42	75	35	4275-35-1194	320833	1057151	257
42	75	35	4275-35-1195	320880	1057154	235
42	75	35	4275-35-1196	320884	1057104	258
42	75	35	4275-35-1197	320883	1057052	255
42	75	35	4275-35-1198	321576	1057151	213
42	75	35	4275-35-1199	322461	1057350	198
42	75	35	4275-35-1200	322469	1057302	192
42	75	35	4275-35-1201	322477	1057246	197
42	75	35	4275-35-1202	322510	1057051	193
42	75	35	4275-35-1203	322511	1057007	195
42	75	35	4275-35-1204	322511	1056962	198
42	75	35	4275-35-1205	322514	1056915	194
42	75	35	4275-35-1206	322570	1056914	197
42	75	35	4275-35-1207	321827	1058206	256
42	75	35	4275-35-1208	321878	1058204	256
42	75	35	4275-35-1209	321924	1058206	258
42	75	35	4275-35-1210	323319	1059103	400
42	75	35	4275-35-1211	323364	1059105	294
42	75	35	4275-35-1212	323417	1059107	297
42	75	35	4275-35-1213	321422	1057097	218
42	75	35	4275-35-1214	323519	1059210	276
42	75	35	4275-35-1215	321522	1057102	212

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1216	321518	1057153	212
42	75	35	4275-35-1217	322422	1057296	193
42	75	35	4275-35-1218	322426	1057246	196
42	75	35	4275-35-1219	322434	1057198	213
42	75	35	4275-35-1220	321467	1057149	213
42	75	35	4275-35-1221	322419	1057353	192
42	75	35	4275-35-1222	323372	1059155	275
42	75	35	4275-35-1223	323370	1059200	276
42	75	35	4275-35-1224	323424	1059207	269
42	75	35	4275-35-1225	323473	1059209	273
42	75	35	4275-35-1226	323472	1059160	276
42	75	35	4275-35-1227	323465	1059110	294
42	75	35	4275-35-1228	323475	1059061	276
42	75	35	4275-35-1229	323516	1059113	277
42	75	35	4275-35-1230	321473	1057100	213
42	75	35	4275-35-1231	323470	1059250	277
42	75	35	4275-35-1232	323371	1059257	271
42	75	35	4275-35-1233	321515	1057201	210
42	75	35	4275-35-1234	321572	1057203	214
42	75	35	4275-35-1235	321621	1057199	214
42	75	35	4275-35-1236	320120	1056350	235
42	75	35	4275-35-1237	320120	1056250	235
42	75	35	4275-35-1238	320120	1056150	235
42	75	35	4275-35-1239	320722	1056397	232
42	75	35	4275-35-1240	320476	1056899	234
42	75	35	4275-35-1241	320480	1056947	232
42	75	35	4275-35-1242	320531	1056942	238
42	75	35	4275-35-1243	320580	1056942	237
42	75	35	4275-35-1244	323566	1059255	296
42	75	35	4275-35-1245	323568	1059305	295
42	75	35	4275-35-1246	323568	1059358	291
42	75	35	4275-35-1247	323520	1059355	291
42	75	35	4275-35-1248	323470	1059358	275
42	75	35	4275-35-1249	320770	1056446	236
42	75	35	4275-35-1250	320768	1056396	215
42	75	35	4275-35-1251	320772	1056350	216
42	75	35	4275-35-1252	320774	1056305	236
42	75	35	4275-35-1253	320725	1056298	215
42	75	35	4275-35-1254	320770	1056495	232
42	75	35	4275-35-1255	320675	1056292	400
42	75	35	4275-35-1256	320683	1057099	233
42	75	35	4275-35-1257	320938	1057195	200
42	75	35	4275-35-1258C	322572	1059137	277
42	75	35	4275-35-1259C	322540	1056435	277
42	75	35	4275-35-1260C	322581	1059557	195
42	75	35	4275-35-1261	322524	1058281	228
42	75	35	4275-35-1262	322570	1057347	196
42	75	35	4275-35-1263	322566	1057548	220
42	75	35	4275-35-1264	323470	1059000	223
42	75	35	4275-35-1265	323520	1059000	293
42	75	35	4275-35-1266	323570	1059000	296

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1267	323570	1059050	294
42	75	35	4275-35-1268	323570	1059100	294
42	75	35	4275-35-1269	323270	1058200	259
42	75	35	4275-35-1270	323270	1058000	259
42	75	35	4275-35-1271	323270	1057950	260
42	75	35	4275-35-1272	323270	1057900	250
42	75	35	4275-35-1273	322320	1057300	196
42	75	35	4275-35-1274	322270	1057250	196
42	75	35	4275-35-1275	322320	1057200	196
42	75	35	4275-35-1276	322470	1057050	199
42	75	35	4275-35-1277	322470	1057000	199
42	75	35	4275-35-1278	322470	1056950	199
42	75	35	4275-35-1279	321370	1056550	214
42	75	35	4275-35-1280	321470	1056650	216
42	75	35	4275-35-1281	320370	1056700	235
42	75	35	4275-35-1282	320320	1056700	234
42	75	35	4275-35-1283	322970	1056900	215
42	75	35	4275-35-1284	323170	1056900	217
42	75	35	4275-35-1285	322170	1057100	219
42	75	35	4275-35-1286	322170	1057300	219
42	75	35	4275-35-1287	323570	1057700	278
42	75	35	4275-35-1288	323570	1058100	278
42	75	35	4275-35-1289	323370	1058150	259
42	75	35	4275-35-1290	323370	1058100	259
42	75	35	4275-35-1291	323370	1058050	259
42	75	35	4275-35-1292	323820	1058750	296
42	75	35	4275-35-1293	323820	1058950	294
42	75	35	4275-35-1294	323820	1059150	283
42	75	35	4275-35-1295	322568	1057294	239
42	75	35	4275-35-1296	320820	1056450	215
42	75	35	4275-35-1297	320820	1056400	218
42	75	35	4275-35-1298	320820	1056350	217
42	75	35	4275-35-1299	320820	1056300	218
42	75	35	4275-35-1300	320820	1056250	216
42	75	35	4275-35-1301	320820	1057200	238
42	75	35	4275-35-1302	320770	1057200	237
42	75	35	4275-35-1303	320720	1057200	400
42	75	35	4275-35-1304	320670	1057200	238
42	75	35	4275-35-1305	320620	1057200	238
42	75	35	4275-35-1306	320920	1057200	238
42	75	35	4275-35-1307	320970	1057200	238
42	75	35	4275-35-1308	320770	1056250	215
42	75	35	4275-35-1309	320720	1056250	214
42	75	35	4275-35-1310	320670	1056250	214
42	75	35	4275-35-1311	320620	1056250	217
42	75	35	4275-35-1312	320620	1056300	217
42	75	35	4275-35-1313	320620	1057150	238
42	75	35	4275-35-1314	320620	1057100	237
42	75	35	4275-35-1315	320622	1056999	237
42	75	35	4275-35-1316	320680	1056999	236
42	75	35	4275-35-1317	320970	1057150	239

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1318	320970	1057100	239
42	75	35	4275-35-1319	320970	1057050	238
42	75	35	4275-35-1320	320927	1057103	238
42	75	35	4275-35-1321	320720	1056050	213
42	75	35	4275-35-1322	320720	1055850	215
42	75	35	4275-35-1323	320420	1056350	235
42	75	35	4275-35-1324	320370	1056350	234
42	75	35	4275-35-1325	320320	1056350	236
42	75	35	4275-35-1326	320270	1056350	238
42	75	35	4275-35-1327	320220	1056400	236
42	75	35	4275-35-1328	320220	1056450	236
42	75	35	4275-35-1329	321120	1056850	238
42	75	35	4275-35-1330	321120	1056650	239
42	75	35	4275-35-1331	321120	1056450	236
42	75	35	4275-35-1332	321120	1056250	237
42	75	35	4275-35-1333	320620	1056200	218
42	75	35	4275-35-1334	320670	1056200	216
42	75	35	4275-35-1335	320720	1056200	216
42	75	35	4275-35-1336	321470	1056550	216
42	75	35	4275-35-1337	321470	1056600	216
42	75	35	4275-35-1338	321420	1056600	216
42	75	35	4275-35-1339	321420	1056700	216
42	75	35	4275-35-1340	321324	1056449	236
42	75	35	4275-35-1341	321820	1056650	216
42	75	35	4275-35-1342	321770	1056650	246
42	75	35	4275-35-1343	321870	1056650	215
42	75	35	4275-35-1344	322570	1056700	216
42	75	35	4275-35-1345	322570	1056500	216
42	75	35	4275-35-1346	320770	1056200	214
42	75	35	4275-35-1347	320720	1056150	216
42	75	35	4275-35-1348	320670	1056150	216
42	75	35	4275-35-1349	320620	1056150	216
42	75	35	4275-35-1350	320570	1056150	216
42	75	35	4275-35-1351	320570	1056250	216
42	75	35	4275-35-1352	320570	1056200	215
42	75	35	4275-35-1353	321525	1056500	216
42	75	35	4275-35-1354	321602	1056475	214
42	75	35	4275-35-1355	321623	1056498	214
42	75	35	4275-35-1356	323320	1058200	256
42	75	35	4275-35-1357	323320	1058250	254
42	75	35	4275-35-1358	320720	1056100	219
42	75	35	4275-35-1359	320670	1056100	219
42	75	35	4275-35-1360	320620	1056100	150
42	75	35	4275-35-1361	320770	1056100	218
42	75	35	4275-35-1362	320770	1056150	218
42	75	35	4275-35-1363	322570	1056650	215
42	75	35	4275-35-1364	322570	1056750	214
42	75	35	4275-35-1365	322620	1056700	216
42	75	35	4275-35-1366	322520	1056700	215
42	75	35	4275-35-1367	320270	1056650	238
42	75	35	4275-35-1368	322370	1056700	219

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1369	322570	1056900	234
42	75	35	4275-35-1370	320320	1056300	248
42	75	35	4275-35-1371	320370	1056300	238
42	75	35	4275-35-1372	320420	1056300	239
42	75	35	4275-35-1373	320820	1056150	216
42	75	35	4275-35-1374	320820	1056200	215
42	75	35	4275-35-1375	321523	1056451	215
42	75	35	4275-35-1376	321520	1056450	216
42	75	35	4275-35-1377	321926	1056447	216
42	75	35	4275-35-1378	321470	1057450	218
42	75	35	4275-35-1379	321520	1057400	214
42	75	35	4275-35-1380	321520	1057500	218
42	75	35	4275-35-1381	321470	1057500	219
42	75	35	4275-35-1382	321470	1057400	217
42	75	35	4275-35-1383	321570	1057400	217
42	75	35	4275-35-1384	321320	1057450	219
42	75	35	4275-35-1385	323820	1059350	296
42	75	35	4275-35-1386	323820	1059750	296
42	75	35	4275-35-1387	323620	1059450	294
42	75	35	4275-35-1388	323620	1059550	295
42	75	35	4275-35-1389	323620	1059750	296
42	75	35	4275-35-1390	322620	1056750	234
42	75	35	4275-35-1391	322670	1056750	217
42	75	35	4275-35-1392	322520	1056750	217
42	75	35	4275-35-1393	322520	1056650	216
42	75	35	4275-35-1394	322620	1056650	216
42	75	35	4275-35-1395	322670	1056650	215
42	75	35	4275-35-1396	322670	1056700	212
42	75	35	4275-35-1397	321579	1057503	215
42	75	35	4275-35-1398	321420	1057150	218
42	75	35	4275-35-1399	321120	1056950	234
42	75	35	4275-35-1400	321120	1057150	239
42	75	35	4275-35-1401	321120	1057350	219
42	75	35	4275-35-1402	321120	1057550	219
42	75	35	4275-35-1403	320920	1055850	216
42	75	35	4275-35-1404	321120	1055850	235
42	75	35	4275-35-1405	320520	1055850	218
42	75	35	4275-35-1406	320320	1055850	219
42	75	35	4275-35-1407	320120	1055850	216
42	75	35	4275-35-1408	320320	1056050	218
42	75	35	4275-35-1409	322170	1056700	216
42	75	35	4275-35-1410	322170	1056900	215
42	75	35	4275-35-1411	322170	1057050	216
42	75	35	4275-35-1412	321120	1056050	214
42	75	35	4275-35-1413	321521	1056046	216
42	75	35	4275-35-1414	321924	1056054	217
42	75	35	4275-35-1415	320270	1057100	238
42	75	35	4275-35-1416	320270	1057050	238
42	75	35	4275-35-1417	320273	1056995	237
42	75	35	4275-35-1418	320370	1057100	236
42	75	35	4275-35-1419	320370	1057050	236

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1420	320375	1056996	236
42	75	35	4275-35-1421	320320	1057100	237
42	75	35	4275-35-1422	320323	1056997	237
42	75	35	4275-35-1423	320570	1057200	239
42	75	35	4275-35-1424	320570	1057150	239
42	75	35	4275-35-1425	320570	1057250	236
42	75	35	4275-35-1426	320620	1057250	239
42	75	35	4275-35-1427	320670	1057250	239
42	75	35	4275-35-1428	320420	1056250	237
42	75	35	4275-35-1429	320470	1056250	237
42	75	35	4275-35-1430	320370	1056250	236
42	75	35	4275-35-1431	320470	1056350	237
42	75	35	4275-35-1432	320470	1056300	238
42	75	35	4275-35-1433	320920	1055650	218
42	75	35	4275-35-1434	322570	1056600	217
42	75	35	4275-35-1435	322520	1056600	217
42	75	35	4275-35-1436	322470	1056600	215
42	75	35	4275-35-1437	322470	1056700	216
42	75	35	4275-35-1438	322470	1056650	215
42	75	35	4275-35-1439	322670	1056800	214
42	75	35	4275-35-1440	322619	1056808	213
42	75	35	4275-35-1441	322569	1056810	214
42	75	35	4275-35-1442	321723	1056857	216
42	75	35	4275-35-1443	322370	1056900	217
42	75	35	4275-35-1444	322820	1056900	212
42	75	35	4275-35-1445	320920	1056250	236
42	75	35	4275-35-1446	320920	1056600	233
42	75	35	4275-35-1447	320720	1056600	237
42	75	35	4275-35-1448	320220	1056950	233
42	75	35	4275-35-1449	320220	1057000	237
42	75	35	4275-35-1450	320220	1057050	238
42	75	35	4275-35-1451	320320	1056200	237
42	75	35	4275-35-1452	320370	1056200	219
42	75	35	4275-35-1453	320420	1056200	237
42	75	35	4275-35-1454	320470	1056200	237
42	75	35	4275-35-1455	320320	1056250	239
42	75	35	4275-35-1456	320520	1057000	236
42	75	35	4275-35-1457	320570	1057000	237
42	75	35	4275-35-1458	321570	1057350	217
42	75	35	4275-35-1459	321470	1057350	217
42	75	35	4275-35-1460	322170	1057200	215
42	75	35	4275-35-1461	322170	1056500	215
42	75	35	4275-35-1462	321520	1056350	216
42	75	35	4275-35-1463	321320	1056350	215
42	75	35	4275-35-1464	320270	1056950	237
42	75	35	4275-35-1465	320470	1057000	236
42	75	35	4275-35-1466	320520	1057200	237
42	75	35	4275-35-1467	322420	1056700	214
42	75	35	4275-35-1468	322420	1056650	216
42	75	35	4275-35-1469	322420	1056600	216
42	75	35	4275-35-1470	322420	1056550	215

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1471	322470	1056550	214
42	75	35	4275-35-1472	322520	1056550	216
42	75	35	4275-35-1473	322022	1056150	217
42	75	35	4275-35-1474	321920	1056150	216
42	75	35	4275-35-1475	321823	1056150	216
42	75	35	4275-35-1476	321620	1056150	216
42	75	35	4275-35-1477	321520	1056150	215
42	75	35	4275-35-1478	321420	1056150	216
42	75	35	4275-35-1479	321420	1056050	216
42	75	35	4275-35-1480	321420	1055950	216
42	75	35	4275-35-1481	321520	1055950	210
42	75	35	4275-35-1482	321620	1055950	215
42	75	35	4275-35-1483	321820	1055950	217
42	75	35	4275-35-1484	321920	1055950	214
42	75	35	4275-35-1485	322023	1055950	219
42	75	35	4275-35-1486	322020	1056045	217
42	75	35	4275-35-1487	321820	1056050	216
42	75	35	4275-35-1488	321724	1056051	215
42	75	35	4275-35-1489	321620	1056050	215
42	75	35	4275-35-1490	320620	1057300	237
42	75	35	4275-35-1491	320570	1057300	237
42	75	35	4275-35-1492	320520	1057300	237
42	75	35	4275-35-1493	321320	1056250	235
42	75	35	4275-35-1494	320320	1056150	216
42	75	35	4275-35-1495	320370	1056150	216
42	75	35	4275-35-1496	320420	1056150	215
42	75	35	4275-35-1497	320720	1056550	236
42	75	35	4275-35-1498	320770	1056550	235
42	75	35	4275-35-1499	320770	1056600	235
42	75	35	4275-35-1500	320770	1056650	237
42	75	35	4275-35-1501	321420	1055900	217
42	75	35	4275-35-1502	321620	1055900	215
42	75	35	4275-35-1503	321520	1055900	217
42	75	35	4275-35-1504	322025	1056199	217
42	75	35	4275-35-1505	321820	1056250	196
42	75	35	4275-35-1506	321920	1056200	217
42	75	35	4275-35-1507	322170	1057150	212
42	75	35	4275-35-1508	322170	1057250	213
42	75	35	4275-35-1509	322120	1057200	216
42	75	35	4275-35-1510	322220	1057200	214
42	75	35	4275-35-1511	322220	1057250	214
42	75	35	4275-35-1512	322120	1057143	215
42	75	35	4275-35-1513	322220	1057150	217
42	75	35	4275-35-1514	320820	1056550	235
42	75	35	4275-35-1515	320820	1056600	235
42	75	35	4275-35-1516	320470	1056450	237
42	75	35	4275-35-1517	320120	1056050	216
42	75	35	4275-35-1518	320470	1056150	217
42	75	35	4275-35-1519	322720	1056750	214
42	75	35	4275-35-1520	320620	1057350	237
42	75	35	4275-35-1521	320570	1057350	238

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1522	320670	1057350	237
42	75	35	4275-35-1523	320670	1057300	237
42	75	35	4275-35-1524	322174	1057099	198
42	75	35	4275-35-1525	322124	1057093	197
42	75	35	4275-35-1526	320520	1057300	198
42	75	35	4275-35-1527	322223	1057106	197
42	75	35	4275-35-1528	322170	1057300	215
42	75	35	4275-35-1529	322220	1057300	216
42	75	35	4275-35-1530	322120	1057300	215
42	75	35	4275-35-1531	322270	1057200	196
42	75	35	4275-35-1532	322270	1057150	195
42	75	35	4275-35-1533	322516	1056858	218
42	75	35	4275-35-1534	322524	1056809	220
42	75	35	4275-35-1535	320720	1057350	239
42	75	35	4275-35-1536	320720	1057300	239
42	75	35	4275-35-1537	320720	1057250	237
42	75	35	4275-35-1538	323920	1060450	275
42	75	35	4275-35-1539	324170	1059150	298
42	75	35	4275-35-1540	324170	1058750	295
42	75	35	4275-35-1541	324170	1058350	255
42	75	35	4275-35-1542	324170	1057950	239
42	75	35	4275-35-1543	324170	1057550	238
42	75	35	4275-35-1544	324570	1057950	235
42	75	35	4275-35-1545	324570	1058350	274
42	75	35	4275-35-1546	324570	1058750	298
42	75	35	4275-35-1547	324570	1059151	297
42	75	35	4275-35-1548	324970	1059150	274
42	75	35	4275-35-1549	324970	1058750	273
42	75	35	4275-35-1550	322895	1056900	193
42	75	35	4275-35-1551	322820	1056800	197
42	75	35	4275-35-1552	322820	1056700	140
42	75	35	4275-35-1553	322170	1056304	195
42	75	35	4275-35-1554	321420	1056250	216
42	75	35	4275-35-1555	321420	1056350	214
42	75	35	4275-35-1556	321420	1056450	216
42	75	35	4275-35-1557	321105	1056747	236
42	75	35	4275-35-1558	321020	1056750	236
42	75	35	4275-35-1559	320920	1056750	236
42	75	35	4275-35-1560	321020	1056850	236
42	75	35	4275-35-1561	321220	1056850	236
42	75	35	4275-35-1562	321220	1056950	235
42	75	35	4275-35-1563	321220	1057050	216
42	75	35	4275-35-1564	321220	1057150	214
42	75	35	4275-35-1565	321220	1057250	215
42	75	35	4275-35-1566	321220	1057350	217
42	75	35	4275-35-1567	321220	1057450	216
42	75	35	4275-35-1568	321220	1057550	217
42	75	35	4275-35-1569	321329	1057550	215
42	75	35	4275-35-1570	320820	1057550	235
42	75	35	4275-35-1571	320820	1057650	235
42	75	35	4275-35-1572	321023	1057366	200

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1573	320620	1057650	238
42	75	35	4275-35-1574	320520	1057750	258
42	75	35	4275-35-1575	320920	1057750	236
42	75	35	4275-35-1576	321020	1057750	238
42	75	35	4275-35-1577	320420	1057550	252
42	75	35	4275-35-1578	320420	1057350	238
42	75	35	4275-35-1579	320420	1056050	218
42	75	35	4275-35-1580	320520	1055950	216
42	75	35	4275-35-1581	320620	1055850	216
42	75	35	4275-35-1582	320420	1055850	215
42	75	35	4275-35-1583	320720	1055650	216
42	75	35	4275-35-1584	320770	1057350	237
42	75	35	4275-35-1585	320770	1057300	235
42	75	35	4275-35-1586	320770	1057250	237
42	75	35	4275-35-1587	321720	1056150	196
42	75	35	4275-35-1588	321870	1056150	197
42	75	35	4275-35-1589	321920	1056300	198
42	75	35	4275-35-1590	321720	1055950	218
42	75	35	4275-35-1591	321575	1056041	217
42	75	35	4275-35-1592	321320	1057500	218
42	75	35	4275-35-1593	323433	1059153	278
42	75	35	4275-35-1594	321370	1056450	216
42	75	35	4275-35-1595	321326	1056344	216
42	75	35	4275-35-1596	321320	1056150	219
42	75	35	4275-35-1597	321320	1055950	218
42	75	35	4275-35-1598	321501	1055800	218
42	75	35	4275-35-1599	321020	1056650	235
42	75	35	4275-35-1600	321276	1056991	218
42	75	35	4275-35-1601	321421	1057216	216
42	75	35	4275-35-1602	320520	1057100	235
42	75	35	4275-35-1603	320420	1057150	239
42	75	35	4275-35-1604	324570	1058150	257
42	75	35	4275-35-1605	324770	1058750	277
42	75	35	4275-35-1606	324770	1058950	276
42	75	35	4275-35-1607	324970	1058950	276
42	75	35	4275-35-1608	320370	1056100	215
42	75	35	4275-35-1609	320420	1055950	216
42	75	35	4275-35-1610	320620	1055650	219
42	75	35	4275-35-1611	321620	1056100	219
42	75	35	4275-35-1612	321720	1056100	218
42	75	35	4275-35-1613	321820	1056100	218
42	75	35	4275-35-1614	321820	1056200	197
42	75	35	4275-35-1615	321620	1056000	218
42	75	35	4275-35-1616	321970	1056100	197
42	75	35	4275-35-1617	321926	1056242	197
42	75	35	4275-35-1618	322035	1056297	194
42	75	35	4275-35-1619	322570	1055700	198
42	75	35	4275-35-1620	322540	1056099	194
42	75	35	4275-35-1621	322170	1055700	219
42	75	35	4275-35-1622	321770	1055700	219
42	75	35	4275-35-1623	321320	1055697	219

Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1624	321920	1056350	195
42	75	35	4275-35-1625	322175	1056793	213
42	75	35	4275-35-1626	322275	1056700	213
42	75	35	4275-35-1627	321570	1056000	217
42	75	35	4275-35-1628	321570	1056100	216
42	75	35	4275-35-1629	321220	1056750	237
42	75	35	4275-35-1630	321370	1057500	217
42	75	35	4275-35-1631	321370	1057550	216
42	75	35	4275-35-1632	322915	1056801	193
42	75	35	4275-35-1633	321220	1057650	217
42	75	35	4275-35-1634	324020	1056051	279
42	75	35	4275-35-1635	321370	1056150	218
42	75	35	4275-35-1636	321730	1056195	193
42	75	35	4275-35-1637	321920	1056100	196
42	75	35	4275-35-1638	321676	1056049	214
42	75	35	4275-35-1639	321504	1055848	218
42	75	35	4275-35-1640	324670	1059053	298
42	75	35	4275-35-1641	321370	1056350	215
42	75	35	4275-35-1642	321370	1056250	218
42	75	35	4275-35-1643	321120	1056800	236
42	75	35	4275-35-1644	321000	1056698	232
42	75	35	4275-35-1645	320820	1056050	215
42	75	35	4275-35-1646	320920	1056350	150
42	75	35	4275-35-1647	320920	1055950	215
42	75	35	4275-35-1648	321120	1055950	215
42	75	35	4275-35-1649	320920	1055750	214
42	75	35	4275-35-1650	321126	1055649	214
42	75	35	4275-35-1651	321383	1056203	237
42	75	35	4275-35-1652	321379	1056298	237
42	75	35	4275-35-1653	321379	1056392	237
42	75	35	4275-35-1654C	320576	1056600	229
42	75	35	4275-35-1655C	320572	1056704	238
42	75	35	4275-35-1656C	320570	1056799	234
42	75	35	4275-35-1657	320933	1056301	233
42	75	35	4275-35-1658	320933	1055997	215
42	75	35	4275-35-1659	320870	1056049	214
42	75	35	4275-35-1660	320940	1055691	214
42	75	35	4275-35-1661	321425	1056199	234
42	75	35	4275-35-1662	321425	1056295	232
42	75	35	4275-35-1663	321422	1056392	233
42	75	35	4275-35-1664	322332	1055698	194
42	75	35	4275-35-1665C	320771	1056324	234
42	75	35	4275-35-1666C	320646	1056419	215
42	75	35	4275-35-1667C	320172	1056780	219
42	75	35	4275-35-1668C	320710	1057078	400
42	75	35	4275-35-1669C	320777	1056974	238
42	75	35	4275-35-1670C	320273	1056826	258
42	75	35	4275-35-1671C	321502	1056774	195
42	75	35	4275-35-1672C	321577	1056803	218
42	75	35	4275-35-1673C	322790	1057107	193
42	75	35	4275-35-1674	322242	1055695	190

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1675C	322683	1057228	195
42	75	35	4275-35-1676C	323397	1059208	277
42	75	35	4275-35-1677	322328	1058345	234
42	75	35	4275-35-1678C	322496	1056642	216
42	75	35	4275-35-1679C	322121	1057170	217
42	75	35	4275-35-1680	321512	1055696	214
42	75	35	4275-35-1681	321909	1055700	194
42	75	35	4275-35-1682	321712	1055503	194
42	75	35	4275-35-1683	322025	1056240	214
42	75	35	4275-35-1684	322171	1056400	214
42	75	35	4275-35-1685	322225	1056700	214
42	75	35	4275-35-1686	320775	1056046	212
42	75	35	4275-35-1687	321378	1056106	212
42	75	35	4275-35-1688	321427	1056098	214
42	75	35	4275-35-1689	321913	1055497	195
42	75	35	4275-35-1690	322325	1055500	195
42	75	35	4275-35-1691	321717	1055603	193
42	75	35	4275-35-1692	321539	1055504	199
42	75	35	4275-35-1693	321335	1055504	199
42	75	35	4275-35-1694	321636	1055801	215
42	75	35	4275-35-1695	321813	1055797	215
42	75	35	4275-35-1696	322168	1056352	215
42	75	35	4275-35-1697	321473	1056452	219
42	75	35	4275-35-1698	321474	1056499	215
42	75	35	4275-35-1699	321426	1056495	219
42	75	35	4275-35-1700	321382	1056497	220
42	75	35	4275-35-1701	321473	1056044	215
42	75	35	4275-35-1702	321475	1056093	215
42	75	35	4275-35-1703C	323375	1058877	277
42	75	35	4275-35-1704	321026	1057099	233
42	75	35	4275-35-1705	320929	1056510	233
42	75	35	4275-35-1706	321323	1056391	232
42	75	35	4275-35-1707	321315	1056489	216
42	75	35	4275-35-1708	321323	1056549	219
42	75	35	4275-35-1709	321380	1056549	213
42	75	35	4275-35-1710	321274	1057547	216
42	75	35	4275-35-1711	321221	1057851	218
42	75	35	4275-35-1712	324521	1055475	216
42	75	35	4275-35-1713	323164	1056686	197
42	75	35	4275-35-1714	322931	1056701	193
42	75	35	4275-35-1715	322770	1056644	199
42	75	35	4275-35-1716	322271	1056795	219
42	75	35	4275-35-1717	322282	1056506	219
42	75	35	4275-35-1718	321123	1056549	220
42	75	35	4275-35-1719	320727	1057499	200
42	75	35	4275-35-1720	320824	1057443	231
42	75	35	4275-35-1721	320928	1057592	228
42	75	35	4275-35-1722	321124	1057949	225
42	75	35	4275-35-1723	323712	1059455	290
42	75	35	4275-35-1724	324008	1059757	298
42	75	35	4275-35-1725	324111	1060090	150

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1726	321273	1057596	216
42	75	35	4275-35-1727	321222	1057694	150
42	75	35	4275-35-1728	321378	1056593	200
42	75	35	4275-35-1729	321329	1056583	237
42	75	35	4275-35-1730	322224	1056501	217
42	75	35	4275-35-1731	322079	1056590	220
42	75	35	4275-35-1732	321275	1056601	238
42	75	35	4275-35-1733	321275	1056653	238
42	75	35	4275-35-1734	321817	1056697	219
42	75	35	4275-35-1735	321978	1056600	219
42	75	35	4275-35-1736	321159	1057386	217
42	75	35	4275-35-1737	321142	1055498	400
42	75	35	4275-35-1738	320307	1055644	218
42	75	35	4275-35-1739	321425	1056547	238
42	75	35	4275-35-1740	322404	1056800	219
42	75	35	4275-35-1741	321720	1055452	216
42	75	35	4275-35-1742	321690	1055756	200
42	75	35	4275-35-1743	321789	1055743	217
42	75	35	4275-35-1744	322272	1056035	218
42	75	35	4275-35-1745	321222	1056797	239
42	75	35	4275-35-1746	321325	1056748	239
42	75	35	4275-35-1747	321066	1056746	238
42	75	35	4275-35-1748	320918	1056695	239
42	75	35	4275-35-1749	322030	1056595	218
42	75	35	4275-35-1750	321983	1056551	218
42	75	35	4275-35-1751	321723	1056502	214
42	75	35	4275-35-1752	322458	1056803	214
42	75	35	4275-35-1753	320345	1056107	218
42	75	35	4275-35-1754	320127	1055951	219
42	75	35	4275-35-1755	320126	1056558	238
42	75	35	4275-35-1756	320229	1056359	238
42	75	35	4275-35-1757	321070	1056701	236
42	75	35	4275-35-1758	322036	1056540	216
42	75	35	4275-35-1759	321932	1056559	217
42	75	35	4275-35-1760	321934	1056604	217
42	75	35	4275-35-1761	322404	1056848	200
42	75	35	4275-35-1762	322405	1056750	218
42	75	35	4275-35-1763	322070	1056403	215
42	75	35	4275-35-1764	322080	1056490	213
42	75	35	4275-35-1765	321370	1056650	218
42	75	35	4275-35-1766	320372	1056947	235
42	75	35	4275-35-1767	320122	1057002	238
42	75	35	4275-35-1768	320121	1057051	238
42	75	35	4275-35-1769	320320	1057200	239
42	75	35	4275-35-1770	320478	1057137	239
42	75	35	4275-35-1771	320869	1057199	236
42	75	35	4275-35-1772	320869	1057342	234
42	75	35	4275-35-1773	321027	1057409	236
42	75	35	4275-35-1774	322083	1056543	239
42	75	35	4275-35-1775	321974	1056652	236
42	75	35	4275-35-1776	322080	1056550	238

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-1777	322021	1056659	238
42	75	35	4275-35-1778	321925	1056653	234
42	75	35	4275-35-1779	321988	1056491	212
42	75	35	4275-35-1780	322040	1056500	216
42	75	35	4275-35-1781	322136	1056538	218
42	75	35	4275-35-1782	321930	1056705	213
42	75	35	4275-35-1783	322116	1056488	219
42	75	35	4275-35-1784	321927	1056763	214
42	75	35	4275-35-1785	321982	1056703	200
42	75	35	4275-35-1786	322119	1056431	218
42	75	35	4275-35-1787	321981	1056758	219
42	75	35	4275-35-1788	322135	1056589	216
42	75	35	4275-35-1789	321891	1056610	217
42	75	35	4275-35-1790	321942	1056512	150
42	75	35	4275-35-1791	320167	1056999	237
42	75	35	4275-35-1792	320072	1057001	236
42	75	35	4275-35-1793	320170	1057190	237
42	75	35	4275-35-1794	320272	1057193	235
42	75	35	4275-35-1795	320220	1057150	253
42	75	35	4275-35-1796	320070	1057050	255
42	75	35	4275-35-1797	320170	1057050	236
42	75	35	4275-35-1798	320170	1056950	234
42	75	35	4275-35-1799	320070	1056950	255
42	75	35	4275-35-1800	322070	1056650	217
42	75	35	4275-35-1801	321970	1056450	197
42	75	35	4275-35-1802	321820	1056550	218
42	75	35	4275-35-1803	320930	1057650	234
42	75	35	4275-35-1804	320070	1057050	258
42	75	35	4275-35-1811C	322237	1057812	400
42	75	35	4275-35-1812C	323078	1058306	279
42	75	35	4275-35-1813C	320650	1057250	229
42	75	35	4275-35-1814C	320575	1056555	207
42	75	35	4275-35-1816	320600	1056530	207
42	75	35	4275-35-1817	320575	1056750	233
42	75	35	4275-35-1821	321469	1060442	1216
42	75	35	4275-35-1822	321478	1060498	741
42	75	35	4275-35-4000	321824	1060399	761
42	75	35	4275-35-4001	321925	1060396	762
42	75	35	4275-35-4002	322029	1060401	761
42	75	35	4275-35-4003	322026	1059997	762
42	75	35	4275-35-4004	322193	1059894	760
42	75	35	4275-35-4005	322346	1059785	762
42	75	35	4275-35-4006	322424	1059558	761
42	75	35	4275-35-4007	322527	1059560	761
42	75	35	4275-35-4008	322625	1059558	763
42	75	35	4275-35-4009	323271	1059465	300
42	75	35	4275-35-4011	323485	1059572	299
42	75	35	4275-35-4012	323580	1059561	298
42	75	35	4275-35-4013	323719	1059167	298
42	75	35	4275-35-4014	323567	1059167	298
42	75	35	4275-35-4015	323121	1059062	761

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-4016	323124	1058964	762
42	75	35	4275-35-4017	323082	1058568	761
42	75	35	4275-35-4018	323172	1058522	763
42	75	35	4275-35-4019	323076	1058422	754
42	75	35	4275-35-4020	322993	1058420	300
42	75	35	4275-35-4021	323025	1058311	759
42	75	35	4275-35-4022	322978	1058210	759
42	75	35	4275-35-4023	322778	1058207	300
42	75	35	4275-35-4024	322775	1058112	299
42	75	35	4275-35-4025	322775	1058009	764
42	75	35	4275-35-4026	323075	1058009	299
42	75	35	4275-35-4027	322973	1057856	298
42	75	35	4275-35-4028	322673	1057915	762
42	75	35	4275-35-4029	322474	1057908	298
42	75	35	4275-35-4030	323027	1057547	301
42	75	35	4275-35-4031	322813	1056965	302
42	75	35	4275-35-4032	322466	1057109	763
42	75	35	4275-35-4033	322378	1057111	302
42	75	35	4275-35-4034	322379	1057308	299
42	75	35	4275-35-4035	322075	1057908	298
42	75	35	4275-35-4036	321774	1057813	298
42	75	35	4275-35-4037	321576	1057811	301
42	75	35	4275-35-4038	321776	1056912	302
42	75	35	4275-35-4039	321626	1056913	299
42	75	35	4275-35-4040	321325	1056708	301
42	75	35	4275-35-4041	321056	1056808	173
42	75	35	4275-35-4042	320675	1057809	301
42	75	35	4275-35-4043	320676	1056810	302
42	75	35	4275-35-4044	320572	1056760	302
42	75	35	4275-35-4045	320525	1056610	301
42	75	35	4275-35-4046	320629	1056358	299
42	75	35	4275-35-4048	320519	1055558	639
42	75	35	4275-35-4049	320196	1056735	301
42	75	35	4275-35-4050	322521	1058364	298
42	75	35	4275-35-4051C	320554	1056623	217
42	75	35	4275-35-4052C	322796	1058224	220
42	75	35	4275-35-4053	323089	1058308	300
42	75	35	4275-35-4054	322891	1058257	298
42	75	35	4275-35-4055	322789	1058259	297
42	75	35	4275-35-4056	322676	1058173	299
42	75	35	4275-35-4057	322062	1057821	298
42	75	35	4275-35-4058	321790	1056964	300
42	75	35	4275-35-4059	321710	1056987	299
42	75	35	4275-35-4060	321674	1056862	298
42	75	35	4275-35-4061	321362	1056856	297
42	75	35	4275-35-4062	321573	1056763	297
42	75	35	4275-35-4063	321776	1056812	298
42	75	35	4275-35-4064	321675	1056763	299
42	75	35	4275-35-4065	321716	1057220	299
42	75	35	4275-35-4066	320980	1057012	299
42	75	35	4275-35-4067	320678	1056957	299

**Table 3.3-1a
Moore Ranch Drill Holes**

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-4068	321026	1057479	298
42	75	35	4275-35-4069	320878	1057713	299
42	75	35	4275-35-4070	320775	1057809	300
42	75	35	4275-35-4071	320676	1057711	295
42	75	35	4275-35-4072	320126	1057302	296
42	75	35	4275-35-4138	320572	1056485	299
42	75	35	4275-35-4139	320487	1056646	299
42	75	35	4275-35-4140	322130	1060401	762
42	75	35	4275-35-4141	322200	1057842	295
42	75	35	4275-35-4142	322645	1058087	303
42	75	35	4275-35-4154	321801	1057356	300
42	75	35	4275-35-4156	321961	1057215	295
42	75	35	4275-35-4157	320586	1056926	301
42	75	35	4275-35-4290	320100	1057159	302
42	75	35	4275-35-4291	320100	1057061	302
42	75	35	4275-35-4325	320326	1057553	300
42	75	35	4275-35-4326	320621	1057559	400
42	75	35	4275-35-4327	321127	1057762	301
42	75	35	4275-35-4328	321045	1057956	300
42	75	35	4275-35-4329	321279	1057960	301
42	75	35	4275-35-4330	321476	1058058	301
42	75	35	4275-35-4331	321878	1057900	301
42	75	35	4275-35-4332	321824	1058101	301
42	75	35	4275-35-4333	321925	1058263	400
42	75	35	4275-35-4334	322076	1058212	400
42	75	35	4275-35-4336	322429	1058311	302
42	75	35	4275-35-4337	322780	1057853	297
42	75	35	4275-35-4338	322882	1057795	302
42	75	35	4275-35-4339	322878	1058329	402
42	75	35	4275-35-4340	323624	1059359	402
42	75	35	4275-35-4341	323479	1058758	401
42	75	35	4275-35-4342	323228	1058408	401
42	75	35	4275-35-4343	323379	1058359	400
42	75	35	4275-35-4344	322765	1056907	302
42	75	35	4275-35-4345	321889	1056519	301
42	75	35	4275-35-4346	321571	1055809	302
42	75	35	4275-35-4347	321731	1057501	302
42	75	35	4275-35-4348	321286	1056857	302
42	75	35	4275-35-4349	320970	1056808	302
42	75	35	4275-35-4382	322350	1060398	805
42	75	35	4275-35-IMW-1	321670	1057758	263
42	75	35	4275-35-IMW-2	321770	1057758	265
42	75	35	4275-35-IMW-3	321670	1057658	264
42	75	35	4275-35-IMW-4	321771	1057662	264
42	75	35	4275-35-KM1	323861	1059568	1159
42	75	35	4275-35-KM2	322291	1060188	952
42	75	35	4275-35-KM3	323757	1057163	400
42	75	35	4275-35-KM4	322304	1060477	748
42	75	35	4275-35-KM5	322347	1059875	748
42	75	35	4275-35-KM6	322014	1060194	760
42	75	35	4275-35-KM7	322615	1060200	760


Table 3.3-1a
Moore Ranch Drill Holes

Township	Range	Section	Hole	Easting	Northing	Depth
42	75	35	4275-35-KM8	321100	1059298	800
42	75	35	4275-35-KM9	321907	1060193	762
42	75	35	4275-35-KM10	322121	1060188	762
42	75	35	4275-35-KM11	322026	1060483	758
42	75	35	4275-35-KM12	322027	1059891	761
42	75	35	4275-35-MW-1	320102	1057971	279
42	75	35	4275-35-MW-2	322637	1057719	201
42	75	35	4275-35-MW-5	321453	1056691	218
42	75	35	4275-35-MW-6	323791	1058288	282
42	75	35	4275-35-MW-7	322537	1056311	198
42	75	35	4275-35-MW-10	320118	1059390	281
42	75	35	4275-35-MW-16	321713	1057701	264
42	75	35	4275-35-MW-17	321692	1057680	264
42	75	35	4275-35-MW-18	321719	1057678	264
42	75	35	4275-35-MW-19	321685	1057649	264
42	75	35	4275-35-OMW-1	320092	1057972	180
42	75	35	4275-35-OMW-2	322626	1057719	100
42	75	35	4275-35-PMW-1	321720	1057708	265
42	75	35	4275-35-PW-1	320195	1057997	275
42	75	35	4275-35-UMW-1	320113	1057971	339
42	75	35	4275-35-UMW-2	322645	1057720	280
42	75	35	4275-35-UMW-5	321780	1057708	260
42	75	35	4275-35-WW-1	323056	1055695	686
42	75	36	4275-36-4504	326990	1058011	990
42	75	36	4275-36-4505	330500	1058010	924

TABLE 3.3-1b
Historical Exploration Drill Holes Within the Proposed Moore Ranch Permit Area

Company	Type	Qtr	Qtr	Section	Township	Range	Hole Name	Date Drilled	Depth
Conoco, Inc.	LE39	NWNE		9	41	75	UM-1567-1	1978	120
Conoco, Inc.	LE39	NWNE		9	41	75	UM-1567-10	1979	160
Conoco, Inc.	LE39	NWNE		9	41	75	UM-1567-11	1979	160
Conoco, Inc.	LE39	NWNE		9	41	75	UM-1567-12	1979	160
Conoco, Inc.	LE39	NWNE		9	41	75	UM-1567-13	1979	160
Conoco, Inc.	LE39	NWNE		9	41	75	UM-1567-14	1979	160
Conoco, Inc.	LE39	NWNE		9	41	75	UM-1567-33	1979	160
Conoco, Inc.	LE39	NWNE		9	41	75	UM-1567-34	1979	160
Conoco, Inc.	LE39	NWNE		9	41	75	UM-1567-4	1979	160
Conoco, Inc.	LE39	NWNE		9	41	75	UM-1567-6	1979	160
Conoco, Inc.	LE39	NWNE		9	41	75	UM-1567-8	1978	160
Conoco, Inc.	LE39	NWNE		9	41	75	UM-1567-9	1979	120
Conoco, Inc.	LE39	NWNE		26	42	75	UL-1814-1	1977	800
American Nuclear Corp.	LE7	NENW		26	42	75	BETH 19-1	1978	840
American Nuclear Corp.	LE7	NENW		26	42	75	BETH 28-2	1978	840
American Nuclear Corp.	LE7	NESW		26	42	75	BETH 14-1	1980	900
American Nuclear Corp.	LE7	NESW		26	42	75	BETH 30-2	1978	320
American Nuclear Corp.	LE7	NWNW		26	42	75	BETH 19-2	1980	760
American Nuclear Corp.	LE7	NWSE		26	42	75	BETH 25-1	1980	960
American Nuclear Corp.	LE7	SESE		26	42	75	BETH 27-5	1980	760
American Nuclear Corp.	LE7	SESE		26	42	75	BETH 31-2	1980	760
American Nuclear Corp.	LE7	SESW		26	42	75	BETH 27-3	1978	860
American Nuclear Corp.	LE7	SWNW		26	42	75	BETH 23-1	1980	805
American Nuclear Corp.	LE7	SWSW		26	42	75	BETH 27-4	1978	840
American Nuclear Corp.	LE7	NESE		27	42	75	BETH 10-1	1980	820
American Nuclear Corp.	LE7	NWNW		27	42	75	BETH 2-1	1980	760
American Nuclear Corp.	LE7	SENE		27	42	75	BETH 6-1	1980	820

R. 75 W.



T.
42
N.

Moore Ranch Permit Boundary

28

28


27


5381
Windmill


Figure 3.3-25A

URANIUM ONE AMERICAS
MOORE RANCH PROJECT
Drill Hole Map A
SEC. 27, 28 T. 42 N., R. 75 W.
July 11, 2008


DRILL HOLE	DEPTH (FEET)	U3O8 (PPM)	DATE
5435	100	100	07/11/08
5435	200	100	07/11/08
5435	300	100	07/11/08
5435	400	100	07/11/08
5435	500	100	07/11/08
5435	600	100	07/11/08
5435	700	100	07/11/08
5435	800	100	07/11/08
5435	900	100	07/11/08
5435	1000	100	07/11/08







P. 75 W.



T. 41 N.

Moore Ranch Permit Boundary

3: 5.6 MI.

Figure 3-258

URANIUM ONE AMERICAS
 MOORE RANCH PROJECT
 2003 State Map 9
 20.4 x 20.4 x 20.4 x 20.4
 20.4 x 20.4 x 20.4 x 20.4



R. 75 W.

R. 74 W.




Figure 53-007
 GRAND OIL AMERICAS
 WOOD DANCE PROJECT
 Well Site Map 2
 11/11/11