#### Norris, Michael

From:

Norris, Michael

Sent: To: Wednesday, September 12, 2012 2:00 PM Hay, Michael; Louden, Patrick; Elkmann, Paul

Cc: Subject: Guerra, Gilbert; Anderson, Joseph; Laughlin, Jeff; Thaggard, Mark Region IV Resident Inspector Quarterly Inspection Report Feeders

Attachments:

Wolf Creek IR Feeder Memo 03 2012.docx; ANO IR Feeder Memo 03 2012.docx; Columbia Qrtly IR Feeder Memo 03 2012.docx; Cooper IR Feeder Memo 03 2012.docx; Diablo Canyon IR Feeder Memo 03 2012.docx; Palo Verde IR Feeder Memo 03 2012.docx; River Bend IR Feeder Memo 03 2012.docx; San Onofre IR Feeder Memo 03 2012.docx; South Texas Project IR Feeder Memo 03 2012.docx; Waterford IR Feeder Memo 03 2012.docx

Attached are feeder inputs to the Region IV Resident Inspector Quarterly Inspection Reports. These feeder inputs document NSIR staff reviews of the Emergency Plan and Emergency Plan Implementing Procedures that were submitted to the NRC Document Control Desk during the 3<sup>nd</sup> Quarter CY 2012.

If you have any questions regarding the content of these feeder reports, please contact either Mike Norris (301) 415-4098 or Jeff Laughlin (301) 415-1113.

Michael B. Norris (Acting Chief)
Team Leader
Division of Preparedness and Response
Office of Nuclear Security and Incident Response
U.S. Nuclear Regulatory Commission

# OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE INPUT TO INTEGRATED REPORT 05000528/2012004, 05000529/2012004 AND 05000530/2012004 FOR PALO VERDE NUCLEAR GENERATING STATION UNITS 1, 2 AND 3

The following is a feeder for integration into the Palo Verde Nuclear Generating Station Inspection Report Nos 05000528/2012004, 05000529/2012004 and 05000530/2012004. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 3<sup>rd</sup> Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR

(301) 415-4098

## TITLE PAGE

in the first part of the part of

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

#### REPORT DETAILS

#### REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

#### a. Inspection Scope

. I fine a brown six

To by Way is project or gifted in Prog. Table 18.

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) and the Emergency Plan located under ADAMS accession number ML12200A022 and ML12202A643 as listed in the Attachment.

The licensee determined that in accordance with 10 CFR 50.54(q), the changes made in the revisions resulted in no reduction in the effectiveness of the Plan, and that the revised Plan continued to meet the requirements of 10 CFR 50.47(b) and Appendix E to 10 CFR Part 50. The NRC review was not documented in a safety evaluation report and did not constitute

and the state of the first all and the state of

#### b. Findings

No findings were identified.

## ATTACHMENT

### SUPPLEMENTAL INFORMATION

## KEY POINTS OF CONTACT

#### Licensee Personnel

Manager State of the State of t

N/A

### LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

and distribute a comparison of the action of the distribute of the comparison of the

None.

#### LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

#### Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

Emergency Plan, Revision 48
EP-0904, "ERO/ERF Activation and Operation," Revision 2
EP-0905, "Protective Actions," Revision 3

The last the control of the control

The first open by the second of the second of the dispersion of the first of the first of the second of the second

表示大体。这些66个,这是的现在分词并有多多数。AMO (1995)的基础数据。

## OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE INPUT TO INTEGRATED REPORT 05000458/2012004 FOR RIVER BEND STATION UNIT 1

The following is a feeder for integration into the River Bend Station Inspection Report No. 05000458/2012004. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 3<sup>rd</sup> Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR

(301) 415-4098

#### TITLE PAGE

1994年 - 1994年

agram in the agram of the control of the control of the control of

TO SERVICE AND THE RESIDENCE OF THE SERVICE AND THE SERVICE AN

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

## REPORT DETAILS

#### REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

a. Inspection Scope

e sina problem styrm mesta into a compar-

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) and the Emergency Plan located under ADAMS accession number ML12194A042 as listed in the Attachment.

The licensee determined that in accordance with 10 CFR 50.54(q), the changes made in the revisions resulted in no reduction in the effectiveness of the Plan, and that the revised Plan continued to meet the requirements of 10 CFR 50.47(b) and Appendix E to 10 CFR Part 50. The NRC review was not documented in a safety evaluation report and did not constitute

and the second of the contract of the second of the second

#### b. Findings

No findings were identified.

#### ATTACHMENT, ATTACH

e non cere entre la comunicación de comunicación el Artire, confluiro ficamiente y tres fareces la comunicació

#### SUPPLEMENTAL INFORMATION

#### KEY POINTS OF CONTACT

#### Licensee Personnel

N/A

#### LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

ant the contract the property of the contract of

None.

#### LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

EIP-2-001, "Classification of Emergencies," Revision 22

order of the process of the second

popular of a policia of the contract of the second second

ATTICK TIP FOR FOUR DECKES AND DISTRIBUTE

TARREST STATE OF THE STATE OF T

o de forma de la tropa de la companio de la companio de la compaña de forma de la compaña de la compaña de la La compaña de la compaña d

# OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE INPUT TO INTEGRATED REPORT 05000361/2012004 AND 05000362/2012004 FOR SAN ONOFRE NUCLEAR GENERATING STATION UNITS 2 AND 3

The following is a feeder for integration into the San Onofre Nuclear Generating Station Inspection Report Nos. 05000361/2012004 and 05000362/2012004. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 3<sup>rd</sup> Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR

(301) 415-4098

## TITLE PAGE

a the car after a foundation

Define a Computation of the Computatio

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

## REPORT DETAILS

#### 1. REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

#### a. Inspection Scope

Served to the Late Control of Served to

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) and the Emergency Plan located under ADAMS accession number ML121850028, ML12202A642 and ML12202A639 as listed in the Attachment.

The licensee determined that in accordance with 10 CFR 50.54(q), the changes made in the revisions resulted in no reduction in the effectiveness of the Plan, and that the revised Plan continued to meet the requirements of 10 CFR 50.47(b) and Appendix E to 10 CFR Part 50. The NRC review was not documented in a safety evaluation report and did not constitute

The Spatial American Architecture (1996) and the contract of the Spatial Architecture (1994) and the Architecture (1994)

expenses and the process of the control of the cont

#### b. Findings

No findings were identified.

#### ATTACHMENT

#### SUPPLEMENTAL INFORMATION

### KEY POINTS OF CONTACT

ALL THE MEAN OF A REPORT OF A SECOND PARTY.

#### Licensee Personnel

N/A

### LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

None.

#### LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

#### Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

Emergency Plan, Revision 32

SO123-VIII-1, "Recognition and Classification of Emergencies," Revision 37

SO123-VIII-10.1, "Station Emergency Director Duties," Revision 23

EPSD-1, "Emergency Action Level Technical Bases," Revision 6

EPSD-1 5.1, "Section 5.1-Category A - Abnormal Rad Levels/Radiological Effluent," Revision 4

EPSD-1 5.4, "Section 5.4-Category F - Fission Product Barrier Degradation," Revision 5

EPSD-1 5.5, "Section 5.5-Category H -- Hazards and Other Conditions Affecting Plant Safety,"

Revision 5

EPSD-1 5.6, "Section 5.6-Category S - System Malfunction," Revision 6

and the could be an interest to be because the contract of the back to be because the beginning the course

ranka ka ka ing mangali dan katalah ka ka

to the second the second of the second of the second of

# OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE INPUT TO INTEGRATED REPORT 05000498/2012004 AND 05000499/2012004 FOR SOUTH TEXAS PROJECT UNITS 1 AND 2

PART OF THE PART O

The following is a feeder for integration into the South Texas Project Inspection Report Nos. 05000498/2012004 and 05000499/2012004. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 3<sup>rd</sup> Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

Diff of the fire that is a set a court of a fire with residual for some fire processing in the course of

the safe in the case of the safe of the first of the safe of the s

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR (301) 415-4098

#### TITLE PAGE

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

#### REPORT DETAILS

#### REACTOR SAFETY

W-11. 2 1 . 1 . 1

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

#### Inspection Scope

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) and the Emergency Plan located under ADAMS accession number ML12208A325 as listed in the Attachment.

The licensee determined that in accordance with 10 CFR 50.54(q), the changes made in the revisions resulted in no reduction in the effectiveness of the Plan, and that the revised Plan continued to meet the requirements of 10 CFR 50.47(b) and Appendix E to 10 CFR Part 50. The NRC review was not documented in a safety evaluation report and did not constitute

The first term of the first than the first the first term of the f

#### b. Findings

No findings were identified.

## ATTACHMENT

#### SUPPLEMENTAL INFORMATION

#### **KEY POINTS OF CONTACT**

#### Licensee Personnel

production and project the second

N/A

### LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

The same of the transfer of the transfer of

None.

#### LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

#### Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

Emergency Plan, ICN #20-11

OERP01-ZV-EF01, "EOF Director," Revision 14

OERP01-ZV-IN01, "Emergency Classification," Revision 9

OERP01-ZV-OF03, "Alternate TSC/OSC," Revision 0

OERP01-ZV-SH01, "Shift Manager," Revision 26

ala, signer agree on the executions along

TO DESCRIPTION OF THE PROPERTY OF THE

ากระบาง จะทำการสมาสเรารับ คายกระบางกระทำการสมาชาก (เปลือดการ เการสมาชาวิทยาลา

# OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE INPUT TO INTEGRATED REPORT 05000382/2012004 FOR WATERFORD STEAM ELECTRIC STATION UNIT 3

The following is a feeder for integration into the Waterford Steam Electric Station Inspection Report No. 05000382/2012004. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 3<sup>rd</sup> Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR (301) 415-4098

#### TITLE PAGE

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

### REPORT DETAILS

The second plat is still a first that the

The state of the s

#### 1. REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

#### a. Inspection Scope

To the Mindel Made Love Stower Commit

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) and the Emergency Plan located under ADAMS accession number ML12181A532 and ML12201A134 as listed in the Attachment.

The licensee determined that in accordance with 10 CFR 50.54(q), the changes made in the revisions resulted in no reduction in the effectiveness of the Plan, and that the revised Plan continued to meet the requirements of 10 CFR 50.47(b) and Appendix E to 10 CFR Part 50. The NRC review was not documented in a safety evaluation report and did not constitute

and a major consist of the contract of the con

#### b. Findings

No findings were identified.

and the second of the second

a comparate against the comparate

and Late Annual of the specific and the Late of the control of the

#### **ATTACHMENT**

하는 사람들이 얼마 요즘 사람들이 가장 하지만 사람들이 얼마를 살아내려면 살아 되었다.

#### SUPPLEMENTAL INFORMATION

## KEY POINTS OF CONTACT

#### Licensee Personnel

N/A

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

None.

#### LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

THE REPORT OF THE RESERVE OF THE RES

Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

Emergency Plan, Revision 43 EP-001-001, "Recognition and Classification of Emergency Conditions," Revision 30

MATERIAL STREET, A. A. A. C. C. C.

At a propring through the propring of the proprint of a file of the field to the third of the contract of

# OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE INPUT TO INTEGRATED REPORT 05000482/2012/004 FOR WOLF CREEK GENERATING STATION

The following is a feeder for integration into the Wolf Creek Generating Station Inspection Report No. 05000482/2012004. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 3<sup>rd</sup> Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR

(301) 415-4098

#### TITLE PAGE

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

#### REPORT DETAILS

#### REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

### a. Inspection Scope

Tark parties falls a tree of the start

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) and the Emergency Plan located under ADAMS accession number ML12187A218 as listed in the Attachment.

The licensee determined that in accordance with 10 CFR 50.54(q), the changes made in the revisions resulted in no reduction in the effectiveness of the Plan, and that the revised Plan continued to meet the requirements of 10 CFR 50.47(b) and Appendix E to 10 CFR Part 50. The NRC review was not documented in a safety evaluation report and did not constitute

#### b. Findings

No findings were identified.

## ATTACHMENT COMMENT COM

#### SUPPLEMENTAL INFORMATION

#### KEY POINTS OF CONTACT

#### Licensee Personnel

N/A

### LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

THE PERSON OF TH

None.

#### LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

#### Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

AP 06-002, "Radiological Emergency Response Plan," Revision 12 EPP 06-002, "Technical Support Center Operations," Revision 32 EPP 06-005, "Emergency Classification," Revision 5

I give a series of the set property

en la región de la seguida de la compania de la compaña Esta de la compaña de la c La compaña de la compaña d

provide the control of the provide the control of t

# OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE INPUT TO INTEGRATED REPORT 05000313/2012004 AND 05000368/2012004 FOR ARKANSAS NUCLEAR ONE UNITS 1 AND 2

The following is a feeder for integration into the Arkansas Nuclear One Inspection Report Nos. 05000313/2012004 and 05000368/2012004. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 3<sup>rd</sup> Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT:

Michael Norris, NSIR/DPR

(301) 415-4098

#### TITLE PAGE

The second secon

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

## REPORT DETAILS

entra a regional de la compansión de la co

#### REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

#### a. Inspection Scope

red with the CINCAP A Committee 2

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) and the Emergency Plan located under ADAMS accession number ML12180A530 as listed in the Attachment.

The licensee determined that in accordance with 10 CFR 50.54(q), the changes made in the revisions resulted in no reduction in the effectiveness of the Plan, and that the revised Plan continued to meet the requirements of 10 CFR 50.47(b) and Appendix E to 10 CFR Part 50. The NRC review was not documented in a safety evaluation report and did not constitute

and the second term of the control of the state of the control of

was to some the sale of the first of the second was the first of the second second second second second second

#### b. Findings

No findings were identified.

#### **ATTACHMENT**

the feature of the large and feature at the stage of the feature.

A comparation of the Cartina C

## SUPPLEMENTAL INFORMATION

## KEY POINTS OF CONTACT

Licensee Personnel

21...

N/A .

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

None.

#### LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

一种产品,通过"加速"的数据,使为对外交换

Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

OP-1903.010, "Emergency Action Level Classification," Revision 45

Color Call Market Specific Market Specific Specific

The Decree by the compage property of the series

to the street with the street of the significant will be set in the second

## OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE INPUT TO INTEGRATED REPORT 05000397/2012004 FOR COLUMBIA GENERATING STATION

The following is a feeder for integration into the Columbia Generating Station Inspection Report No. 05000397/2012004. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 3rd Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT:

Michael Norris, NSIR/DPR

(301) 415-4098

#### TITLE PAGE

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

#### REPORT DETAILS

#### 1. REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

#### a. Inspection Scope

, , ski se say Zavari i je i jekirin

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) and the Emergency Plan located under ADAMS accession numbers ML12096A337, ML12173A171, ML121850027 and ML12198A397 as listed in the Attachment.

The licensee determined that in accordance with 10 CFR 50.54(q), the changes made in the revisions resulted in no reduction in the effectiveness of the Plan, and that the revised Plan continued to meet the requirements of 10 CFR 50.47(b) and Appendix E to 10 CFR Part 50. The NRC review was not documented in a safety evaluation report and did not constitute

#### b. Findings

No findings were identified.

#### ATTACHMENT

They were the second of the se

ாது செரி உள்ள நுத்தை சுநார் சிரி நாகிக அரசி **எனி** கிறு சிறு சாகி <sup>68</sup>, கோது நகரிக

#### SUPPLEMENTAL INFORMATION

#### KEY POINTS OF CONTACT

#### Licensee Personnel

Elmer Dumlao, System Engineer
Roger Fahnestock, Manager, Emergency Preparedness
Chuck Forrester, Emergency Planner
Rick Garcia, Licensing Engineer
Don Gregoire, Manager, Regulatory Affairs
Tim Powell, Former Emergency Planner

#### LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

None.

#### LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

#### Section 1EP4: 1 Emergency Action Level and Emergency Plan Changes

PPM 13.1.1, "Classifying the Emergency," Revisions 41, 42

PPM 13.1.1A, "Classifying the Emergency - Technical Bases," Revision 25

PPM 13.4.1, "Emergency Notifications," Revision 41

PPM 13.10.2, "TSC Manager Duties," Revision 34

PPM 13.10.9, "Operations Support Center Manager and Staff Duties," Revision 48

Columbia Generating Station Emergency Plan, Revision 57

They the couple that so it is the birth of a file of a given by the color of the co

# OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE INPUT TO INTEGRATED REPORT 05000298/2012004 FOR COOPER NUCLEAR STATION

The following is a feeder for integration into the Cooper Nuclear Station Inspection Report No. 05000298/2012004. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 3<sup>rd</sup> Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR (301) 415-4098

#### TITLE PAGE

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

#### REPORT DETAILS

#### 1. REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

#### a. Inspection Scope

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) and the Emergency Plan located under ADAMS accession number ML12199A019 as listed in the Attachment.

The licensee determined that in accordance with 10 CFR 50.54(q), the changes made in the revisions resulted in no reduction in the effectiveness of the Plan, and that the revised Plan continued to meet the requirements of 10 CFR 50.47(b) and Appendix E to 10 CFR Part 50. The NRC review was not documented in a safety evaluation report and did not constitute

If the Ellips of the property of the second control of the second

and the second of the second o

#### b. Findings

No findings were identified.

#### **ATTACHMENT**

### SUPPLEMENTAL INFORMATION

#### KEY POINTS OF CONTACT

#### Licensee Personnel

N/A

#### LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

在中国中国的大学,我们在4000年间,就是一个企业,不是一个企业的企业,在1980年间的企业,在1980年间,在1980年间,1980年间,1980年间,1980年间,1980年间,1980年间,1980年间,1980年

None.

#### LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

Emergency Plan, Revision 60

and the problem of the complete contract the section of the problem of the contract of the con

and the responsibility of the Carlot Service Services for the first of the contract of the con

v a technica de escapa da que caractería de como activado a decida de como de como de como de como de como de c

Manager and the real of the state of the sta

The second secon

# OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE INPUT TO INTEGRATED REPORT 05000275/2012004 AND 05000323/2012004 FOR DIABLO CANYON NUCLEAR POWER PLANT UNITS 1 AND 2

The following is a feeder for integration into the Diablo Canyon Nuclear Power Plant Inspection Report Nos. 05000275/2012004 and 05000323/2012004. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 3<sup>rd</sup> Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR

(301) 415-4098

#### TITLE PAGE

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

#### REPORT DETAILS

#### REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

#### a. Inspection Scope

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) and the Emergency Plan located under ADAMS accession number ML12200A133 as listed in the Attachment.

The licensee determined that in accordance with 10 CFR 50.54(q), the changes made in the revisions resulted in no reduction in the effectiveness of the Plan, and that the revised Plan continued to meet the requirements of 10 CFR 50.47(b) and Appendix E to 10 CFR Part 50. The NRC review was not documented in a safety evaluation report and did not constitute

#### b. Findings

No findings were identified.

#### **ATTACHMENT**

#### SUPPLEMENTAL INFORMATION

#### **KEY POINTS OF CONTACT**

#### Licensee Personnel

N/A

#### LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

None.

#### LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

#### Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

Emergency Plan, Section 4: Revision 4, Change 12

Emergency Plan, Section 6: Revision 4, Change 11

Emergency Plan, Section 7: Revision 4, Change 16

Emergency Plan, Section 8: Revision 4, Change 11

Emergency Plan, Appendix D, Category H: Revision 4, Change 2

EP G-1, "Emergency Classification and Emergency Plan Activation," Revision 42

EP EF-3, "Activation and Operation of the Emergency Operations Facility," Revision 35

EP EF-11, "Operation of Alternate Emergency Response Facilities," Revision 0

that keather of the classes beginning to