U.S. NUCLEAR REGULATORY COMMISSION	Date:
------------------------------------	-------

09/18/12

09:20am

Ι

Time:

TELEPHONE CONVERSATION RECORD

Mail Control or Report No(s).	577810	License No(s).	06-31418-01	Docket No(s).	03038340	
Name of Licensee: Name of Participant(s): Telephone No. Subject: (NOTE: This will be used as the Documents Title in ADAMS)	Lisa Shor (860) 482	cut Oncology & Herr nsky, Business Adm -5384 ext. 230 I information for tern	ninistrator	st		
 NRC staff contacted the licensee to clarify the following information provided in a deficiency response dated September 12, 2012: 1. Verification that the licensee is no longer in operation. Lisa verified that they have not provided any PET services since June 15, 2012. 2. The leak test record provided did not include readings for three Germanium-68 rod sources. I asked Lisa to provide the leak tests for these. 3. The Cs-137 source (Model GF-0008, SN 1181-63-82) listed on the leak test and the inventory records showed different activities (0.5 mCi and 0.5 µCi). I asked Lisa to verify the actual activity of the source. Lisa agreed to provide this information by COB today. 						
Action Required: Issue termination						
Document Availability: X Non-Sensitive Sensitive – Privacy Act/ PI Immediate Release SUNSI Review Completed	L	Publicly Available Non-Sensitive Cop Sensitive – Internal X Normal Release Date:09/26/2012 M. Abogunde		Non-Publicly Available Sensitive- Proprietary Sensitive – Security-Related Delayed Release Date: Document Accession #:	I	