Change Notice 13-017				
	DELETED:		TRANSMITTED:	
	<u>Number</u>	<u>Date</u>	<u>Number</u>	<u>Date</u>
1.	IMC 0612 App D	10/28/11	IMC 0612 App D	08/13/13
2.	IMC 2516	02/18/05	IMC 2516	08/13/13
3.			IP 62712	08/13/13
5.	IP 65001	10/03/07	IP 65001	08/13/13
4.	IP 71152	01/31/13	IP 71152	08/13/13

TRAINING: No.

REMARKS:

IMC 0612 App D, "Documenting Problem Identification and Resolution Biennial Team Inspections (IP 71152)," has been revised to address regional reliability effort change recommendations. Removed sample inspection reports for future incorporation into IMC 0612 Exhibit 3.

IMC 2516, "Policy and Guidance for the License Renewal Inspection Program," has been revised to update the division and branches, include additional definitions, include guidance on timely renewal applications and remove the Region Notification of Plant Readiness for License Renewal and the Sample License Renewal Inspection Letter.

IP 62712, "Part 52, Maintenance Rule," is an initial issuance to support inspections of construction programs described in IMC 2504, "Inspection of Construction and Operational Programs."

IP 65001, "Inspections of Inspections, Tests, Analyses and Acceptance Criteria (ITAAC) Related Work," has been revised as a complete re-write to address current inspection program policies.

IP 71152, "Problem Identification and Resolution," has been revised to relocate some documentation guidance related to the biennial PI&R inspection contained in Section 03.07 of this IP to IMC 0612 App D to eliminate redundancy and possible guidance conflicts.

DISTRIBUTION: Standard.

**END**