



**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

*DBB*

April 14, 1981

DJS LTR #81-301

James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Reportable Occurrence Report #81-15/03L-0, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.

*DJ Scott*

D. J. Scott  
Station Superintendent  
Dresden Nuclear Power Station

DJS:lg

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
U.S. NRC, Document Mgt. Branch  
File/NRC

APR 17 1981





Commonwealth Edison

# DEVIATION REPORT

DVR NO.	STA	UNIT	YEAR	NO.
D-12	-	2	-	81-28

<b>PART 1</b> TITLE OF DEVIATION		OCCURRED	
Semi-Annual Cardox System Surveillance		3-19-81	1000
		DATE	TIME
SYSTEM AFFECTED 4100	PLANT CONDITIONS	TESTING	
Fire Protection Cardox System	U-2 Refuel Outage	<input type="checkbox"/>	<input checked="" type="checkbox"/>
MODE U-3 Run	PWR (MWT) 2510	YES	NO
LOAD (MWE) 825			
DESCRIPTION OF EVENT			
Per Tech. Spec. 4.12.A.1 the heat detectors on the Cardox System which protect the Diesel Generators must be checked semi-annually - this surveillance was not completed by the latest due date of February 13, 1981			
DESCRIPTION OF CAUSE			
OTHER APPLICABLE INFORMATION			
EQUIPMENT FAILURE	DR NO.	WR NO.	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	N/A	11679	
M. Dillon - Station Fire Marshal		3-19-81	
RESPONSIBLE SUPERVISOR		DATE	

<b>PART 2</b> OPERATING ENGINEERS COMMENTS
None

TYPE OF DEVIATION REPORTABLE OCCURRENCE	EVENT OF POTENTIAL PUBLIC INTEREST	TECH SPEC VIOLATION	NON-REPORTABLE OCCURRENCE	ANNUAL REPORTING	SAFETY-RELATED WR ISSUED
<input type="checkbox"/> 14 DAY <input checked="" type="checkbox"/> 30 DAY	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
NOTIFICATION 6.6.B.2.C.					
REPORTABLE OCCURRENCE NUMBER	ACTION ITEM NO.	PROMPT ON-SITE NOTIFICATION			
81-15/03L-0		R. M. Ragan TITLE DATE 3-19-81 TIME 1600			
24-HOUR NRC NOTIFICATION		PROMPT OFF-SITE NOTIFICATION			
<input type="checkbox"/> TPH	N/A	F. Palmer TITLE DATE 3-20-81 TIME 11:53			
<input type="checkbox"/> TGM	N/A	TITLE DATE TIME			
RESPONSIBLE COMPANY OFFICER INFORMED OF 10CFR21 CONDITIONS AND THEIR REPORT TO NRC		TITLE DATE TIME			
REVIEW AND COMPLETED		E. Budzichowski OPERATING ENGINEER		3-19-81 DATE	

ACCEPTANCE BY STATION REVIEW AS REQUIRED

DATE: 4/14/81

RESOLUTION APPROVED AND AUTHORIZED FOR DISTRIBUTION:

J. Brunner John [unclear]  
4/14/81 4/12/81

Douglas [unclear] 4/15/81  
STATION SUPERINTENDENT DATE