, , , ,	•	• •			*	
NRC FORM 195		U.S. NU	CLEAR R	EGULATORY COMPOSIO	DOD DOC	SO-335
NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL					: FILI	E NUMBER NCIDENT REPORT
TO: FROM:					. DAT	
Mr. W. G. McDonald		Florida Power & Light Company / Miami, Florida				5/19/77
		A. D. Schmi			DAI	5/23/77
		PROP INPUT FORM			NUN	ABER OF COPIES RECEIVED
	SSIFIED	-	• =			· · ·
DESCRIPTION	. К	·	ENCLOS	URE	•	
		•				· · · · ·
PLANT NAME: St. Lucie Unit No. 1 T RJL	ONOT F		con not con on	ference memorandu ification re repo cerning a leak ap line 1"-SI-228 on in containment.	um doc ortabl opéari n Safe	
RJL		• .		SEND DIRECTLY		RE IS INVOLVED EGER/J. COLLINS
DDANOU OUTDDA	71014	FOR ACTION/		IATION		
BRANCH CHIEF: W/3 CYS FOR ACTION	ZIEM.	4,070	╏─╎──			
LIC. ASST.:	D1665					
W/ CYS ACRS /GCYS HOLDING/	SENT AS	CAT (3				
REG_FILE		INTERNAL D		JTION		
INRC PDR		4				
I & E (2)	•					
MIPC SCHROEDER/IPPOLITO			┨━━-┨╼━╼━			
HOUSTON			<u> </u>			•
NOVAK/CHECK						
GRIMES			┟╌┤──			
BUTLER						
HANAUER						•
TEDESCO/MACCARY			┨			
EISENHUT BAER			┼╾┼╾╴			<u></u>
SHAO				e		· · · · · · · · · · · · · · · · · · ·
VOLLMER/BUNCH		·····		•		
KREGER/J. COLLINS			┨━-┨━──			۰
			╏━┥──			
<u> </u>	EXTERNAL	DISTRIBUTION	<u></u>	-		CONTROL NUMBER
LPDR: FT. Piegee FLA.				·····		A0 4
-NSIC:			<u> -</u>			77145000
<u>_</u>		······				771450084

NRC FORM 195 (2-76)

st.

· · · · · ·

±

• × • ۰. ۲

`. , , ,

1. 1. 2000 - 200 - 200 1. 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000 - 2000

đ **N N**

.

• •

đ •



May 19, 1977

PRN-LI-77-153

Regulatory Docket File

Mr. W. G. McDonald, Director
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. McDonald:

RE: St. Lucie Unit 1 Docket No. 50-335 Reportable Occurrence

On May 11, 1977, we notified the Region II Office of Inspection and Enforcement of a reportable occurrence at St. Lucie Unit 1. In accordance with Regulatory Guide 10.1, two (2) copies of the telephone conference memorandum documenting our notification of Region II are attached.

Very truly yours,


Vice President

Power Resources

MAS/pm

Attachment

cc: Robert Lowenstein, Esquire





.

Ð

•

• •

• •

• • • •

.

, **.**

• • · · •

. .

To: R.C. Lewis FLOPER & LIGHT COMPANY FROM: St. LUCIE PLANT. TELEPHONE CONFERENCE MEMORANDUM

DATE 5/11/77 INCOMING OUTGOING WITH MR. RC Lewis OF THE NRC M. Harris OF THE St Frice Plant Mana WITH MR. K _____TIME 2:00 pm poman COPIES TO: $\mathcal{M}Q$ Schnudt - CO Woody :_____COST _____ Benan CHARGE ____ SUBJECT Jine 1-51-228 Pressure Boundary Lea kages FILE LER- 335-77-29 DETAILS OF CONFERENCE:__ that a leak has Mr. Harris notilied Mr. Lewiss appeared in a fillet weld an line 1"-SI-228 and Salaty Injection Header 1A2 in containment. The unit was placed in a cold shut low condition of this is considered Pressure Boundary Leakage and ia being reported under Rea. Guides 1.16 Section 2.a.3 as prompt reportable. This leak appears to ber the same tuss of problem that accurred ional testing FI 1975 deisena He mainaring is evaluating the leak and line restr this headers. The three other SI Seaders have same type of drain linear satisistas and are als being evaluated CC: ADS SIGNATURE KNAMIN

Trees States States

***** *

مر الإسلام المراجع الم المراجع المراجع

• ,

FROM: St. LUCIE PLANT FLORIDA POWER & LIGHT COMPANY TELEPHONE CONFERENCE MEMORANDUM INCOMING OUTGOING DATE 5/11/77. WITH MR. RC Leiner OF THE NRC WITH MR. K. M. Harris OF THE At Frice Flant Manage COPIES TO: Ma Shoppmans, ______ TIME 2:00 pm a. Q. Schmidt - C.O Wordy . :_____COST_ J.L Benson CHARGE _____ SUBJECT Jine 1-51-228 Treesus Boundary Las kages FILE LER - 335-77-29 DETAILS OF CONFERENCE: Mr. Harris notilied the Lewis that a leak for appeared in a fillet weld in lines 1"-SI-228 and Talety Injection Beader 1A2 in containment. The unit was placed in a cold shutdown condition of this is considered Pressure Boundary & enhance and ic being reported under Reg. Suides 1.16 Section, 2.a.3 as prompt reportable. This leak appears to ber the same type of problem that accurred in 1975 during Hat Functional testing Fled Carginaring is evaluating the look and line restraints for this header. The three other SI Headers have. same type of drain lines satisists and are also leing evaluated. CC ADS. SIGNATURE K inno

1911 MAY 23 PM 12 22

لال

where it

1

Reperved document Processing unit