

REGULATORY DOCKET FILE COPY

ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.

TELEPHONE
AREA CODE 718 546-2700

August 3, 1978

Mr. Boyce H. Grier, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

STRIBUTION
STANCES SHIT
STANCES
STANCES
STANCES
STANCES

Subject: LER 78-006/03L-0, Main steam line snubbers, positions MS146 top and bottom

R. E. Ginna Nuclear Power Plant, Unit No. 1

Docket No. 50-244

Dear Mr. Grier:

In accordance with Technical Specifications, Article 6.9.2.b.(2) operation in a degraded mode permitted by a limiting condition for operation, the attached report of Reportable Occurrence 78-006, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

L. D. White, Jr.

Attachment

cc: Director, IE, Washington (30) Mr. William G. McDonald (3)

782230094′

A002/1

24 .	CAR 1192 & 1196)
^	. CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	N Y R E G 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 5 S LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 2 4 4 7 0 7 1 3 7 8 8 0 8 0 8 7 8 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During snubber inspection position MS146 (bottom) was found with low accumulator
03	level. After adding and later rechecking level, snubber unit along with unit in
0 4	position MS146 (top) were replaced for maintenance. When tested both units failed to
0 5	lock up in compression and tension modes. (T.S.3.13.1).
0 6	
0 7	
08	9 80
0 9 7 8	SYSTEM CAUSE SUBCODE COMPONENT CODE SUBCODE SUBCODE H B 11 E 12 B 13 S U P O R T 14 D 15 Z 16 SEQUENTIAL OCCURRENCE REPORT REVISION
110	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
	tube, piston, piston shaft and shaft seal on each unit. Top unit had broken spring.
	Both units are Bergen-Paterson model HSSA-30. They were replaced with tested
1 2	spares. Inspection of snubbers will be as dictated in schedule given in Technical
1 3	Specifications.
1 5	FACILITY % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 28 1 0 0 29 NA B 31 Surveillance of snubbers
	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34) NA
1 7 7 8	NUMBER TYPE DESCRIPTION (39) O O O O O O O O O O O O O O O O O O O
1 8	NUMBER DESCRIPTION (41) [0 0 0 40 NA 9 11 12 80
1 9 7 8	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA
	9 10 80
2 0	PUBLICITY ISSUED DESCRIPTION 45 NRC USE ONLY PHONE: 716/546-2700, ext. 291-215

19 06/14/ns

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS) DISTRIBUTION FOR INCOMING MATERIAL

REC: GRIER B H

ORG: WHITE L D

NRC

ROCHESTER GAS & ELEC

DOCBATE: 06/06/78 DATE RCVD: 06/12/79

DOCTYPE: LETTER

NOTARIZED: NO

COPIES RECEIVED

LTR 1 ENCL 1

SUBJECT: FORWARDING SUPPLEMENTAL LICENSEE EVENT REPT (RO 50-244/77-007) ON 06/29/77 CONCERNING DURING TEST C SI PUMP FAILED TO START FROM BUS 14 BREAKER ON 2

PLANT NAME: RE GINNA - UNIT 1

REVIEWER INITIAL:

DISTRIBUTOR INITIAL:

************ DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *************

INCIDENT REPORTS

*(DISTRIBUTION CODE A002) ***

FOR ACTION:

BR CHIEF ORB#2 BC**W/4 ENCL

INTERNAL:

EXTERNAL:

REG_FICE**W/ENCL I & E**W/2 ENCL

I & C SYSTEMS BR**W/ENCL

NOVAK/CHECK**W/ENCL AD FOR ENG**W/ENCL HANAUER**W/ENCL

AD FOR OPER TECH**W/ENCL

ENGINEERING BR**W/ENCL KREGER/J. COLLINS**W/ENCL

K SEYFRIT/IE**W/ENCL

LPDR'S

ROCHESTER, NY**W/ENCL

TIC**W/ENCL NSIC**W/ENCL

ACRS CAT B**W/16 ENCL

NRC PDR**W/ENCL MIPC**W/3 ENCL

EMERGENCY PLAN BR**W/ENCL

EEB**W/ENCL

PLANT SYSTEMS BR**W/ENCL

'AD FOR PLANT SYSTEMS**W/ENCL

REACTOR SAFETY BR**W/ENCL VOLLMER/BUNCH**W/ENCL

POWER SYS BR**W/ENCL

DISTRIBUTION: SIZE: 1P+1P

LTR 45

CONTROL NBR:

781650068

THE END

UNITED STATES NUCLEAR REGULATORY COMMISDOC DAILY ACCESSION LIST

05/04/78

FILE LEVELS DOC. DATE		05/04/78	
	DOC. DATE	•	
STN-50-484 NORTHERN S 50 484 C	STATES POWER COMP 02/22/78	PANY TYRONE #1 ACCESSION NBR: 77346-0280 DOCUMENT TYPE: MEMO DOCUMENT SIZE: 1P DOCKET DATE: REPORT NBR: RECP: CARLSON R T ORG: REINMUTH G W	TASK NBR: FICHE NBR: NOTARIZED: LPDR: RECP AFFIL ORG AFFILI
		SUBJECT: "SNUPPS" INSPECTIONS	s .
50 484 C	04/20/78	DOCKET DATE: 04/21/78 REPORT NBR: RECP: SMITH I W KORNBLITH L	TASK NBR: FICHE NBR : NOTARIZED: LPDR: RECP AFFIL
		ANDERSON G C ORG: LEWIS S H	ORG AFFILI
) H	SUBJECT: RESPONSE TO THE BOAF BY 04/21/78 THEIR VI CONSIDERATION, &, IF CONSIDERING THE REMA	CEWS ON "WHETHE F SO, WHAT SCHE
50 484 C	04/21/78	ACCESSION NBR: 78121-0006 DOCUMENT TYPE: OTHERS DOCUMENT SIZE: 6P+2P DOCKET DATE: 04/24/78 REPORT NBR:	TASK NBR: FICHE NBR : NOTARIZED: LPDR:
•		RECP: ORG: CHARNOFF G BAXTER T A	RECP AFFIL ORG AFFILI
	,	SUBJECT: PERMITTEES' NEGATIVE WHETHER MATTERS REMA APPLICANT'S MN CORP. OF SVC.	ANDED TO ASLB C