

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

TO: J.P.O'REILLY

FROM: ROCHESTER GAS & ELEC. CORP. ROCHESTER, NY. L.D. WHITE, JR.

FILE NUMBER INCIDENT REPORT

DATE OF DOCUMENT 11-9-76

DATE RECEIVED 11-12-76

LETTER ORIGINAL COPY

NOTORIZED UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED 30

DESCRIPTION LTR. TRANS THE FOLLOWING... PLANT NAME: RE GINNA # 1

ENCLOSURE LICENSEE EVENT REPORT # 76-25, ON 10-10-76 CONCERNING LEAK AT WELDOLET TO NIPPLE WELD ON 3/4" VENT ON RHR RETURN LINE... ACKNOWLEDGED Do Not Remove NOTE: IF PERSONNEL EXPOSURE IS INVOLVED SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

SAB 11-12-76

Table with 4 columns: Action/Information items (BRANCH CHIEF, W/3 CYS FOR ACTION, LIC. ASST., W/1 CYS, ACRS 16 CYS) and corresponding names (SHCWENCER, SHEPPARD).

INTERNAL DISTRIBUTION

Table with 4 columns: Internal distribution list (REG FILE, NRC PDR, I & E (2), MIPC, SCHROEDER/IPPOLITO, HOUSTON, NOVAK/CHECK, GRIMES, CASE, BUNLER, HANAUER, TEDESCO/MACCARY, EISENHUT, PAER, SHAO, VOLLMER/FUNCH, KREGER/J. COLLINS).

EXTERNAL DISTRIBUTION

CONTROL NUMBER

Table with 4 columns: External distribution items (T/PDR: LYONS & ROCHESTER NY, TIC, NSIC).

Control number 11531 with handwritten mark.

1000

THE UNIVERSITY OF CHICAGO
LIBRARY

.....

()
()

.....

.....

.....

.....

.....

.....

.....

.....



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

November 9, 1976



Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 76-25 (30-day report), Leak at Residual Heat Removal System return pipe vent
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly:


In accordance with Technical Specifications, Article 6.9.2b, the attached report of Reportable Occurrence 76-25, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

L. D. White, Jr.
L. D. White, Jr.

Attachment

cc: Dr. Ernst Volgenau (30)
Mr. William G. McDonald (3)





LER 76-25/3L
LICENSEE EVENT REPORT

Regulatory Docket File

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

Received w/Ltr Dated: 11-9-76

LICENSEE NAME: 01 N Y R E G I LICENSE NUMBER: 00-000000-00 LICENSE TYPE: 41111 EVENT TYPE: 03

CATEGORY: 01 CONT 57 REPORT TYPE: L 59 REPORT SOURCE: L 60 DOCKET NUMBER: 050-0244 68 EVENT DATE: 101076 74 REPORT DATE: 110976 80

EVENT DESCRIPTION

02 | During operation of RHR system an operator noted small puddle on floor and discovered
03 | leak at weldolet to nipple weld on 3/4" vent on RHR return line. This is similar to
04 | Reportable Occurrence 74-5. Replaced nipple and rewelded using approved procedures.
05 | (Reportable Occurrence 76-25, 30-day).
06 |

SYSTEM CODE: CF CAUSE CODE: B COMPONENT CODE: PIPEXX PRIME COMPONENT SUPPLIER: N COMPONENT MANUFACTURER: K055 VIOLATION: N

CAUSE DESCRIPTION

08 | Stresses were induced due to improper fitup of nipple to socket during construction.
09 | Nipple appeared bottomed in socket. New nipple properly installed.
10 |

FACILITY STATUS: G % POWER: 000 OTHER STATUS: NA METHOD OF DISCOVERY: a DISCOVERY DESCRIPTION: By operator

FORM OF ACTIVITY RELEASED: Z CONTENT OF RELEASE: Z AMOUNT OF ACTIVITY: NA LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER: 000 TYPE: Z DESCRIPTION: NA

PERSONNEL INJURIES

NUMBER: 000 DESCRIPTION: NA

OFFSITE CONSEQUENCES

15 | NA

LOSS OR DAMAGE TO FACILITY

TYPE: Z DESCRIPTION: NA

PUBLICITY

17 | NA

ADDITIONAL FACTORS

18 | NA

19 |

NAME: Jack Noon PHONE: 716/546-2700, ext. 291-215

