

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: Bortolot Daybreak Corporation 50 Denison Drive Guilford, Connecticut 06437  REPORT NUMBER(S)                      2018-001		2. NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713	
3. DOCKET NUMBER(S) 030-12440		4. LICENSE NUMBER(S) 06-17253-01	
5. DATE(S) OF INSPECTION March 29, 2018, - July 9, 2018			

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.
2. Previous violation(s) closed.
3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):

4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

10 CFR 20.1101(c) requires, in part, that the licensee shall periodically (at least annually) review the radiation protection program content and implementation.




Contrary to the above, from June 11, 2013, through March 29, 2018, a period of greater than one year, the licensee failed to perform a review of the radiation protection program content and implementation.

This is a Severity Level IV violation (Enforcement Policy 6.3(d))

As a corrective action, the licensee will perform an annual audit within the next 30 days, and add a reminder to a tracking chart that the licensee uses for other aspects of their program.

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Victor Bortolot, PhD		7/9/2018
NRC INSPECTOR	Michael Reichard		7/9/18
BRANCH CHIEF	Arthur Burritt		8/1/18

SUNSI Review Completed By: / RA / Michael Reichard

Public     Non-Sensitive