

December 19, 1980 PM-80-1237

PLANT E. I. HATCH Special Report Docket # 50-321

10

10

Edwin J. Hatch Nuclear Plant

United States Nuclear Regulatory Commission Office of Inspection and Enforcement Region II Suite 3100 101 Marietta Street Atlanta, GA 30303

ATTENTION: Mr. James P. O'Reilly

Pursuant to section 6.9.2 of Hatch Unit 1 Technical Specifications, please find attached a Special Report.

Deepe M. Manry

Plant Manager

BEB/pebc

xc:	J.	Τ.	Beckham,	Jr.
			Widner	
	J.	R .	Jordan	
	D.	₩.	Howell	
	Ψ.	F .	Garner	
	J.	с.	Vance	
	Τ.	۷.	Greene	
	С.	Τ.	Moore	
			Coggin	
			Brown	
			L43	

Special Report Georgia Power Company Plant E. I. Hatch Docket #50-321 December 18, 1980

INOPERABLE SPRINKLER SYSTEM

On 12-13-80, at 2400 hours, the sprinkler system providing protection for the Unit 1 reactor building HVAC room had been inoperative for a period of 14 days. This system was isolated in order to implement design modifications that will bring the system into NFPA code compliance and will provide corrective action for NRC I&E open item 50-321/80-02-02.

Modification work and system functional test are expected to be complete by 1-1-81.