

50-237

NNNN"!!""NR



Regulatory

File Cy.

#  
R B

MSG NR 617

M  
USAEC HQS GTWN  
TLXA404 KA023

K VEB449 JQ PDBITDVE CHICAGO ILL 19 1240P CDT  
DONALD SKOVHOLT ASST DIR FOR OPERATING REACTORS DIRECTORATE  
OF LICENSING DLR DONT FONE

US ATOMIC ENERGY COMM WASHDC 20545  
THIS IS TO INFORM YOU THAT THE REPAIR OF THE DRESDEN UNIT 2  
MAIN STEAMLINES BY PINNING OF THE DOWN STREAM FLOW RESTRICTOR  
CONES HAVE BEEN COMPLETED. THE MODIFICATION HAS BEEN REVIEWED  
AND APPROVED BY THE COMMONWEALTH EDISON NUCLEAR REVIEW BOARD  
AND DRESDEN UNIT 2 IS EXPECTED TO BE RETURNED TO SERVICE LATE  
ON SEPTEMBER 19 1972R

L D BUTTERFIELD COMMONWEALTH EDISON CO

2 2 19 1972.(807)

113A EDT

USAEC HQS GTWN



5166

8103110060