Duke Power Company P.O. Box 33198

Charlotte, N.C. 28242

HAL B. Tucker Vice President Nuclear Production (704)373-4531



DUKE POWER

June 4, 1990

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Subject: McGuire Nuclear Station Decket Nos. 50-369, 370 Inspection Report Nos. 369, 370/89-01 Corrective Action Delay

Gentlemen:

In my letter of December 27, 1989, "Corrective Action Delay Violation 50-369, 370/89-01-07," I informed you that corrective actions involving a review of our Problem Investigation Program would be complete by June 1, 1990.

This review is complete and the Problem Investigation Process (PIR) Directive has been revised. However, we still have several departmental interface issues to resolve and training on the revised directive must be completed.

These corrective actions will be complete by September 1, 1990.

Should there be any questions concerning this matter, contact W. T. Byers at (704) 373-6194.

Very truly yours,

hac

Hal B. Tucker

WTB/200/1cs

Attachment

D

xc: Mr. S. D. Ebneter Regional Administrator, Region II U. S. Nuclear Regulatory Commission 101 Marietta St., NW, Suite 2900 Atlanta, Georgia 30323

Mr. Darl Hood U. S. Nuclear Regulatory Commission Office of Nuclear Reactor Regulation Washington, D.C. 20555 9006200505 900604 PDR ADOCK 05000369 PDC

Mr. P. K. VanDoorn NRC Resident Inspector McGuire Nuclear Station