

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

July 15, 1982

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

32 JUL 19 4 9:0
TENNESSEE VALLEY AUTHORITY
ATLANTA, GEORGIA

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/82040 - REVISION 0

The enclosed report is a supplement to my letter to you dated July 8, 1982,
concerning the failure of a drywell sump pump discharge flow control valve
to close. This report is submitted in accordance with Browns Ferry unit 1
Technical Specification 6.7.2.b(2).

We are reissuing this reportable occurrence because the supplemental information
sheet was inadvertently omitted.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

8207230353 820715
PDR ADOCK 05000259
S PDR

~~OFFICIAL COPY~~
TE 22