

**PHILADELPHIA ELECTRIC COMPANY**

**NUCLEAR GROUP HEADQUARTERS**

**955-65 CHESTERBROOK BLVD.**

**WAYNE, PA 19087-5691**

**(215) 640-6000**

August 9, 1990

Docket Nos. 50-352  
50-353

License Nos. NPF-39  
NPF-85

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

Subject: Limerick Generating Station, Units 1 and 2  
Emergency Plan Implementing Procedure Correction

Gentlemen:


This letter is being submitted to correct a deficiency in Emergency Plan Implementing Procedure EP-234, Revision 10, "Obtaining Containment Gas Samples From the Containment Leak Detector During Emergencies," for Limerick Generating Station, Units 1 and 2, that we identified on July 20, 1990. When this procedure revision was issued on April 3, 1989, page 9 of 10 (Appendix EP-234-1) should have included a figure. This figure was inadvertently omitted during the duplication process and the page remained blank. Therefore, attached is the applicable page correction including this figure. This procedure correction is being submitted within thirty (30) days from when this deficiency was identified in accordance with 10 CFR 50, Appendix E, and in accordance with 10 CFR 50.4.

If you have any questions, please do not hesitate to contact us.

9008130251 900809  
PDR ADDCK 05000352  
F PDC

*Aug 5 '90*

Sincerely yours,



G. A. Hunger, Jr.  
Manager  
Licensing Section  
Nuclear Engineering and Services

Attachment

cc: T. T. Martin, Administrator, Region I, USNRC (2 copies)  
T. J. Kenny, USNRC Senior Resident Inspector, LGS