September 5, 1990

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D.C. 20555

Subject:

LaSalle County Station Unit 2

Inservice Inspection Summary Report

NRC Decket No. 50-374

Dear Sir:

Attached please find a copy of the Commonwealth Edison Company LaSalle County Nuclear Power Station Unit 2 ISI Summary Report for the spring 1990 ASME Section XI Inservice Inspection. This is the second period of the first ten year plan and this was LaSalle's third refueling outage for Unit 2. LaSalle's mailing address is LaSalle County Station, P.O. Box 220, Rural Route 1, Marseilles, IL 61341. Unit 2 is owned and operated by Commonwealth Edison Co., whose address is One First National Plaza, P.O. Box 767, Chicago, Illinois 60690. Unit 2 has a Commercial Operating date of October 17, 1984, and has a gross generating capacity of 1122 MWE.

The Unit 2 reactor vessel was supplied by Chicago Bridge and Iron, Oak Brook, IL 60521. The reactor recirculation system components were supplied by General Electric, Co., San Jose, CA 95125. All other piping examined during the third refueling outage was supplied by B.F. Shaw, Wilmington, Delaware 19801. The residual heat removal system heat exchangers were supplied by Struthers Wells Corp., Warren, Pennsylvania 16365.

The inspections that were performed, the conditions that were obseived, and the corrective measures that were taken are contained in the attached report.

We certify that the staten ents made in this report are correct and that the examinations and corrective measures taken conform to the rules of the 1980 Edition of ASME Section XI, including the Winter 1980 Addenda.

00000

September 5, 15.30 U.S. NRC -2-If there are any questions or comments regarding this matter, please contact this office. Very truly yours, W.E. Morgan
Nuclear Licensir g Administrator Attachment A. Bert Davis - Regional Administrator, RIII T. Tongue - Senior Resident Inspector, LSCS CC: Imw/ID145