

July 2, 1982

DJS Ltr. #82-744

James G. Keppler, Regional Administrator
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #82-21/01T-0, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.l.(e), failure or malfunction of one or more components which prevents or could prevent, by itself, and the fulfillment of the functional requirements of system(s) used to cope with accidents analyzed in the SAR.

D. J. Scott

Station Superintendent Dresden Nuclear Power Station

DJS/nh

Enclosure

cc/ Director of Inspection & Enforcement
Director of Management Information & Program Control
U.S. NRC, Document Management Branch
File/NRC

8207130461 820702 PDR ADDCK 05000237 PDR JUL 6 1982 E 2