

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

December 28, 1982

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-32 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/81037 REVISION 2

The enclosed report is a supplement to my letters to you dated July 10, 1981
and August 11, 1981 concerning an indication which was observed on the vessel
side of the valve weld during ultrasonic inspection of the gate valve 69-1.
This report is submitted in accordance with Browns Ferry unit 1 Technical
Specification 6.7.2.A.9.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Green
H. J. Green
Director of Nuclear Power

Enclosure

cc (Enclosure):

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Browns Ferry

DEC 30 10 38 AM '82

GENERAL COPY

IE 22

8301040175 821228
PDR ADOCK 05000259
S PDR