



Tennessee Valley Authority, Post Office Box 2000, Decatur, Alabama 35809-2000

R. D. (Rick) Machon  
Vice President, Browns Ferry Nuclear Plant

July 28, 1995

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

10 CFR 50.73

Dear Sir:

**BROWNS FERRY NUCLEAR PLANT (BFN) - UNITS 1, 2, AND 3 - DOCKET  
NOS. 50-259, 50-260, AND 50-296 - FACILITY OPERATING LICENSE  
DPR-33, 52, AND 68 - LICENSEE EVENT REPORT 50-259/95001**

The enclosed report provides details concerning an inadvertent Engineered Safety Feature (ESF) actuation due to an auto start of an emergency equipment cooling water pump. This event occurred as a result of jumpering the wrong relay contacts during the performance of a surveillance instruction.

This report is submitted in accordance with 10 CFR 50.73 (a)(2)(iv) as an event or condition that resulted in an automatic actuation of any ESF.

Sincerely,

R. D. Machon  
Site Vice President

Enclosure  
cc: See page 2

010067

9508010020 950728  
PDR ADOCK 05000259  
S PDR

IE22  
111

U.S. Nuclear Regulatory Commission

Page 2

July 28, 1995

Enclosure

cc (Enclosure):

INPO Records Center  
700 Galleria Parkway  
Atlanta, Georgia 30339

Paul Krippner  
American Nuclear Insurers  
Town Center, Suite 300S  
29 South Main Street  
West Hartford, Connecticut 06107

NRC Resident Inspector  
Browns Ferry Nuclear Plant  
Route 12, Box 637  
Athens, Alabama 35611

Regional Administrator  
U.S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Mr. J. F. Williams, Project Manager  
U.S. Nuclear Regulatory Commission  
One White Flint, North  
11555 Rockville Pike  
Rockville, Maryland 20852