




KANSAS GAS AND ELECTRIC COMPANY

GLENN L KOESTER
VICE PRESIDENT - NUCLEAR

September 21, 1984

Mr. D.R. Hunter, Chief
Reactor Project Branch 2
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



KMLNRC 84-165
Re: Docket No. STN 50-482
Ref: Interim Report KMLNRC 83-104 from GLKoester, KG&E,
to WCSeidle, NRC
Subj: Final 10CFR50.55(e) Report - Sway Strut Washers

Dear Mr. Hunter:

This letter provides the final report submitted pursuant to 10CFR50.55(e) on installation of paddle washers on piping sway struts at Wolf Creek Generating Station. This concern was initially reported on July 15, 1983, with supplemental information provided in the Reference.

As documented in the Reference, several sway struts were identified as potentially having incorrect paddle washers installed or washers installed incorrectly. After reviewing this concern, it was determined that sufficient information may not have been provided to the crafts to assure proper installation. Therefore, Kansas Gas and Electric Company (KG&E) decided to have all of the sway struts in question inspected, and reworked if necessary, to assure that the correct washers were installed properly. This inspection effort, and any necessary rework, is being accomplished in lieu of performing a case-by-case engineering evaluation of the safety implications of any incorrect washer configuration.

Corrective Action Report 1-G-0033 documents the actions described above and provides a controlled mechanism to assure the actions are completed. The inspection and rework effort is currently 97% complete and will be 100% complete prior to fuel load.

Please contact me or Mr. Otto Maynard of my staff if you have any questions concerning this subject.

Yours very truly,

8410110254 840921
PDR ADOCK 05000482
S PDR

Glenn L Koester

GLK:bb
xc:RCDeYoung
PO'Connor
HBundy

1027
1/0