



**Northeast
Utilities System**

107 Selden Street, Berlin, CT 06037

Northeast Utilities Service Company
P.O. Box 270
Hartford, CT 06141-0270
(203) 665-5000

October 7, 1996

Docket No. 50-423
B15899

Re: 10CFR 50.73(a)(2)(v)(C)
10CFR 50.73(a)(2)(v)(C)

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


This letter forwards Licensee Event Report 96-032-00, documenting a condition that was determined at Millstone Unit No. 3 on September 9, 1996. This LER is submitted pursuant to 10CFR 50.73(a)(2)(v)(C) and 10CFR 50.73(a)(2)(v)(D).

The following are NNECO's commitments made within this letter:

- B15899-01: Perform the hydrostatic test of the SIH relief valves at the required test pressure. The retest will be performed during the current outage.
- B15899-02: Provide retraining and counseling to the individuals responsible for initially performing hydrostatic tests. Such retraining will encompass ASME code requirements and system design requirements.
- B15899-03: Maintained the Plant in Mode 5 or lower until such time as the hydrostatic testing of the SIH relief valves has been completed and the issues resolved.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY


M. H. Brothers
Unit Director, Millstone Unit No. 3

160009

Attachment: LER 96-032-00

9610160111 961007
PDR ADOCK 05000423
S PDR

IC22
1/1

cc: H. J. Miller, Region I Administrator
A. C. Cerne, Senior Resident Inspector, Millstone Unit No. 3
V. L. Rooney, NRC Project Manager, Millstone Unit No. 3