

Carolina Power & Light Company P.O. Box 10429 Southport, NC 28461-0429

OCT 1 4 1996

SERIAL: BSEP 96-0361

U. S. Nuclear Regulatory Commission ATTENTION: Mr. Stewart D. Ebneter, Regional Administrator 101 Marietta Street, N.W., Suite 2900 Atlanta, GA 30323-0199

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 AND 2
DOCKET NOS. 50-325 AND 50-324/LICENSE NOS. DPR-71 AND DPR-62
NRC INSPECTION REPORT NOS. 50-324/96-04 AND 50-325/96-04
UNIT 2 MOISTURE SEPARATOR REHEATER MANWA: VELDS

Mr. Ebneter:

In Inspection Report Nos. 50-324/96-04 and 50-325/96-04, the U.S. Nuclear Regulatory Commission (NRC) documented inspection activities pertaining to the Brunswick Steam Electric Plant, Units 1 and 2. Section 4.1 in this report discussed replacement of the "B" low pressure turbine rotor and included a statement that all welders who performed work on the turbine during this outage were appropriately trained and certified to weld and perform work to the appropriate procedures. Carolina Power & Light Company would like to clarify this statement by noting that all welders who were involved with this work, with the exception of the one non-certified welder discussed in our August 15, 1996 letter, were appropriately trained and certified to weld and perform work to the appropriate procedures.

Please refer any questions regarding this submittal to Mr. Mark A. Turkal at (910) 457-3066.

Sincerely,

William Levis

Director - Site Operations

Brunswick Nuclear Plant

WRM/wrm

IEOI/0

9610240108 961014 PDR ADDCK 05000324 Q PDR Document Control Desk BSEP 96-0361 / Page 2

cc: U. S. Nuclear Regulatory Commission ATTN.: Document Control Desk Washington, D.C. 20555

> Mr. C. A. Patterson NRC Senior Resident Inspector - Brunswick Units 1 and 2:

U.S. Nuclear Regulatory Commission ATTN.: Mr. David C. Trimbie, Jr. (Mail Stop OWFN 14H22) 11555 Rockville Pike Rockville, MD 20852-2738

The Honorable H. Wells Chairman - North Carolina Utilities Commission P.O. Box 29510 Raleigh, NC 27626-0510