SAFEGUARDS INFORMATION



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30323

OCT 03 1985

Report No. 50-302/85-35

Licensee: Florida Power Corporation

3201 34th Street South St. Petersburg, FL 33733

Docket No. 50-302

License No. DPR-72

Facility Name: Crystal River 3

Inspection Dates: August 11-15, 1985 and August 22-23, 1985

Inspectors:

A. Tillman, Physical Security Inspector

O. M. Masnyk, Physical Security Inspector

Approved by:

D. R. McGuire, Chief, Physical Security Section Nuclear Materials Safety and Safeguards Branch Division of Radiation Safety and Safeguards 9-30-85 Date Signed

Date Signed

Date Signed

Date Signed

SUMMARY

Scope: The initial unannounced physical security inspection and subsequent special inspection involved 70 inspector-hours (five on back shift) inspecting: Physical Security Plan and Implementing Procedures; Management Effectiveness - Security Program; Security Organization; Records and Reports; Testing and Maintenance; Locks, Keys and Combinations; Physical Barriers - Protected Area; Physical Barriers - Vital Areas; Security System Power Supply; Compensatory Measures; Assessment Aids; Access Control-Personnel; Access Control-Packages; Access Control-Vehicles; Detection Aids - Protected Area; Detection Aids-Vital Areas; Alarm Stations; Communications; and Personnel Training and Qualifications General Requirements.

In addition to inspection of the above listed areas, a special inspection was conducted on August 22-23, 1985, to review and determine the circumstances of a licensee identified and reported incident relating to alleged unauthorized introduction of firearms into the protected area.

Results: The licensee was found to be in compliance with regulatory requirements in the areas inspected with the exception of the following:

- 1. Failure to provide positive access control to the protected area.
- Failure to maintain two-way radio communication capability with the local law enforcement agency.

8510220229 851003 PDR ADOCK 05000302

ON UPON SEPARATION THIS PAGE IS DECONDROLLED.