

NOTICE OF VIOLATION

Florida Power Corporation  
Crystal River Unit 3

Docket No. 50-302  
License No. DPR-72

During NRC inspections conducted on July 14 through August 10, 1996, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," (60 FR 34381: June 30, 1995/NUREG 1600), the violation is listed below:

10 CFR 50, Appendix B, Criterion XVI, Corrective Action, requires that measures be established to assure that conditions adverse to quality, such as failures, malfunctions, deficiencies, deviations, defective material and equipment, and nonconformances are promptly identified and corrected.

1. Contrary to the above, as of July 1996, the licensee had failed to take prompt corrective actions to address discrepancies identified in February 1995 during a make-up system audit.
2. Contrary to the above, on July 12, 1996, the licensee failed to initiate prompt corrective actions to address the identification of an increasing trend in excessive vibration on the spent fuel pump cooling fan motor, which was originally identified in 1994.

This is a Severity Level IV Violation (Supplement 1).

Pursuant to the provisions of 10 CFR 2.201, Florida Power Corporation is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555, with a copy to the Regional Administrator, Region II, and a copy to the NRC Resident Inspector, at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. If an adequate reply is not received within the time specified in this Notice, an order or demand for information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Dated at Atlanta, Georgia  
this 12 day of Sept 1996

Enclosure 1

9609270049 960912  
PDR ADOCK 05000302  
G PDR