

## UNITED STATES

## NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011 8064

MAR 7 1997

EA 97-099

Charles M. Dugger, Vice President Operations - Waterford Entergy Operations, Inc. P.O. Box B Killona, Louisiana 70066

SUBJECT: NRC INSPECTION REPORT 50-382/97-03

Dear Mr. Dugger:

An NRC inspection was conducted February 3-28, 1997, at your Waterford Steam Electric Station, Unit 3 reactor facility. The enclosed report presents the scope and results of that inspection.

Based on the results of this inspection, four apparent violations were identified and are being considered for escalated enforcement action in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions" (Enforcement Policy), NUREG-1600. The apparent violations discussed in the enclosed report include the failure to: (1) maintain adequate design control for the containment cooling system, (2) establish an adequate test procedure to implement Technical Specification 4.6.2.2.b.2, (3) comply with the Technical Specification 3.6.2.2 requirement to maintain at least one operable containment fan cooler per train, and (4) implement adequate corrective actions following identification that the containment fan coolers could not meet their design basis requirements. Accordingly, no Notice of Violation is presently being issued for these inspection findings. In addition, please be advised that the number and characterization of apparent violations described in the enclosed inspection report may change as a result of further NRC review.

A predecisional enforcement conference to discuss these apparent violations has been scheduled for 1 p.m. (CDT) on April 8, 1997. The decision to hold a predecisional enforcement conference does not mean that the NRC has determined that a violation has occurred or that enforcement action will be taken. This conference is being held to obtain information to enable the NRC to make an enforcement decision, such as a common understanding of the facts, root causes, missed opportunities to identify the apparent violation sooner, corrective actions, significance of the issues and the need for lasting and effective corrective action. In addition, this is an opportunity for you to point out any errors in our inspection report and for you to provide any information concerning your perspectives on: (1) the severity of the violations, (2) the application of the factors that the NRC considers when it determines the amount of a civil penalty that may be assessed in accordance with Section VI.B.2 of the Enforcement Policy, and (3) any other application

9703130113 970307 PDR ADOCK 05000382 Q PDR

mbanbinanan

of the Enforcement Policy to this case, including the exercise of discretion in accordance with Section VII.

You will be advised by separate correspondence of the results of our deliberations on this matter. No response regarding these apparent violations is required at this time.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Arthur T. Howell III, Acting Director

Division of Reactor Projects

Docket No.: 50-382 License No.: NPF-38

Enclosure: NRC Inspection Report

50-382/97-03

cc w/enclosure:

Executive Vice President and Chief Operating Officer Entergy Operations, Inc. P.O. Box 31995 Jackson, Mississippi 39286-1995

Vice President, Operations Support Entergy Operations, Inc. P.O. Box 31995 Jackson, Mississippi 39286-1995

Wise, Carter, Child & Caraway P.O. Box 651 Jackson, Mississippi 39205 General Manager, Plant Operations Waterford 3 SES Entergy Operations, Inc. P.O. Box B Killona, Louisiana 70066

Manager - Licensing Manager Waterford 3 SES Entergy Operations, Inc. P.O. Box B Killona, Louisiana 70066

Chairman Louisiana Public Service Commission One American Place, Suite 1630 Baton Rouge, Louisiana 70825-1697

Director Nuclear Safety & Regulatory Affairs Waterford 3 SES Entergy Operations, Inc. P.O. Box B Killona, Louisiana 70066

William H. Spell, Administrator Louisiana Radiation Protection Division P.O. Box 82135 Baton Rouge, Louisiana 70884-2135

Parish President St. Charles Parish P.O. Box 302 Hahnville, Louisiana 70057

Mr. William A. Cross
Bethesda Licensing Office
3 Metro Center
Suite 610
Bethesda, Maryland 20814

Winston & Strawn 1400 L Street, N.W. Washington, D.C. 20005-3502 E-Mail report to T. Boyce (THB)

E-Mail report to NRR Event Tracking System (IPAS)

E-Mail report to Document Control Desk (DOCDESK)

E-Mail report to Richard Correia (RPC)

E-Mail report to Don Taylor (DRT)

bcc to DCD (IEO1)

bcc distrib. by RIV:

Regional Administrator

**DRP** Director

Branch Chief (DRP/D)

Project Engineer (DRP/D)

Branch Chief (DRP/TSS)

G. F. Sanborn, EO

W. L. Brown, RC

J. Lieberman, OE (MS: 7-H5)

OE: EA File, (MS: 7-H5)

Resident Inspector

DRS-PSB

MIS System

RiV File

Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME: R:\\_WAT\WT702RP,CAK

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

SRI MANGE	C:DRP/PA	AD:DRR	
LAKetter total	PHHarrel	ATHowell	The state of the s
03/ 407	03/15/3/1	03/ / /97	03/ /97
V	OFF	ICIAL RECORD COPY	

E-Mail report to T. Boyce (THB)

E-Mail report to NRR Event Tracking System (IPAS)

E-Mail report to Document Control Desk (DOCDESK)

E-Mail report to Richard Correia (RPC)

E-Mail report to Don Taylor (DRT)

bcc to DCD (IEO1)

bcc distrib. by RIV:

Regional Administrator

**DRP** Director

Branch Chief (DRP/D)

Project Engineer (DRP/D)

Branch Chief (DRP/TSS)

G. F. Sanborn, EO

W. L. Brown, RC

J. Lieberman, OE (MS: 7-H5)

OE: EA File, (MS: 7-H5)

Resident Inspector

DRS-PSB

MIS System

RIV File

Leah Tremper (OC/LFDCB, MS: TWFN 9E10)