

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

August 20, 1985

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Attention: Ms. E. G. Adensam, Chief
Licensing Branch No. 4

Subject: McGuire Nuclear Station
Docket Nos. 50-369 and 50-370
Commitment to Reroute Instrument Lines

Dear Mr. Denton:

In Licensee Event Report 369/85-03 dated February 20, 1985, Duke Power Company committed to reroute instrument impulse lines and to heat trace and insulate by next winter (December, 1985). Due to design and material lead times, and that the implementation of these modifications during an outage is preferred, the modifications will be delayed until an outage in 1986.

Very truly yours,



Hal B. Tucker

JBD/hrp

cc: Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Mr. W. T. Orders
Senior Resident Inspector
McGuire Nuclear Station

8508230158 850820
PDR ADOCK 05000369
S PDR

Pool
1/0