Docket No. 50-346

Mr. Joe Williams, Jr.
Senior Vice President, Nuclear
Toledo Edison Company
Edison Plaza - Stop 712
300 Madison Avenue
Toledo, Ohio 43652

DISTRIBUTION

Docket File

NRC PDR

L PDR

ORB#4 Rdg

HThompson

OELD

EJordan

BGrimes

JPartlow

JRidgely ACRS-10 RIngram ADEAgazio GDick EBrach HOrnstein WPaulson GEdison OParr

Dear Mr. Williams:

SUBJECT: DAVIS BESSE ROOT CAUSE FINDING REPORT PLAN 1D

On October 30, 1985 we provided Toledo Edison Company with our evaluation of your report related to AFPT overspeed trip throttle valve problems, Plan 1D. The revision of the report which we reviewed indicated that it was Toledo Edison Company's intent to replace the trip spring for the trip and throttle valve on both AFPTs prior to restart of Davis Besse. This recommendation had previously been provided to you in a letter from Terry Turbine on February 3, 1984.

In Revision 3 to Plan 1D, submitted on October 31, 1985 (Serial No. 1202), this commitment has been deleted. It is our position that these springs should be replaced as per manufacturer's recommendations prior to restart; otherwise an acceptable justification should be provided. The report on Plan 1D should be revised to reflect restoration of the commitment or the requested justification for our review. Please provide your revision no later than November 30, 1985.

Sincerely,

ORIGINAL SIGNED BY JOHN F. STOLE

John F. Stolz, Chief Operating Reactors Branch #4 Division of Licensing

cc: See next page

ORB#4:DL ORB#4:DL Jol ADeAgazio; cr JStolz 11/5/85 11/5/85

Mr. J. Williams Toledo Edison Company

cc:
Donald H. Hauser, Esq.
The Cleveland Electric
Illuminating Company
P. O. Box 5000
Cleveland, Ohio 44101

Mr. Robert F. Peters Manager, Nuclear Licensing Toledo Edison Company Edison Plaza 300 Madison Avenue Toledo, Ohio 43652

Gerald Charnoff, Esq. Shaw, Pittman, Potts and Trowbridge 1800 M Street, N.W. Washington, D.C. 20036

Paul M. Smart, Esq. Fuller & Henry 300 Madison Avenue P. O. Box 2088 Toledo, Ohio 43603

Mr. Robert B. Borsum
Babcock & Wilcox
Nuclear Power Generation
Division
Suite 200, 7910 Woodmont Avenue
Bethesda, Maryland 20814

Resident Inspector
U.S. Nuclear Regulatory Commission
5503 N. State Route 2
Oak Harbor, Ohio 43449

Regional Administrator, Region JJJ U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Jllinois 60137 Davis-Besse Nuclear Power Station Unit No. 1

Ohio Department of Health ATTN: Radiological Health Program Director P. O. Box 118 Columbus, Ohio 43216

Attorney General
Department of Attorney
General
30 East Broad Street
Columbus, Ohio 43215

Mr. James W. Harris, Director Division of Power Generation Ohio Department of Industrial Relations 2323 West 5th Avenue P. O. Box 825 Columbus, Ohio 43216

Mr. Harold Kohn, Staff Scientist Power Siting Commission 361 East Broad Street Columbus, Ohio 43216

President, Board of Ottawa County Port Clinton, Ohio 43452