

Tennessee Valley Authority, Post Office Box 2000, Soddy-Daisy, Tennessee 37379-2000

R.J. Adney
Site Vice President
Sequoyah Nuclear Plant

March 28, 1997

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555


Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT (SQN)
UNIT 2 - DOCKET NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 -
LICENSEE EVENT REPORT (LER) 50-328/96004, REVISION 1

The enclosed LER revision provides details concerning the replacement of reactor trip breaker "B". After the replacement breaker was removed from service, it was found to have a problem with the linkage for the auxiliary contacts. This caused two of the three relays of the auxiliary contacts to be inoperable. This resulted in a failure to comply with the technical specification (TS) requirements pertaining to the auxiliary contacts for reactor trip breaker "B". When the original report was submitted, the root cause had not been established. The root cause has now been established and the results are being transmitted in this revision to the original report. This revision supersedes the original report. In addition, investigation revealed on February 3, 1997, that the redundant reactor trip breaker "A" had missed one portion of its required surveillance and was not technically operable in accordance with TSs during the time breaker "B" was not operable. This condition was not related to the linkage problems which existed on breaker "B". Subsequent testing has proven the "A" breaker was fully functional. This information was not available during the December 16, 1996, enforcement conference, but was provided to the Region II staff on February 3 and 4, 1997, and to the acting regional administrator, Jon Johnson, on February 5, 1997.

The event was originally reported on October 23, 1996, in accordance with 10 CFR 50.73(a)(2)(i)(B) as an operation prohibited by the plant TSs.

Sincerely,



R. J. Adney

Enclosure (See page 2)

IE 22 1/2

9704160078 970328
PDR ADOCK 05000328
S PDR



U.S. Nuclear Regulatory Commission

Page 2

March 28, 1997

Enclosure

cc (Enclosure):

Mr. R. W. Hernan, Project Manager
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852-2739

INPO Records Center
Institute of Nuclear Power Operations
700 Galleria Parkway
Atlanta, Georgia 30339-5957

NRC Resident Inspector
Sequoyah Nuclear Plant
2600 Igou Ferry Road
Soddy-Daisy, Tennessee 37379-3624

Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323-2711