

**Northeast
Nuclear Energy**

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station
Northeast Nuclear Energy Company
P.O. Box 128
Waterford, CT 06385-0128
(860) 447-1791
Fax (860) 444-4277

The Northeast Utilities System

May 2, 1997
Docket No. 50-336
B16372

Re: 10 CFR 50.73(a)(2)(ii)
10 CFR 50.73(a)(2)(v)
10 CFR 50.73(a)(2)(vii)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

This letter forwards Licensee Event Report (LER) 97-011-00, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on April 2, 1997. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(ii), 10 CFR 50.73(a)(2)(v) and 10 CFR 50.73(a)(2)(vii).

The following are NNECO's commitments made within this letter.

B16372-01: Appropriate procedures shall be revised prior to entry into Mode 4 from the current outage to ensure that proper valve control parameters (benchset, air regulator, and stroke length) are specified and verified after any maintenance activities are performed that could affect dual function valve closing forces.

IED 2/1


9705080296 970502
PDR ADOCK 05000336
S PDR
U O O O O O



B16372-02: The affected valves will be adjusted to ensure they properly close against containment design pressure and NOSP, and they will be tested to ensure Appendix J, Type C leakage rate testing criteria are met. These activities will be performed prior to entry into Mode 4 from the current outage.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY



J. A. Price
Director - Millstone Unit No. 2

Attachment: LER 97-011-00

cc: W. D. Travers, Director of Special Projects
H. J. Miller, Region I Administrator
D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2
D. G. McDonald, Jr., NRC Senior Project Manager, Millstone Unit No. 2