

NOV 6 1985

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Joe Williams, Jr.
Senior Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the special safety inspection conducted by Mr. I. T. Yin of this office on October 8 through 24, 1985, of activities at Davis-Besse Nuclear Power Station, Unit 1, authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. S. M. Quennoz at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosures will be placed in the NRC's Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by J. J. Harrison

J. J. Harrison, Chief
Engineering Branch

Enclosure: Inspection Report
No. 50-346/85033(DRS)

See Attached Distribution

8511180573 851106
PDR ADOCK 05000346
G PDR

11
DE01

Distribution

cc w/enclosure:

- L. Storz, Plant Manager
- DCS/RSB (RIDS)
- Licensing Fee Management Branch
- Resident Inspector, RIII
- Harold W. Kohn, Ohio EPA
- James W. Harris, State of Ohio
- Robert H. Quillin, Ohio
Department of Health

RIII
JWA
 Yin/kja
 11/05/85

RIII
JWA
 Danielson
 11/6

(JWA)
 RIII
JWA
 Jackie
 11/7

RIII
JWA
 Harrison
 11/6