April 30, 1997

Mr. M. Wadley, Vice President Nuclear Generation Northern States Power Company 414 Nicollet Mall Minneapolis, MN 55401

SUBJECT:

NRC SPECIAL INSPECTION REPORT NO. 50-306/97006 AND

NOTICE OF VIOLATION

Dear Mr. Wadley:

On March 17, 1997, the NRC completed a special inspection at your Prairie Island Nuclear Generating Plant. The enclosed report presents the results of that inspection.

The purpose of this inspection was to review the circumstances of a Unit 2 shutdown operations event on the night of March 6-7, 1997, involving a planned drain of coolant from the reactor coolant system. Due to a non-licensed operator's valve tagging error, the drain was conducted without the system vented. Without an adequate vent path, the instrumentation that control room operators used to monitor the drain was not representative of the amount of inventory drained from the system. Consequently, more coolant than intended was drained from the system and a gas void developed in the high points of the reactor coolant system.

Although there was no adverse impact on decay heat removal capability, this event represents a loss of control of a plant evolution. We identified weaknesses in the procedures used for the evolution, your evaluation of the impact of a change in plant configuration to establish a vent path, plant configuration control, and interpretation of available data by control room operators during the evolution.

Based on the results of this inspection, the NRC has determined that two violations of NRC requirements occurred. The violations are cited in the enclosed Notice of Violation (Notice) and the circumstances surrounding them are described in detail in the subject inspection report.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. The NRC will use your response, in part, to determine whether further enforcement action is necessary to ensure compliance with regulatory requirements.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room (PDR).

Sincerely,

/s/ J. L. Caldwell

J. L. Caldwell, Director Division of Reactor Projects

Docket No.: 50-306 License No.: DPR-60

Enclosures: Notice of Violation

Inspection Report 50-306/97006

cc w/encl: Plant Manager, Prairie Island

John W. Ferman, Ph.D., Nuclear Engineer, MPCA State Liaison Officer, State

of Minnesota

State Liaison Officer, State

of Wisconsin Tribal Council

Prairie Island Dakota Community

Distribution:

Docket File w/encl
PUBLIC IE-01 w/encl
OC/LFDCB w/encl
SRI Prairie Island w/encl
Monticello w/encl
RIII Enf. Coordinator, w/enc

RIII Enf. Coordinator, w/encl Deputy RA, w/encl DRP w/encl

Prairie Island PM, NRR w/encl

CAA1 w/encl (E-mail)
A. B. Beach, w/encl
DRS (2) w/encl
TSS w/encl

DOCUMENT NAME: R:\INSPRPTS\POWERS\PRAI\PRA97006.DRP

To receive a copy of this document, indicate in the box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	Filli	N	Pull N	RIII N	RHI OOA
NAME	Schweibinz/go		MONEY MEB for	Jacobson W/	Caldwall
DATE	41 9 197		41 4 197	4/ 197	4/1/197