

DMB

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

86 JAN 3 P 1: 24

TELEPHONE
(704) 373-4531

SECURITY RELATED
NOT CLASSIFIED

December 18, 1985

Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
P. O. Box 2203
Atlanta, Georgia 30301

Subject: Oconee Nuclear Station
IE Inspection Report
50-269/85-05
50-270/85-05
50-287/85-05
Supplemental Response to the
Duke Response of April 26, 1985


Dear Dr. Grace:

During the week of December 9, 1985, NRC/Region II Inspector O. M. Masnyk conducted a routine security inspection of Oconee Nuclear Station. In the process of the inspection Ms. Masnyk reviewed the Duke response to violation 50-269, -270, -287/85-05-01 (jump test) and questioned the physical description of site perimeter intrusion detection units. Based on conversation between your staff and my staff it was determined that some of the technical information approximated in our April 26, 1985 response was in error. During the December 16-17, 1985 period of time this was corrected by a comprehensive review of the physical layout of the perimeter alarm system by station personnel to confirm barrier and detector configuration. The corrected information is available at the station for your inspection.

Duke recognizes the need to resolve and close this violation as expeditiously as possible. The options will be evaluated to determine the corrective steps we intend to take and you shall be informed of these corrective steps in a supplemental response to be provided within the first quarter/1986.

If there are any questions or problems concerning this matter, please advise.

Very truly yours,



Hal B. Tucker

JWD:slb

8601080225 851218
PDR ADOCK 05000269
Q PDR

1/0 IE01

Dr. J. Nelson Grace, Regional Administrator
December 18, 1985
Page Two

cc: Mr. J. C. Bryant
NRC Resident Inspector
Oconee Nuclear Station

SECURITY RELATED
NOT CLASSIFIED

