May 3, 1999

Mr. Oliver D. Kingsley President, Nuclear Generation Group Commonwealth Edison Company ATTN: Regulatory Services Executive Towers West III 1400 Opus Place, Suite 500 Downers Grove, IL 60515

SUBJECT: NRC RADIATION PROTECTION INSPECTION REPORT 50-373/99009(DRS); 50-374/99002(DRS)

Dear Mr. Kingsley:

On April 9, 1999, the NRC completed a routine inspection at the LaSalle Nuclear Generating Station, Units 1 and 2. The enclosed report summarizes the results of this inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. Specifically, the inspection focused on the actions recently taken to identify common causes for previously identified programmatic problems with radiation worker and radiation protection staff performance at the LaSalle Station, and to correct these weaknesses. Within these areas, the inspection consisted of selective examinations of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified. Your staff completed in-depth assessments of the radiation protection (RP) program, identified several common causes for previously documented problems with human performance during radiological work, and a comprehensive improvement strategy was developed to address these recent findings and those previously made by the NRC. Your staff was generally effective in implementing and monitoring the initial phases of the improvement strategy and overall positive steps were taken toward achieving the station's goal to provide superior radiological services.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room. O. Kingsley

.*

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original /s/ G. E. Grant

Geoffrey E. Grant, Director Division of Reactor Projects

Docket Nos. 50-373; 50-374 License Nos. NPF-11; NPF-18

Enclosure: Inspection Report 50-373/99009(DRS); 50-374/99009(DRS)

cc w/encl:

D. Helwig, Senior Vice President

H. Stanley, PWR Vice President

C. Crane, BWR Vice President

R. Krich, Vice President, Regulatory Services DCD - Licensing

J. Benjamin, Site Vice President

T. O'Connor, Station Manager

R. Brady, Jr., Regulatory Assurance Supervisor

M. Aguilar, Assistant Attorney General

State Liaison Officer

Chairman, Illinois Commerce Commission

DOCUMENT NAME: G:DRS\LAS99009.WPD

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RIII	E.	RIII	E	RIII	N	RIII	
NAME	WSlawinski:tb Auc		GShear 615		MLeach Har		GGrant	
DATE	04/27/99		04/11/99		04/30/99		05/2/9900	

OFFICIAL RECORD COPY

O. Kingsley

.1

Distribution: SAR (E-Mail) RPC (E-Mail) Project Mgr., NRR w/encl J. Caldwell, RIII w/encl B. Clayton, RIII w/encl SRI LaSalle w/encl DRP w/encl DRS w/encl RIII PRR w/encl PUBLIC IE-01 w/encl Docket File w/encl GREENS IEO (E-Mail) DOCDESK (E-Mail)

Jeo6

11,