

Commonwealth Edison Company  
Braidwood Generating Station  
Route #1, Box 84  
Braceville, IL 60407-9619  
Tel 815-458-2801

**ComEd**

March 8, 1999

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555 - 0001

Braidwood Station, Unit 1  
Facility Operating License Nos. NPF-72  
NRC Docket No. STN 50-456


Subject: Braidwood Station, Unit 1 Inservice Inspection Summary Report

Reference: G. K. Schwartz (Commonwealth Edison Company) to J. E. Dyer,  
Regional Administrator, US Nuclear Regulatory Commission, Region  
III, letter dated February 11, 1999, "Braidwood Station, Unit 1  
Inservice Inspection Summary Report."

Enclosed is the Post-Outage (90 day) for Inservice Inspection examinations  
conducted during the seventh refueling outage of Braidwood Station Unit 1 (i.e.,  
A1R07). This report has been submitted to the NRC Region III office by the  
reference transmittal in accordance with the requirements of ASME Section XI,  
Article IWA-6200. However, to ensure consistency with the requirements of 10 CFR  
50.4 it is being submitted, by this separate transmittal, to the Document Control  
Desk.

Please direct any questions you may have regarding this submittal to Mr. Terry  
Simpkin, Regulatory Assurance Manager, at (815) 458-2801, x2980.

Respectfully,



G. K. Schwartz  
Station Manager - Braidwood Station

NRC/99013gks.doc

Enclosure: Braidwood Station ISI Outage Report for A1R07

cc: Regional Administrator - NRC Region III (w/o enclosure)  
NRC Senior Resident Inspector - Braidwood Station (w/o enclosure)

9903160277 990308  
PDR ADOCK 05000456  
G PDR